

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 511B**AAD1911-207***Not Authored**Presony B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

27 NOV 2019

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 511B

VF1ABL15AUC283480

RENAULT

LATITUDE

25.11.19

AIG

10/7/2017

PART**LIST**

1	1	BUMPER COVER REAR	\$	CM/Bu	561.70	✓
2	1	BUMPER LOWER REAR	\$	Bu	411.90	✓
3	1	BUMPER BRACKET CTR REAR	\$	SL	98.10	X
4	1	BUMPER BRACKET SIDE RH REAR	\$	SL	82.10	X
5	1	BUMPER RETAINER RH REAR	\$	SL	59.80	X
6	1	BUMPER REFLECTOR RH	\$	Bu	16.60	✓
7	1	BUMPER BRACKET SIDE LH REAR	\$	SL	80.80	X
8	1	BUMPER RETAINER LH REAR	\$	SL	54.20	X
9	1	BUMPER REFLECTOR LH	\$	SL	16.60	X
10	1	BUMPER BEAM REAR	\$	Bu	547.80	✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	SL	114.50	X
12	1	BUMPER BEAM BRACKET RH REAR	\$	SL	100.90	X
13	1	OUTER PANEL REAR (End Panel)	\$	Bu	745.80	✓
14	1	OUTER PANEL REAR (End Panel) TRIM	\$	CM	404.56	✓
15	1	TAILLAMP RH	\$	SL	313.10	X
16	1	TAILLAMP PANEL RH	\$	SL	401.40	X
17	1	TAILLAMP LH	\$	SL	401.40	X
18	1	TAILLAMP PANEL LH	\$	SL	401.40	X
19	1	BOOT REAR	\$	Bu	1,677.20	✓
20	1	BOOT FINISHER	\$	SL	344.70	X
21	1	BOOT WHEATERSTRIP	\$	SL	178.20	X
22	1	BOOT REFLECTOR LAMP LH	\$	SL	277.70	X
23	1	BOOT REFLECTOR LAMP RH	\$	SL	277.70	X
24	1	BOOT BADGE 'RENAULT'	\$	SL	82.40	✓
25	1	BOOT BADGE	\$	SL	95.80	✓
26	1	BOOT STRUT LH	\$	SL	145.10	X
27	1	BOOT STRUT RH	\$	SL	145.10	X
28	1	BOOT HINGE LH	\$	SL	254.20	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD1911-207**SHD 511B**

29	1	BOOT HINGE RH	\$	R	253.80	}	X	
30	2	BOOT RUBBER PLUG	\$	Sh	139.90			
31	2	BOOT BUFFER	\$	Sh	26.80			
32	1	BOOT LOCK LINKAGE	\$	Sh	20.60			
33	1	BOOT LOCK LINKAGE HOLDER	\$	Sh	99.50			
34	1	BOOT INNER TRIM BOARD	\$	Sh	611.00			
35	1	BOOT SWITCH	\$	Sh	113.00			
36	1	BOOT LOCK	\$	R	246.60			
37	1	BOOT LOCK CATCH	\$	R	41.70			
38	1	EXHAUST REAR	\$	R	5,263.60	}		
39	1	EXHAUST CAP REAR	\$	R	125.40			
TOTAL			\$		15,232.66			
10%			\$		1,523.27			
			\$		13,709.39			

Special Nett

Special Note			
1	1SET	PARKING AID	\$ 700.00 X
2	1SET	REAR BUMPER CLIP	\$ 66.00 —
3	1SET	BUMPER BRACKET CTR CLIP	\$ 33.00 —
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$ 10.00 X
5	1SET	BUMPER RETAINER RH CLIP RR	\$ 20.00 X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$ 10.00 X
7	1SET	BUMPER RETAINER CLIP LH RR	\$ 20.00 X
8	1SET	BUMPER LOWER REAR RIVET	\$ 22.00 X
9	1SET	BUMPER LOWER REAR CLIP	\$ 66.00 ✓
10	1	BOOT STICKER "Trans-cab"	\$ 30.00 —
11	1	BOOT STICKER "6555-3333"	\$ 30.00 —
12	2	REAR WINDSCREEN SEALANT	\$ 80.00
13	1	WINDSCREEN MOULDING	\$ 100.00
14	1	REAR WINDSCREEN INNER SPONGE SEAL	\$ 100.00
15	1	BOOT INNER TRIM CLIP	\$ 45.00
16	1SET	BOOT FINISHER CLIP	\$ 24.20
17	1	TAILLAMP CLIP LH	\$ 5.00
18	1	TAILLAMP CLIP RH	\$ 5.00
19	1	Rear Bumper Protector	\$ 100.00 4050

Trans-cab Auto Services Pte Ltd**AAD1911-207**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 511B

20	1	EXHAUST MOUNTING REAR	\$	Sh	16.00	X
21	1	EXHAUST BRACKET REAR	\$	Sh	24.80	X
TOTAL			\$		1,507.00	
TOTAL PARTS			\$		15,216.39	

LABOUR

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	601
To Rust-Proofing Of The Affected Areas.	\$	170.00	601
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	6001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	↪ 170.00	X
To check steering geometry and computer wheel alignment	\$	↪ 220.00	X
To repair and realign rear exhaust pipe.	\$	↪ 170.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	↪ 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1911-207**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 511B

Labour charge to mount and dismount vehicle on jig
bench, to facilitate repair.

\$ *nn* 380.00 X

Putty and spray painting of the affected portion.

\$ 6,000.00 *6601*

To drop rear exhaust box, renew the same, to repair
and realign centre exhaust pipe.

\$ *nn* 170.00 X**TOTAL** \$ **14,680.00****Over All Total** \$ **29,896.39****PART BY PART (REPAIR DAY)**~~20~~ DAYS*5 days***LKK Auto Consultants** hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: