

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 511B****AAD1911-207***Not Authorized**Resonny B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

27 NOV 2019

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

**SHD 511B**

VF1ABL15AUC283480

RENAULT

LATITUDE

25.11.19

**AIG**

10/7/2017

**P/P = \$5,874.38  
5 REPAIR DAYS**

		<b>PART</b>	<b>LIST</b>	
1	1	BUMPER COVER REAR	\$ CM/Bu	561.70 ✓
2	1	BUMPER LOWER REAR	\$ Bu	411.90 ✓
3	1	BUMPER BRACKET CTR REAR	\$ SL	98.10 X
4	1	BUMPER BRACKET SIDE RH REAR	\$ SL	82.10 X
5	1	BUMPER RETAINER RH REAR	\$ SL	59.80 X
6	1	BUMPER REFLECTOR RH	\$ Bu	16.60 ✓
7	1	BUMPER BRACKET SIDE LH REAR	\$ SL	80.80 X
8	1	BUMPER RETAINER LH REAR	\$ SL	54.20 X
9	1	BUMPER REFLECTOR LH	\$ SL	16.60 X
10	1	BUMPER BEAM REAR	\$ Bu	547.80 ✓
11	1	BUMPER BEAM BRACKET LH REAR	\$ H	114.50 X
12	1	BUMPER BEAM BRACKET RH REAR	\$ H	100.90 X
13	1	OUTER PANEL REAR (End Panel)	\$ Bu	745.80 ✓
14	1	OUTER PANEL REAR (End Panel) TRIM	\$ CM	404.56 ✓
15	1	TAILLAMP RH	\$ SL	313.10 X
16	1	TAILLAMP PANEL RH	\$ H	401.40 X
17	1	TAILLAMP LH	\$ SL	401.40 X
18	1	TAILLAMP PANEL LH	\$ H	401.40 X
19	1	BOOT REAR	\$ Bu	1,677.20 ✓
20	1	BOOT FINISHER	\$ SL	344.70 X
21	1	BOOT WHEATERSTRIP	\$ SL	178.20 X
22	1	BOOT REFLECTOR LAMP LH	\$ SL	277.70 X
23	1	BOOT REFLECTOR LAMP RH	\$ SL	277.70 X
24	1	BOOT BADGE 'RENAULT'	\$ H	82.40 ✓
25	1	BOOT BADGE	\$ H	95.80 ✓
26	1	BOOT STRUT LH	\$ SL	145.10 X
27	1	BOOT STRUT RH	\$ SL	145.10 X
28	1	BOOT HINGE LH	\$ H	254.20 X

**Trans-cab Auto Services Pte Ltd****AAD1911-207**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 511B**

29	1	BOOT HINGE RH	\$	R	253.80	}	X	
30	2	BOOT RUBBER PLUG	\$	Sh	139.90			
31	2	BOOT BUFFER	\$	Sh	26.80			
32	1	BOOT LOCK LINKAGE	\$	Sh	20.60			
33	1	BOOT LOCK LINKAGE HOLDER	\$	Sh	99.50			
34	1	BOOT INNER TRIM BOARD	\$	Sh	611.00			
35	1	BOOT SWITCH	\$	Sh	113.00			
36	1	BOOT LOCK	\$	R	246.60			
37	1	BOOT LOCK CATCH	\$	R	41.70			
38	1	EXHAUST REAR	\$	R	5,263.60	}		
39	1	EXHAUST CAP REAR	\$	R	125.40			
TOTAL			\$		15,232.66			
10%			\$		1,523.27			
			\$		13,709.39			

**Special Nett**

Special Net						
1	1SET	PARKING AID	\$	Sh	700.00	X
2	1SET	REAR BUMPER CLIP	\$	na	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00	—
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1	BOOT STICKER "Trans-cab"	\$	na	30.00	—
11	1	BOOT STICKER "6555-3333"	\$	na	30.00	—
12	2	REAR WINDSCREEN SEALANT	\$	na	80.00	} X
13	1	WINDSCREEN MOULDING	\$	na	100.00	
14	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
15	1	BOOT INNER TRIM CLIP	\$	na	45.00	
16	1SET	BOOT FINISHER CLIP	\$	na	24.20	
17	1	TAILLAMP CLIP LH	\$	na	5.00	}
18	1	TAILLAMP CLIP RH	\$	na	5.00	
19	1	Rear Bumper Protector	\$	na	100.00	4050

**Trans-cab Auto Services Pte Ltd****AAD1911-207**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 511B**

20	1	EXHAUST MOUNTING REAR	\$	Sh	16.00	X
21	1	EXHAUST BRACKET REAR	\$	Sh	24.80	X
<b>TOTAL</b>			<b>\$</b>		<b>1,507.00</b>	
<b>TOTAL PARTS</b>			<b>\$</b>		<b>15,216.39</b>	

**LABOUR**

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	601
To Rust-Proofing Of The Affected Areas.	\$	170.00	601
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	6001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	↪ 170.00	X
To check steering geometry and computer wheel alignment	\$	↪ 220.00	X
To repair and realign rear exhaust pipe.	\$	↪ 170.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	↪ 170.00	X

**Trans-cab Auto Services Pte Ltd****AAD1911-207**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 511B**

Labour charge to mount and dismount vehicle on jig  
bench, to facilitate repair.

\$ *nn* 380.00 X

Putty and spray painting of the affected portion.

\$ 6,000.00 *6601*

To drop rear exhaust box, renew the same, to repair  
and realign centre exhaust pipe.

\$ *nn* 170.00 X**TOTAL** \$ **14,680.00****Over All Total** \$ **29,896.39****PART BY PART ( REPAIR DAY)**~~20~~ DAYS*5 days***LKK Auto Consultants** hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance C

Acknowledged by Repairer

Signature:

Date: