



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 27/11/2019

User ID : BoonChewTay

### Section A - Accident Details

Registration Number	SG6019X
Case Reference Number	BUS/11/19/1056
Registration Date	11/12/2018
Company Type	SMRT Buses Ltd
Make	A95 MAN E6
Model	A95
Name of Driver	Loh Wan Thim
Type of Accident	Side Swipe
Accident Date and Time	22/11/2019 12:55 PM
Accident Reported Date and Time	25/11/2019 4:09 PM
Is Surveyor Required?	No
Survey by	
Vehicle Is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG6019X-RIGHT FRONT PORTION YP832K ( TP ) INSURED WITH
Prepared Date and Time	26/11/2019 11:42 AM
Chassis Number	WMAA95ZZ6KF008311
Mileage	
Work Shop	
Repair Completion Date and Time	

### Section B - Summary of Repair Estimates

Summary of Repair Estimates	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,325.00	\$0.00
Total Spray Cost	\$616.00	\$0.00
Total Spare Part Cost	\$3,820.41	\$0.00
Total Other Cost	\$0.00	\$0.00
<b>TOTAL COST</b>	<b>\$5,761.41</b>	<b>\$0.00</b>
Lump Sum Total	\$0.00	
Number of Repair Days	4.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	26/11/2019 11:57 AM	<input checked="" type="checkbox"/>
Signature		

Remarks

### Section C - Quotation and Accident Invoice Details

Quotation Number	Invoice Number
Quotation Date	Invoice Date
Invoice Amount	Prepared Date

27/11/19, 2:00pm

wrl April  
3 days

Steve

P/P  
Ry Bel sy



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 27/11/2019

User ID : BoonChewTay

### Section D - Details of Repair Estimates

#### Part 1 - Labour Works

##### Job Scope

TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.

Quotation from AR

Total Labour \$1,325.00

Adjusted by Surveyor, if applicable

#### Part 2 - Spray Painting & Panel Beating Related Works

##### Job Scope

PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS

Quotation from ARC

Total Spray Painting & Panel Beating \$616.00

Adjusted by Surveyor, if applicable

#### Part 3 - Other Costs - Accident and Accident Repair Related Expense

##### Job Scope

Quotation from ARC

Total Other Costs \$616.00

Adjusted by Surveyor, if applicable

#### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010161			FRONT VIEW MIRROR RH	1.00	\$1,244.90	10.00	\$1,120.41	Replace	BR
013471	Body	124-2-2-009-002	O/S FRP FRONT HEADLAMP COVER	1.00	\$975.00	10.00	\$877.50	Replace	BR
		81-25101-6766	HEADLAMP RHS	1.00	\$2,025.00	10.00	\$1,822.50	Replace	?
total					\$4,244.90		\$3,820.41		

#### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey