

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 20947

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1409/2019/NS
Date : 28-Nov-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured Vehicle No : SFP 1200 C

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: Fax 6338 1504

Owner's Name : Ms Ong Wei Ling
Address : 25 Woodleigh Close
#04-07
Singapore 357920
Telephone : HP +65 93689921
Type of Claim : Third Party Claim
Policy No. : 1800041608-01
Vehicle No : **SJT 9126 M**
Model Code : Audi A3 SEDAN 1.0 TFSI 8V
Model / Year : Apr-18
Engine No : CHZ 425954
Chassis No : WAUZZZ8V3J1050367
Mileage : -
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 27-Nov-19
Place of Accident : Raffles City Level B2 Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJT 9126 M

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns outside temperature sensor and headlight washer assy.	S/N \$	360.00	
2	To remove and reinstall rear parking aid. Check function and renew according to damage.	S/N \$	280.00	
3	To remove and transfer rhs front door and rhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$	560.00	
4	To dismantle rhs front door panel trim. To remove and reinstall rhs wing mirror assy.	S/N \$	300.00	
SUB-TOTAL LABOUR CHARGES		:	<u>\$ 1,500.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJT 9126 M

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
5	To dismantle front bumper, rhs front fender, rhs front door, rhs rear door and rear bumper. To renew rhs front fender, rhs front door and rhs rear door. To repair rhs sill panel and rhs rear fender. Re-organise crash management components. Reinstall all parts removed.	\$ 4,900.00	
6	To respray front bumper, rhs front fender, rhs front door, rhs rear door, door handle, rhs sill panel, rhs rear fender and rear bumper.	\$ 6,300.00	
7	To renew rhs rear rim and carry out wheel alignment.	S/N \$ 280.00	
8	To carry out diagnostic check.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 13,172.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJT 9126 M

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	REMARKS
1	FRONT FENDER - RH	\$ 778.00	
2	FRONT FENDER ATTACHMENT PARTS	\$ 65.00	
3	FRONT FENDER REAR BRACKET - RH	\$ 25.00	
4	FRONT FENDER CENTRE BRACKET - RH	\$ 35.00	
5	FRONT DOOR - RH	\$ 2,279.00	
6	FRONT DOOR OUTER SEAL - RH	NEC \$ 146.00	
7	BONDING AGENT	NEC \$ 45.00	
8	CLEANING SOLUTION	NEC \$ 65.00	
9	FRONT DOOR ATTACHMENT PARTS	\$ 218.00	
10	FRONT DOOR CATCH	\$ 96.00	
11	TYRE PRESSURE DATA PLATE	\$ 26.00	
12	REAR DOOR - RH	\$ 2,279.00	
13	REAR DOOR OUTER SEAL - RH	NEC \$ 146.00	
14	BONDING AGENT	NEC \$ 45.00	
15	CLEANING SOLUTION	NEC \$ 65.00	
16	REAR DOOR ATTACHMENT PARTS	\$ 117.00	
17	REAR DOOR CATCH	\$ 85.00	
18	REAR ALUMINIUM RIM - RH	\$ 666.00	
19	STONE CHIP	S/N \$ 180.00	
20	SUNDRIES	\$ 400.00	
TOTAL SPARE PARTS		: \$ 7,761.00	
TOTAL LABOUR CHARGES		: \$ 13,172.00	
GRAND TOTAL		: \$ 20,933.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant