

K'S PERFORMANCE

Repair Estimates

Make & Model: Volkswagen Touran 1.6 Tdi

Date: _____

Vehicle Number: SKP 984 X

List Price

No.	Description	Cond.	Price
1	Front Bumper <i>scr /</i>		1380
2	Front O/S Fender <i>st /</i>		530
3	Front O/S Headlamp <i>scr /</i>		1100
4	Side Mirror O/S <i>bro /</i>		600
5	Front O/S Rim <i>scr / 8/N</i>		580
Total:			4160
10% Discount:			416
			3744

3610
10%
3249
300
5/N
360
60

Special Nett

1	Front Bumper Retainer (Pair) <i>nu /</i>		120
Total:			120

3249
360
1430
5039
20%
4031.20
L/S - 4000
6 days

B:	Labour		Price
No.	Description		
	Labour to remove, replace and realign all damage parts.		1100
			40
	Electrical testing to ensure functional		100
	Chassis/ Wheel Alignment		120
	Apply Antirust Coating to all the affected parts after repair		1200
	To provide Spray painting service to all affected Exterior Panels eg. Bonnet, Bumper, Fender, Door, Side Mirror Cover, ect...		
Total:			2560

500
30
60
40
800
1430

K's Performance
53265690C

Prepared by: K's Performance

Repair Cost (A+B): **6424**

Lump Sum repair cost: **\$5,100**

Rasul
Hy 9000068
6 days
L/S
28/11/2020 @ 1640
Resurvey after repair

Survey No. of Trip: