

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 16 Nov 2020

Preliminary Advice

Insured Vehicle No	: FBF7802B		
TP Vehicle No	: SKP984X	Accident Date	: 06/11/2019
Make	: VOLKSWAGEN TOURAN	Assignment Date	: 28/11/2019
Date of Inspection	: 28/11/2019	Est. Duration of Repair	: 6
Inspection At	: K'S PERFORMANCE & SERVICES (HQ) 67 YUNNAN DRIVE 3 SINGAPORE 637954		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,424.00
Revised Amount	:S\$	5,039.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,039.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- () Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.