

ASS. REC. BY:

REF:

CS/CT1/9021077/Ht d3b2

Special Instruction:

Surveyor: Hock Ann

ASSIGNMENT (Office)

Person: Chong Boon Sen

of

CT1

Date/Time: 28/11/11 @ 4:23pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

JTO 9311

Insured:

GT9309M

at Workshop m/s

Hua Ho Trading

Tel:

62 84 4487

of

Blk 6 Dofu Lane 10 # 01-540

Policy No:

Claim No:

SNM1AD 205 636

Sum Insured:

Excess:

Make of Veh:

D.O.A.

(Client's Record)

29/11/11

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time: 4:36pm 28/11/11

Person Contacted:

Mr. Lee

Vehicle: IN/OUT

Date/Time	Action/Instruction	Remarks
	JTO 9311-X	✓
	GT9309M-NA/III/2014090/2	BUA: 49/7/2012
22/1/20	JTO 9311 Finded At 2/sup car \$ 650, over 2 days	
	Agree by workshop person exchange (ms thng)	(Red: 634:49%)

ASSIGNMENT

From:

Date:

29/11/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

JTA 9311

at Workshop m/s

Hua Ho Trading

of

Bik 6 Defu lane 10# 01-540

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS ^{1up}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

JTA 9311

Yr Regn:

19/7/17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

YAMAHA LC

cc

134

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

35662

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

PMY4 G0810K 0137252

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

Inorder / Jammed / Leaked / Burnt or

Brake:

Inorder / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

80/90/17

R:

90/80/17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7 - PIR mm

R/Bal.

7 - PIR mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

25/1/17

D.O.I.

29/11/17

Survey held at

Hua Ho

Des. of Damages:

Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Huck Ann

* JTA 9311

Do Direct Av Estimate on

Pls see my remarks

RECEIVED 29 JAN 2020

MV → \$2360 - already consent to sig value

2/12

Date/Time, File Pass to?

DTH Typist

Date/Time, File Return to?

2

Report Format:

TP

Lump Sum / I.B.I.:

650

Days Of Repair:

2

Resurvey No. of Trip:

2

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Insp (\$)

Weed and (\$)

Survey Fee:

220

Transportation:

S + RS: \$

Photos

Other

TOTAL

220

Hock Ann (LKK Auto)

From: Hock Ann (LKK Auto)
Sent: Wednesday, 22 January, 2020 1:17 PM
To: huaho trading
Cc: Denise Tay (LKKAuto)
Subject: RE: FINALIZED JTQ 9311

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear ms thng ,

Good day, o.k will be process base on finalized total amount COR \$ 650 L/sump REPAIR and DOR 2 days close.

Noted : All finalized document > LOA ,LOD,DV,LTA need send direct (china taiping insurance) claim dept .

Thanks.

Best Regards,

Hock Ann | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: huaho trading [mailto:huahotrading@yahoo.com.sg]
Sent: Tuesday, 21 January, 2020 10:18 AM
To: Hock Ann (LKK Auto)
Subject: Re: ~~SMD-2228-FINALIZED ADJUSTMENT ESTIMATE~~

Dear Hock Ann,

Attached for ur reference, kindly send over the discharge voucher

Thank you!

On Monday, 20 January 2020, 02:17:43 PM SGT, huaho trading <huahotrading@yahoo.com.sg> wrote:

Dear Hock Ann,

Kindly send over the discharge voucher to the b/m address.

Hua Ho Trading
Blk 6 Defu Lane 10
#01-540 SE 539187
Tel No:62844487

On Monday, 20 January 2020, 02:04:27 PM SGT, huaho trading <huahotrading@yahoo.com.sg> wrote:

Dear Hock Ann,

Acceptance of lump sum \$650 for repair only.

Thank you!

Best Regards
Hua Ho Trading

On Thursday, 16 January 2020, 01:17:44 PM SGT, Hock Ann (LKK Auto) <hockann@lkkauto.com> wrote:

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Dear ms thng ,

Good day , Kindly attached refer JTQ 9311 YAMAHA 135 LC finalized updated calculate adjustment on 16.1.2020

COR - \$ 650

DOR – 2 DAYS

Please refer adjustment updated total L/SUMP amount \$ 650 if agree total L/SUMP amount and repair days, will be to close case.

Please to updated email back asap.

Thanks.

Best Regards,

Hock Ann | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LETTER OF UNDERTAKING & AUTHORISATION

To: Hua Ho Trading
Blk 6 Defu Lane 10
#01-540 Defu Industrial Estate Park C
Singapore 539187

In the matter of an accident involving motor vehicles ITA 9311 & GT9309M
Next Blk 21 DEFU LANE 10

I/We CHOO POY SHEA the owner of vehicle registration no. ITA 9311
hereby do authorize you to commence repairs to my abovementioned vehicle.

I/We confirm that you are hereby authorized to handle the repairs of my vehicle and/or to negotiate and settle any claims relating to the above accident which I/we may have against the third party/parties or insurers and/or to instruct lawyers on my/our behalf to facilitate the third party claim for me/us.

You are hereby authorized as my attorney to execute and/or sign any documents/discharge vouchers/discharge agreement regarding my/our claim for my convenience.

In the event that I/We am/are required to attend at my/our solicitors' office or to attend court in connection with my/our claim, I/we shall render full co-operation.

I confirm that in the event of an unsuccessful claim against the negligent party and/or my own insurer for the damages caused to my vehicle, I agree to pay all repair cost, survey fee and any incidental expenses incurred by you or to lodge an own damage claim (only for comprehensive cover) to cover the expenses incurred.

I undertake not to independently make negotiate or settle any claim in respect of the above accident without first giving you 7 days notice in writing and upon so doing, I further undertake to pay to you immediately your administrative charges for work done and time expended in managing my claim herein. For the purposes of clarification, the aforesaid administrative charges shall not include any work done or sum expended towards repairs to my said vehicle and in the event that repair work/s has commenced before the giving of the above notice, I hereby undertake to pay to you the full sum of the costs of repairs as shall be recommended by a licensed surveyor.

Dated the 25 day of 11 2015

li
Owner (signature)

CHOO POY SHEA
Owner (name)

612276326T
NRIC No.

Address: 21 DEFU LANE 10
SE 535202

li
Witness (signature)

Thio Boon Khue
Witness (name)

S2585342C
NRIC No.

Address: 6 DEFU LANE 10
#01-340 SE 535187

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 28 November 2019 4:23 PM
To: huaho trading
Cc: assignments
Subject: RE: OUR REF: SNM19D205636/GT9309M/CBS & YOUR REF: JTQ9311 -TO CONDUCT PRS -Accident between JTQ9311 & GT9309M

WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s LKK AUTO CONSULTANTS to survey your client's vehicle.

Aside to LKK AUTO CONSULTANTS,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: huaho trading [mailto:huahotrading@yahoo.com.sg]

Sent: Thursday, November 28, 2019 9:18 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: OUR REF: SNM19D205636/GT9309M/CBS & YOUR REF: JTQ9311 -TO CONDUCT PRS -Accident between JTQ9311 & GT9309M

Dear Sir/Mdm,

We have chosen Kelvin Ang, pls send over the surveyor today.

Thank you!

Best Regards
Hua Ho Trading

On Wednesday, 27 November 2019, 01:18:38 PM SGT, Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without prejudice
Dear Sir,
LKK
STA



Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Wednesday, November 27, 2019 12:00 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; huahotrading@yahoo.com.sg

Subject: OUR REF: SNM19D205636/GT9309M/CBS & YOUR REF: JTQ9311 -TO CONDUCT PRS - Accident between JTQ9311 & GT9309M

Dear Boon Sen,

Please conduct PRS-JTQ9311-soonest possible.

File with officer-in-charge-Chong Boon Sen-DID- 6389 6171

Dear Hua Ho Trading,

***** kindly quote our reference number when replying *****

Thank you.

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

Tel.:6389 6116

Fax: (65) 6224 7175 / 6224 7478

Email : claimsdept@sg.cntaiping.com

Website:www.sg.cntaiping.com

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: huaho trading [<mailto:huahotrading@yahoo.com.sg>]

Sent: Tuesday, November 26, 2019 2:53 PM

To: Claims Dept of CTI

Subject: Accident between JTQ9311 & GT9309M

Dear Sir/Mdm,

Attached is the accident report between JTQ9311 & GT9309M, kindly send over an surveyor to the b/m address.

Hua Ho Trading

Blk 6 Defu Lane 10

#01-540 SE 539187

Tel No: 62844487 Fax No: 6289 8180

Thank you!

Best Regards

Hua Ho Trading

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Search for manufacturers, brand or products



POST FREE AD



YAMAHA LC 135

Kuala Lumpur

RM 6,868

NEGOTIABLE PRICE

CONTACT SELLER

VISIT STORE

sum 1 sum run 7100
↓
\$2300 cannot sig

Brand

Yamaha

Model

135LC

Type

Moped

Year

2019

Color

Blue

Engine

135 Cc

Gearbox

Manual

Engine Type

Petrol

Warranty

1 Year(S)



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

DQPMTS90

No. Pendaftaran : JT09311
No. ID : 920507085667
Nama Pemunya Berdaftar : CHOO POY SHEN
Alamat : A 4710 JALAN MURAI LORONG ALOR AKAR 30
25250 KUANTAN PAHANG

No. Chasis/No. Enjin : PWYH00810K0137252 / 0305E-137312
Buatan/Nama Model : YAMAHA / 135LC
Keupayaan Enjin : 134
Bahan Bakar : PETROL
Status Asal : PEMASANGAN TEMPATAN
Kelas Kegunaan : MOTOSIKAL
Jenis Badan/Tahun Dibuat : MOTOSIKAL / 2019
Tarikh Pendaftaran : 19/09/2019
R. D. W/B. G. K/BTM : -
Syarat Pendaftaran 1 : -
Syarat Pendaftaran 2 : -
Syarat Pendaftaran 3 : -



SINGAPORE POLICE FORCE



T/20191125/2112

1 of 3

Police Station Of Origin:
Paya Lebar NPP
114 Hougang Avenue 1 #01-1270
SINGAPORE 530114
Tel No: 1800-2899999

Report No. T/20191125/2112

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 25/11/2019 14:52		Video Report No.:		Station Diary No.: 14	
Informant's Particulars					
Name of Informant: CHOO POY SHEN			Address: C/O 21 Defu Lane 10 SINGAPORE		
ID Type / ID No.: FIN NO / G2276326T			Contact No.: Home/Office: Mobile: 82123541		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 27	Date of Birth: 07/05/1992	Type of Informant: Rider		
Race: Chinese			Language:		Institution / School Name:
Occupation: Mechanic			Driving Licence Information: Class: 2B,3C Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 25/11/2019 09:15	Type of Location: Straight Road
Location: DEFU LANE 10 near blk 21 defu lane 10				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GT9309M	Van	HYUNDAI		Blue	Slightly Damaged	1
JTQ9311	Motorcycle				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20191125/2112

2 of 3

Report No. T/20191125/2112

Police Station Of Origin:
Paya Lebar NPP
114 Hougang Avenue 1 #01-1270
SINGAPORE 530114
Tel No: 1800-2899999

CONTINUATION OF REPORT

Rider			
Name	CHOO POY SHEN	ID No.	G2276326T
Related Vehicle	JTQ9311 (Motorcycle)	Contact No.	82123541
Hospital/Clinic	HOUGANG CLINIC	Class of Driving Licence & Expiry Date	Class: 2B,3C Date of Expiry: NIL
Date Treatment	25/11/2019	Date Discharge	25/11/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On the 25/11/2019 at about 0915hrs, I was riding along Blk 21 of Defu Lane 10 carpark and suddenly a passenger from a van (GT9309M) opened the door and I was knocked down by it. I hit onto a parked vehicle before landing on the ground.

No traffic police or ambulance came down to scene. I then went to see a doctor after the accident and was given 3 days of MC.



**SINGAPORE
POLICE FORCE**



T/20191125/2112

3 of 3

Police Station Of Origin:
Paya Lebar NPP
114 Hougang Avenue 1 #01-1270
SINGAPORE 530114
Tel No: 1800-2899999

Report No. T/20191125/2112

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

F /

Sgt 2 GABRIEL LEE BO WENG

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

Sgt 2 SHARIFAH NOR FARIZAN BINTE SYED
MOHD SAID

Contact No.: 65476172

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:

25/11/2019 14:52

Classification Of Case:

LESEN KENDERAAN MOTOR
MOTOSIKAL

No. SIRI: AT 353060
18 SEP 2020

JTQ9311

038887 19092019

0101041 IDAA 18092020

JTQ9311

RM2.00

HDSG019

134 SP AA

IMS1 : D02063-19002752

IMS2 :

VEL01001



Zurich General Insurance Malaysia Berhad (INCORPORATED)
 Level 22B, Menara Zebra, 5, Jalan Ronggeng, 43500 Kajang, Selangor, Malaysia
 Tel: 603-89494000 Fax: 603-89494000 E-mail: zgm@zurich.com.my

CONFIRMATION OF PURCHASE OF INSURANCE

E-ClNote No. : D02063-19002752
 Issue Date & Time : 19 SEP 2019 10:44:12am
 Period of Cover : From 19 SEP 2019 to 18 SEP 2020
 Vehicle Registration No. : JTQ6311
 Make of Vehicle : YAMAHA 135 LC
 Engine No. : G3G5E-137312 Chassis No. : PMYUG0810K0137252
 Capacity : 134.00 CC Year of Make : 2019
 Insured Name : CHOO POY SHEN
 Address : A4710 JALAN MURAI LORONG ALOR AKAR 30,25250 KUANTAN,PAHANG DARUL MAKMUR
 NRIC/Business Reg No. : 920507-08-5567
 Type of Cover : V-CO MOTOR COMPREHENSIVE
 Use of Vehicle : MOTORCYCLE - 2-RIDER
 HP Owner :
 Sum Insured (RM) : 7,100.00
 Transaction Type : New
 All Claims Excess : RM 100.00
 Voluntary Excess : 0.00

Sum Insured	(RM)	7,100.00	Premium	(RM)	217.89
All Rider (Y/N)		Y	All Rider Amt	(RM)	108.95
NCD %		0.000000 %	NCD Amt	(RM)	0.00
			Basic Fee	(RM)	326.84
Tuition Load %		0 %	Tuition Load Amt	(RM)	0.00
			Extra Coverage	(RM)	0.00
SST		6.00 %	SST	(RM)	19.61
			Stamp Duty	(RM)	10.00
			Cycle PAC	(RM)	27.56
Act Premium	(RM)	62.91	Payable Premium	(RM)	364.01

Extra Benefits	Extra Summ (RM)	Extra Premium (RM)
ALL RIDERS	0.00	0.00
Cycle PAC (including premium for extra coverage whenever is applicable, SST and stamp duty)	11,000.00	27.56

Named Drivers
 ALL RIDERS

Agent : D02063-000 TIAW @ TEO WEE LI
 Tel No : 07-6956996

THIS IS A COMPUTER GENERATED FORM. SIGNATURE IS NOT REQUIRED.



Zurich General Insurance Malaysia Berhad (INCORPORATED IN MALAYSIA)
Level 21A, Menara S. R. No. 4, Jalan Sultan, 45, 45000 Kuala Lumpur, Malaysia
Tel: 60-3-935 6880 Fax: 60-3-2195-6880 Call Centre: 1-800-888-622

Code / Kod 18 MY3

CERTIFICATE OF INSURANCE

SIJIL INSURANS

BERSEKUTUAN DENGAN 1871/1950/1951
THE MOTOR VEHICLES (Third Party Risks & Compensation) Act (Cap 189) Republic of Singapore
THE MOTOR VEHICLES (Third Party Risks & Compensation) Act (Cap 189) Negara Brunei Darussalam
THE MOTOR VEHICLES (Third Party Risks & Compensation) Act (Cap 189) Brunei Darussalam

BERSEKUTUAN DENGAN 1871/1950/1951
THE MOTOR VEHICLES (Third Party Risks & Compensation) Act (Cap 189) Republic of Singapore
THE MOTOR VEHICLES (Third Party Risks & Compensation) Act (Cap 189) Negara Brunei Darussalam
THE MOTOR VEHICLES (Third Party Risks & Compensation) Act (Cap 189) Brunei Darussalam

Certificate No. (No. Sijil) : 501900155027-00		D02063-000
1. Index Mark and Registration Number of Vehicle (Tanda Indeks dan Nombor Pendaftaran Kenderaan)	JTG9311 YANHA 135 LC	NCD : 0.00 %
2. Name of Policyholder (Nama Pemegang Polisi)	CHOO POY SHEN	
3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance of Parliament		19 SEP 2019
4. Date of Expiry of the Insurance (Tarikh Habisnya Insurans)	18 SEP 2020	
5. Persons or Classes of Persons entitled to drive* (Orang-orang Kelas/Orang yang berhak memandu*)		
a) Policyholder b) Any other person who is riding on the Policyholder's order or with his permission. Provided that the person riding is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from riding the Motor Vehicle.		
Limitation on Usage Use for social domestic and pleasure purposes and by the Policyholder in person in connection with his business or profession. The policy does not cover : Use for hire or reward, racing, pace-making, reliability trial, speed-testing or the carriage of goods (other than samples) in connection with any trade or business or use for any purpose in connection with the Motor Trade.		
Insurans ini dikeluarkan mengikut Seksyen 90 of the Road Transport Act, 1987 (Singapore) or Section 9 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189) Republic of Singapore or Section 7 of the Motor Vehicles Insurance (Third Party Risks) Act (Cap. 90) Negara Brunei Darussalam and not to be construed under those Act(s).		
Insurans ini dikeluarkan mengikut Seksyen 90 of the Road Transport Act, 1987 (Singapore) or Section 9 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189) Republic of Singapore or Section 7 of the Motor Vehicles Insurance (Third Party Risks) Act (Cap. 90) Negara Brunei Darussalam and not to be construed under those Act(s).		
Insured in pursuance to cover Note No : D02063-10002752 Dikurangkan mengikut Nota Indemniti No.		

I / We hereby certify that the Policy to which the Certificate is issued is in accordance with the provisions of Part IV of the Road Transport Act, 1987 (Malaysia), Motor Vehicles (Third Party Risks & Compensation) Act (Cap 189) Republic of Singapore and the Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam

Saya / Kami dengan ini mengesahkan bahawa Polisi yang berkaitan dengan Sijil ini dikeluarkan selaras dengan peruntukan - peruntukan Bahagian IV Akta Pengangkutan Jalan 1987 (Malaysia), Akta Kenderaan Motor (Risiko Dan Penggantian Pihak Ketiga) (Cap 189) Republik Singapura dan Akta Insurans Kenderaan Motor (Risiko Pihak Ketiga) (Cap 90) Negara Brunei Darussalam

For and on behalf of / Untuk dan bagi pihak -
ZURICH GENERAL INSURANCE MALAYSIA BERHAD

Junar Cho
Chief Executive Officer

和 好 貿 易 HUA HO TRADING

新加坡德福工業區C德福十巷大牌6號門牌#01-540
Blk 6, Defu Lane 10, #01-540 Defu Industrial Estate Park C,
Singapore 19653. Tel: 2844487 (2 Lines)
539127 Fax: 2898180

DEAR SIR:

ESTIMATE COST REPAIR FOR THE ACCIDENT MOTOR_CYClev.NO:JTQ 9311

ITEMS	PRICE
MIRROR \$38X2PCS <i>R/H ✓ C/A 14scr ✓</i>	\$76 ✓
BRAKE PUMP 1set <i>✓ C/A</i>	\$192 ✓
HANDLE GRIP <i>X SUC</i>	\$32
HANDLE BAR <i>X SUC</i>	\$86
HANDLE BALANCER <i>✓ SCR 2/H only R/H X</i>	\$36 16 ✓
FOOTREST BAR <i>✓ AT SUC</i>	\$42 ✓
SIDE REAR FOOTREST LEFT <i>✓ C/A</i>	\$58 50 ✓
SIDE PANNEL LEFT <i>X SUC</i>	\$60
REAR BOX <i>✓ SCR</i>	\$200 150 ✓
NO PLATE REAR <i>✓ C/A</i>	\$24 ✓
BRAKE LEVER <i>✓ SCR</i>	\$18 ✓
FRONT FENDER <i>✓ C/A</i>	\$82 ✓
TOP HEAD SMALL WIND SCREEN <i>✓ SCR</i>	\$48 38 ✓
TOWING FEE <i>✓</i>	\$50 30 ✓
LABOUR CHARGE	\$280 160 ✓
TOTAL	<u>\$1284</u>

Parts =	688
Parts less	10%
	619.20
Spent	30
Labour	160
	809.20
L/S less	20%
	647.36
Total	↓
L/S AT	\$650.4

HUA HO TRADING

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

without prejudice
Hock Ann
85311883 / 67418434 - 085
L/S repair
Resurvey after paint
2 day
Hock ANN @ LKK Auto
12.20pm
29/11/19

Resurvey
H. Ann
1hr
1.30pm
29/11/19

門市發票 CASH SALE

C/S No: 22875

和 好 貿 易
HUA HO TRADING

(Business Registration No. 234469/00E)

Block 6, Defu Lane 10, #01-540,
Defu Industrial Estate Park C, Singapore 539187

Tel: 62844487, 62842585 Fax: 62898180

M/ CHINA TAIPING INSURANCE(S).P.L.

ITA 9311.

Date, 20.01.2020

数量 Quantity	貨名 PARTICULARS	單價 Rate	銀 Amount \$ cts.
	Repair motor-cycle lump sum		650 00
	lost of use 2 day x \$35		70 -00
總計 TOTAL			720 00

新舊摩多分期付款及保險代理
New & Second Hand Motor-Cycle Hire Purchase General Insurance.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Jan 2020		24 Jan 2020 08:57 Edit Adj Rpt	S\$650.00 Edit Estimates	S\$650.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	Co. Reg. No.: -								
Main Claimant:	choo poy shen								
Vehicle Reg. No.:	JTQ9311	Date of Loss:	25/11/2019 00:00 - :59 [2 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D205636C02	Policy/Cover Note No.:	DMCVSN30398319000						
Vehicle Reg. No. (Insured):	GT9309M	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Hua Ho Trading (HQ) Blk 6 Defu Lane 10, #01-540 Defu Industrial Estate Park C, 539187 Defu Lane - Tel: 62844487								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 05/02/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*JTQ9311 (SNM19D205636C02)
 [GT9309M]
 TP
 choo poy shen
 Nov 25 2019 12:00AM
 [-]
 Hua Ho Trading

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	24/01/20 09:25	General View						Load JPG	☒	
2	24/01/20 09:25	General View						Load JPG	☒	
3	24/01/20 09:25	General View						Load JPG	☒	
4	24/01/20 09:25	General View						Load JPG	☒	
5	24/01/20 09:25	General View						Load JPG	☒	
6	24/01/20 09:25	General View						Load JPG	☒	
7	24/01/20 09:25	General View						Load JPG	☒	
8	24/01/20 09:25	General View						Load JPG	☒	
9	24/01/20 09:25	General View						Load JPG	☒	
10	24/01/20 09:25	General View						Load JPG	☒	
11	24/01/20 09:25	General View						Load JPG	☒	
12	24/01/20 09:25	General View						Load JPG	☒	
13	24/01/20 09:25	General View						Load JPG	☒	
14	24/01/20 09:25	General View						Load JPG	☒	
15	24/01/20 09:25	General View						Load JPG	☒	
16	24/01/20 09:25	General View						Load JPG	☒	
17	24/01/20 09:25	General View						Load JPG	☒	
18	24/01/20 09:25	General View						Load JPG	☒	
19	24/01/20 09:25	General View						Load JPG	☒	
20	24/01/20 09:25	General View						Load JPG	☒	
21	24/01/20 09:25	General View						Load JPG	☒	
22	24/01/20 09:25	General View						Load JPG	☒	
23	24/01/20 09:25	General View						Load JPG	☒	
24	24/01/20 09:25	General View						Load JPG	☒	
25	24/01/20 09:25	General View						Load JPG	☒	
26	24/01/20 09:25	General View						Load JPG	☒	
27	24/01/20 09:25	General View						Load JPG	☒	
28	24/01/20 09:25	General View						Load JPG	☒	
29	24/01/20 09:25	General View						Load JPG	☒	
30	24/01/20 09:25	General View						Load JPG	☒	
31	24/01/20 09:25	General View						Load JPG	☒	
32	24/01/20 09:25	General View						Load JPG	☒	
33	24/01/20 09:25	General View						Load JPG	☒	
34	24/01/20 09:25	General View						Load JPG	☒	
35	24/01/20 09:25	General View						Load JPG	☒	
36	24/01/20 09:25	General View						Load JPG	☒	
37	24/01/20 09:25	General View						Load JPG	☒	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	24/01/20 09:25	General View	 Load JPG	☒
39	24/01/20 09:25	General View	 Load JPG	☒
40	24/01/20 09:25	General View	 Load JPG	☒
41	24/01/20 09:25	General View	 Load JPG	☒
42	24/01/20 09:25	General View	 Load JPG	☒
43	24/01/20 09:25	General View	 Load JPG	☒
44	24/01/20 09:25	General View	 Load JPG	☒
45	24/01/20 09:25	General View	 Load JPG	☒
46	24/01/20 09:25	General View	 Load JPG	☒
47	24/01/20 09:25	General View	 Load JPG	☒
48	24/01/20 09:25	General View	 Load JPG	☒
49	24/01/20 09:25	General View	 Load JPG	☒
50	24/01/20 09:25	General View	 Load JPG	☒
51	24/01/20 09:25	General View	 Load JPG	☒
52	24/01/20 09:25	General View	 Load JPG	☒
53	24/01/20 09:25	General View	 Load JPG	☒
54	24/01/20 09:25	General View	 Load JPG	☒
55	24/01/20 09:25	General View	 Load JPG	☒
56	24/01/20 09:25	General View	 Load JPG	☒
57	24/01/20 09:25	General View	 Load JPG	☒
58	24/01/20 09:25	General View	 Load JPG	☒
59	24/01/20 09:25	General View	 Load JPG	☒
60	24/01/20 09:25	General View	 Load JPG	☒
61	24/01/20 09:25	General View	 Load JPG	☒
62	24/01/20 09:25	General View	 Load JPG	☒
63	24/01/20 09:25	General View	 Load JPG	☒
64	24/01/20 09:25	General View	 Load JPG	☒
65	24/01/20 09:25	General View	 Load JPG	☒
66	24/01/20 09:25	General View	 Load JPG	☒
67	24/01/20 09:25	General View	 Load JPG	☒
68	24/01/20 09:25	General View	 Load JPG	☒
69	24/01/20 09:25	General View	 Load JPG	☒
70	24/01/20 09:25	General View	 Load JPG	☒
71	24/01/20 09:25	General View	 Load JPG	☒
72	24/01/20 09:25	General View	 Load JPG	☒
73	24/01/20 09:25	General View	 Load JPG	☒
74	24/01/20 09:25	General View	 Load JPG	☒
75	24/01/20 09:25	General View	 Load JPG	☒
76	24/01/20 09:25	General View	 Load JPG	☒
77	24/01/20 09:25	General View	 Load JPG	☒
78	24/01/20 09:25	General View	 Load JPG	☒
79	24/01/20 09:25	General View	 Load JPG	☒
80	24/01/20 09:25	General View	 Load JPG	☒
81	24/01/20 09:25	General View	 Load JPG	☒
82	24/01/20 09:25	General View	 Load JPG	☒
83	24/01/20 09:25	General View	 Load JPG	☒
84	24/01/20 09:25	General View	 Load JPG	☒
85	24/01/20 09:25	General View	 Load JPG	☒
86	24/01/20 09:25	General View	 Load JPG	☒
87	24/01/20 09:25	General View	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	24/01/20 09:25	General View	 Load JPG	☒
89	24/01/20 09:25	General View	 Load JPG	☒
90	24/01/20 09:25	General View	 Load JPG	☒
91	24/01/20 09:25	General View	 Load JPG	☒
92	24/01/20 09:25	General View	 Load JPG	☒
93	24/01/20 09:25	General View	 Load JPG	☒
94	24/01/20 09:25	General View	 Load JPG	☒
95	24/01/20 09:25	General View	 Load JPG	☒
96	24/01/20 09:25	General View	 Load JPG	☒
97	24/01/20 09:25	General View	 Load JPG	☒
98	24/01/20 09:25	General View	 Load JPG	☒
99	24/01/20 09:25	General View	 Load JPG	☒
100	24/01/20 09:25	General View	 Load JPG	☒
101	24/01/20 09:25	General View	 Load JPG	☒
102	24/01/20 09:25	General View	 Load JPG	☒
103	24/01/20 09:25	General View	 Load JPG	☒
104	24/01/20 09:25	General View	 Load JPG	☒
105	24/01/20 09:25	Reinspection Photo	 Load JPG	☒
106	24/01/20 09:25	Reinspection Photo	 Load JPG	☒
107	24/01/20 09:25	Reinspection Photo	 Load JPG	☒
108	24/01/20 09:25	Reinspection Photo	 Load JPG	☒
109	24/01/20 09:25	Reinspection Photo	 Load JPG	☒
110	24/01/20 09:25	Reinspection Photo	 Load JPG	☒
111	24/01/20 09:25	Reinspection Photo	 Load JPG	☒
112	24/01/20 09:25	Reinspection Photo	 Load JPG	☒
113	24/01/20 09:25	Reinspection Photo	 Load JPG	☒
114	24/01/20 09:25	Reinspection Photo	 Load JPG	☒
115	24/01/20 09:26	Photo After Spray	 Load JPG	☒
116	24/01/20 09:26	Photo After Spray	 Load JPG	☒
117	24/01/20 09:26	Photo After Spray	 Load JPG	☒
118	24/01/20 09:26	Photo After Spray	 Load JPG	☒
119	24/01/20 09:26	Photo After Spray	 Load JPG	☒
120	24/01/20 09:26	Photo After Spray	 Load JPG	☒
121	24/01/20 09:26	Photo After Spray	 Load JPG	☒
122	24/01/20 09:26	Photo After Spray	 Load JPG	☒
123	24/01/20 09:26	Photo After Spray	 Load JPG	☒
124	24/01/20 09:26	Photo After Spray	 Load JPG	☒
125	24/01/20 09:26	Photo After Spray	 Load JPG	☒
126	24/01/20 09:26	Photo After Spray	 Load JPG	☒
127	24/01/20 09:26	Photo After Spray	 Load JPG	☒
128	24/01/20 09:26	Photo After Spray	 Load JPG	☒
129	24/01/20 09:26	Photo After Spray	 Load JPG	☒
130	24/01/20 09:26	Photo After Spray	 Load JPG	☒
131	24/01/20 09:26	Photo After Spray	 Load JPG	☒
132	24/01/20 09:26	Photo After Spray	 Load JPG	☒
133	24/01/20 09:26	Photo After Spray	 Load JPG	☒
134	24/01/20 09:26	Photo After Spray	 Load JPG	☒
135	24/01/20 09:26	Photo After Spray	 Load JPG	☒
136	24/01/20 09:26	Photo After Spray	 Load JPG	☒
137	24/01/20 09:26	Photo After Spray	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	24/01/20 08:58	PRI CONTACT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119021077/HTD3E2

Date: 30/01/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN30398319000

Claimant Vehicle
No: JTQ9311Insured Vehicle
No: GT9309M

Date of Loss: 25/11/2019

Nature of Claim: TP

Claim
No: SNM19D205636C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: JTQ9311

Make & Model: YAMAHA LC135, 134cc

Reg. Date: 19/09/2019 (Man. Year: 2019)

Colour: Blue

Engine Capacity: 134 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: G3G5E137312

Chassis No: PMYUG0810K0137252

Odometer: 35662 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 80/90/17

Rear Tyre Size: 90/80/17

Front Left Side: Pirelli 7 mm

Rear Left Side: Pirelli 7 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	954.00	619.20	334.80	35.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	330.00	190.00	140.00	42.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,284.00	809.20	474.80	36.98
Approved Total (Overridden) (S\$)		650.00		
Nett Amount (S\$)	1,284.00	650.00	634.00	49.38

INSPECTION

Date of Assignment: 24/01/2020

Date Inspected: 29/11/2019 Inspected At:

Hua Ho Trading (HQ)
Blk 6 Defu Lane 10, #01-540 Defu
Industrial Estate Park C
Singapore 539187

Estimated Period of Repair: 2.0 days

Adjuster: LEE HOCK ANN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Jan 2020)	
Parts:	N/A	YAMAHA LC135 134cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JTQ9311)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*MIRROR	O/S Cracked / N/S Scratched	76.00 F	*76.00 FL
2	1		*SET BRAKE PUMP	Cracked	192.00 F	*192.00 FL
3	1		*HANDLE GRIP	Serviceable	32.00 F	*- FL
4	1		*HANDLE BAR	Serviceable	86.00 F	*- FL
5	1		*HANDLE BALANCER	N/S Scratched / O/S Serviceable	36.00 F	*16.00 FL
6	1		*FOOTREST BAR	Bent	42.00 F	*42.00 FL
7	1		*SIDE REAR FOOTREST LEFT	Crumpled	58.00 F	*50.00 FL
8	1		*SIDE PANEL LEFT	Serviceable	60.00 F	*- FL
9	1		*REAR BOX	Scratched	200.00 F	*150.00 FL
10	1		*NO PLATE REAR	Cracked	24.00 F	*24.00 FL
11	1		*BRAKE LEVER	Scratched	18.00 F	*18.00 FL
12	1		*FRONT FENDER	Crumpled	82.00 F	*82.00 FL
13	1		*TOP HEAD SMALL WIND SCREEN	Scratched	48.00 F	*38.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	954.00	688.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	68.80
Total Parts (\$\$)	954.00	619.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING FEE	New	50.00	30.00
2	LABOUR CHARGE	New	280.00	160.00
Gross Labour Cost (\$\$)			330.00	190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >