

22/03/2002

ASS. REC. BY:

REF:

CS/CEI/9021080/Kg d3

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of

CEI

Date/Time: 28/11/19 04:20pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLP 5446M

Insured:

YN 5083H

at Workshop m/s

Hui Yang Motor

Tel:

64515752

of

176 & Ming Ave # 0402

Policy No:

DMCVSN 30619619044

Claim No:

SNM19 D205664 C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 27/11/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 432pm 28/11/19

Person Contacted:

Bel

Vehicle IN/OUT

Date/Time

Action/Instruction

Tehmngit

SLP 5446M-CS/AGI/9019/95/Kg d3

D.O.A. 29/10/2019

YN 5083H-NA/CEI/9015689/K4

D.O.A. 27/8/2017

17/12 81806.88 email & confirmed used \$1404.16, 44%

ASS. REC. BY:

REF:

CT21

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

1.3.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SUP 5446M

Yr Regn:

06, 17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

c.c.

1486

Colour:

M. Black

A/C: Insured / Std / NI / NA

Sp. Reading

19.7966

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

RU3

1248725

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

6

mm

L/Bal.

5

mm

L/Bal.

6

mm

D.O.A.

27/11/19

D.O.I.

3/12/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S body

The UIC / Chassis frame / Body Structure affected due to collision.

RECEIVED 19 DEC 2019

Date/Time, File Pass to?



Prell. Report



Final Report

1) 19/12/19 FST

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

220

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Report Format :

MERP

Lump Sum / I.B.I. (\$

1806.88

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 28 November 2019 4:20 PM
To: Hui Yang Motor
Cc: assignments
Subject: RE: OUR REF: SNM19D205664/YN5083H/CBS & YOUR REF: SLP5446M -Survey of SLP5446M DOA: 27/11/2019

WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s LKK AUTO CONSULTANTS to survey your client's vehicle.

Aside to LKK AUTO CONSULTANTS,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Hui Yang Motor [mailto:hui_yang_motor@hotmail.com]
Sent: Thursday, November 28, 2019 4:19 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: Re: OUR REF: SNM19D205664/YN5083H/CBS & YOUR REF: SLP5446M -Survey of SLP5446M DOA: 27/11/2019
Importance: High

Hi Boon Sen,

Our choice is LKK.

Thank you & Regards,
Bel
Tel: 64515752

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Sent: Thursday, November 28, 2019 4:14 PM

To: hui_yang_motor@hotmail.com <hui_yang_motor@hotmail.com>

Subject: RE: OUR REF: SNM19D205664/YN5083H/CBS & YOUR REF: SLP5446M -Survey of SLP5446M DOA: 27/11/2019

Without prejudice

Dear Sir,

LKK

STA

LBS

Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson

Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Hui Yang Motor [mailto:hui_yang_motor@hotmail.com]

Sent: Wednesday, 27 November, 2019 4:10 PM

To: Claims Dept of CTI

Subject: Survey of SLP5446M DOA: 27/11/2019

Importance: High

Hi,

Please refer to attached Estimate and kindly advise us on when can we arrange our client vehicle to be surveyed.

We will pass the surveyor a copy of the GIA Report.

Our Driver: SLP5446M

Your insured: YN5083H

DOA: 27/11/2019

Kindly acknowledge the receipt of this email.

Thank you & Regards,

Sandra

64515752

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

辉陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

27/11/2019

Owner: VFM PTE LTD

ESTIMATE TO REPAIR HONDA VEZEL HYBRID - SLP5446M

1pc RH side mirror
1pc RH side mirror cover
1pc rear RH door
1pc rear RH door frame sticker
1pc rear RH fender protector

less 20%

CM \$ 794.40 ✓
M \$ 185.20 ✓
R \$ 987.50 X
N \$ 155.20 X
S \$ 191.50 X
M \$
\$ 2,313.80
\$ 462.76
\$ 1,851.04

wiring
tuffkote
spray painting
labour charges
Total

\$ 80.00 200
N \$ 80.00 X
\$ 600.00 500
\$ 600.00 350
\$ 3,211.04

LKK Auto Consultants hereby certify
the Repairer of the following

- To resurvey before/after spray painting
- To display damaged part(s) during
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No additional modification(s) is allowed
- Any supplementary item(s) must be approved
- This estimate is subject to final approval from LKK Auto Consultants

Accepted by Repairer
Signature:



China Taping
(LKK)
03.12.19
Tuesday

Not Withdraw
Running AB & paint
@ 1806-88
4 day

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI19021080/KQD3N2**Date:** 23/12/2019**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30619619044
Claimant Vehicle No :	SLP5446M	Insured Vehicle No :	YN5083H
Date of Loss:	27/11/2019	Nature of Claim:	TP
		Claim No:	SNM19D205664C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP5446M		
Make & Model:	HONDA VEZEL, 1.5 (A)	Engine No:	LEB5946742
Reg. Date:	08/06/2017 (Man. Year: 2017)	Chassis No:	RU31246725
Colour:	Metallic Black	Odometer:	197966 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,851.04	936.88	914.16	49.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,360.00	870.00	490.00	36.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,211.04	1,806.88	1,404.16	43.73
+ GST 7.00/7.00% (S\$)	224.77	126.48	98.29	43.73
Nett Amount (S\$)	3,435.81	1,933.36	1,502.45	43.73

INSPECTION

Date of Assignment:	19/12/2019	Hui Yang Motor Pte Ltd (HQ)
Date Inspected:	03/12/2019 Inspected At:	Blk 176 Sin Ming Drive #04-02, Sin Ming Autocare
Estimated Period of Repair:	4.0 days	Singapore 575721

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 Dec 2019)
Parts: M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLP5446M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH SIDE MIRROR	Cracked	794.40 FL	*794.40 FL
2	1		*RH SIDE MIRROR COVER	Missing	185.20 FL	*185.20 FL
3	1		*REAR RH DOOR	Repair	987.50 FL	*- FL
4	1		*REAR RH DOOR FRAME STICKER	Not Necessary	155.20 FL	*- FL
5	1		*REAR RH FENDER PROTECTOR	Mtg Cracked	191.50 FL	*191.50 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,313.80	1,171.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	462.76	234.22
Total Parts (\$\$)	1,851.04	936.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRING	New	80.00	20.00
2	TUFFKOTE	New	80.00	0.00
3	SPRAY PAINTING	New	600.00	500.00
4	LABOUR CHARGES	New	600.00	350.00
Gross Labour Cost (\$\$)			1,360.00	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >