

EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

56 LOYANG WAY # 06-07 ENTERPRISE BUILDING SINGAPORE 508775

VEHICLE NO : GBH319R
MAKE & MODEL : NISSAN CABSTAR
CHASSIS NO : JN1SC2F24Z0860934

DATE : 18/05/2020
CLAIM TYPE : 3RD PARTY CLAIM
D.O.A : 15/11/2019

TO : MSIG

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT LIST PRICE	TOTAL LIST PRICE
1	1	RR TAILLAMP L/H	OR	\$ 266.30	\$ 266.30
2	1	RR TAILLAMP R/H	OR	\$ 266.30	\$ 266.30
3	1	RR NUMBER PLATE BRACKET	X NA	\$ 32.50	\$ 32.50
4	1	RR NUMBER PLATE LIGHT	X NA	\$ 45.60	\$ 45.60
7	1	RR CABIN DOOR L/H	X BENT (Local repair)	\$ 1,800.00	\$ 1,800.00
				\$ 2,410.70	\$ 2,410.70

TOTAL PRICE	\$ 2,410.70
LESS 10%	\$ 241.07
SUB TOTAL PRICE	\$ 2,169.63

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT S/NETT	TOTAL S/NETT
1	1	REVERSE SENSOR	OR	\$ 250.00	\$ 250.00
2	1	SPEED LIMIT 70/KM	OR	\$ 30.00	\$ 30.00
3	1	RR REGISTER PLATE	X NA	\$ 40.00	\$ 40.00
4	4	RR RUBBER STOPPER	X NA	\$ 8.00	\$ 32.00
5	2	RR CABIN DOOR HINGES	X R	\$ 55.00	\$ 110.00
6	2	RR CABIN DOOR LOCK	X R	\$ 85.00	\$ 170.00

TOTAL S/NETT	\$ 468.00	\$ 632.00
--------------	-----------	-----------

Labour Charges

- To dismantle and Re-fix damaged Rear portions; affected damaged portion.
- To apply anti rust coat and Tuff Kote affected areas
- To check lighting & wiring
- To Panel beat affected rear portions
- To Spray painting for Rear Portions affected parts

\$ 600.00	X
\$ 70.00	30
\$ 80.00	30
\$ 600.00	400
\$ 1,000.00	200

TOTAL LABOUR

\$ 2,350.00

Total Cost of Repairs

\$ 5,151.63

(Total parts + Total S/Nett + Total Labour Cost)

Store (LKK)

WH P/L
18/5/20, 3.00 pm
P/P
3 days
By DEL sy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 779.34
N- 225
L- 660
1664.34