

ASS. REC. BY:

Sun Pin

REF:

NS/INC19021088/Qsf307

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHB 5263U

at Workshop m/s SMRT

of

Insured: SKH 1940H

Policy No. 5105692345 (23/11/2018 - 14/01/2020)

Claims No. MT/1072887-002


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SHB 5263U

Yr Regn: 10/oct/2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius 4

c.c 1796

Colour:

Maroon

A/C: Insured / Std / NI / NA

Sp. Reading

317655

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3F4303572290

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

195/65 R15

R:

195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

West lake

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

24/11/2019

D.O.I.

26/11/2019

Survey held at

SMRT

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

SKH 1940H: NA/AWA15018569/h4 DOA: 31/10/2015

T.P

SHB 5263U: NS/INC15003533/k3gy312 DOA: 08/03/2015

TAX/11/19/2116

SKH1940H.

RECEIVED 02 JAN 2020

Confirm with Poh Suan

Finalize \$ 1,333.98 @ 3 days, (P/P) \$ 3,805.41 Red - 74%

Date/Time, File Pass to?

02/01/20



: Prell. Report



: Final Report

1)

Typ: st

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

160

Transportation:

S + RS, SI

Photos

Others

TOTAL

160

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Rep. Form:

Lump Sum (P/P): \$ 1,333.98 P/P

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident
Vehicle No.(For Motor) Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5105692345		TAN ENG BEE	S1537638D	GPC	drive CLASSIC	SKH1940H	SKH1940H	23/11/2018	14/01/2020

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHB5263U
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Nov 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZRS094733
Chassis No.:	JTDKB3FU303572290
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	10 Oct 2017
First Registration Date:	10 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Oct 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	09 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,052.00
COE Rebate Amount:	\$24,944.00
Total Rebate Amount:	\$28,694.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 29 Nov 2019

OK

TP Claims against NTUC Income: Follow-Through Survey

Date : 02/01/2020

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	MT/1072887-002	SMRT TAXIS PTE LTD	SHB 5263U	SKH 1940H	24/11/2019	09:30	\$ 5,139.39	\$ 1,333.98

Oi Sun Pin (LKK Auto)

From: Oi Sun Pin (LKK Auto)
Sent: Tuesday, 31 December, 2019 10:41 AM
To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)
Subject: RE: SHB5263U

Dear Poh Suan,

Confirm the finalize amount \$1333.98. Repair day 3 days under part by part repair.

Thank you.

Best Regards,
Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) [<mailto:YeoPohsuan@smrt.com.sg>]
Sent: Thursday, 26 December, 2019 2:49 PM
To: Oi Sun Pin (LKK Auto)
Cc: SUR; CS A Team
Subject: SHB5263U

Hi Sun Pin,

Attached herewith the repair estimate of SHB 5263U having Case No: TAX/11/19/2116.

There is no change to the approved amount of \$1,333.98 @ 3 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)
Sent: Thursday, 26 December 2019 2:50 PM
To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)
Subject: Scan Data from FX-D421D6

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/11/2019 11:56
Date Of Accident	24/11/2019 09:35
Exact Location Of Accident	PIE TOWAWRDS CITY (LP 368)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5263U
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

Driver

Name of Driver	TAN LYE TECK
NRIC No	S1037961Z
Date Of Birth	29/09/1946
Occupation	OUTDOOR
Date Of Driving Pass	24/03/1971
Driving Experience	48 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG PIE TOWARDS CITY (NEAR LP 368) WITH 2 PASSENGERS (COUPLE AMERICAN CHINESE) ON BOARD. SUDDENLY I FELT AN IMPACT AT THE REAR PORTION OF MY TAXI. A VEHICLE SKP1940H HAD COLLIDED ONTO REAR RIGHT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKH1940H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIU JUN HAO
NRIC/Passport Number	
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

PIE towards City (LP 268)

A diagram showing two boxes, A and B, on a track. Box A is positioned above Box B. Above each box is an arrow pointing to the right, indicating the direction of movement. The track is represented by two vertical lines.

B-5KH1940H

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

I/We declare the foregoing particulars are true in every respect.

are the foreign

25.11.19

25/11/2010

Sketch Plan Pg. 2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Signature] 25-11-19

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature] 25/11/2019

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Case Details

Case Reference Number :

TAX/11/19/2116

Type of Repair : Accident Repair

Vehicle Registration Number : SHB5263U

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-9497-ID

Assigned By : Taxi Claims Manager
Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 24/11/2019 01:25 AM

Vehicle Age(In Months) : 25

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Check	X SVC
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92	Replace	/ SCH
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	1	11.00	11.00	25.00	8.25	Replace	1	8.25	Replace	/ NEC
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 1	1	3.80	3.80	25.00	2.85	Replace	1	2.85	Replace	/ Nec
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 2	1	3.80	3.80	25.00	2.85	Replace	1	2.85	Replace	/ Nec
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 3	1	3.80	3.80	25.00	2.85	Replace	1	2.85	Replace	/ Nec
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0	Check	X SVC
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	0	0	Not Give	X SVC
One Time Key In	Main			SEAL, RR BUMPER , RH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give	X SVC
One Time Key In	Main			SEAL, RR BUMPER , LH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give	X SVC

Total Spare Part Cost 3,883.39

Surveyor Total 863.97

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 3,883.39

Final Sur Total 863.97

SMRT Recommendation												Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	1	1.50	1.50	25.00	1.13	Replace	1	1.13	Replace	✓ Nec
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			FILLER, RR BUMPER, RH	1	119.90	119.90	25.00	89.93	Replace	1	0	Repair	✓ X R
One Time Key In	Main			FILLER, RR BUMPER, LH	1	119.90	119.90	25.00	89.93	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	25.00	90.00	Replace	2	90.00	Replace	✓ Nec
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	25.00	135.00	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			COVER, REAR FLOOR UNDER, RH	1	169.50	169.50	25.00	127.13	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			COVER, REAR FLOOR UNDER, LH	1	234.30	234.30	25.00	175.73	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			COVER, REAR FLOOR UNDER CENTER	1	222.60	222.60	25.00	166.95	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			ANTENNA, ELECTRICAL KEY	1	60.30	60.30	10.00	54.27	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP, RH	1	438.10	438.10	10.00	394.29	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP, LH	1	438.10	438.10	10.00	394.29	Replace	0	0	Not Give	✓ X Svc
One Time Key In	Main			LENS & BODY ASSY, RR BUMPER, RH	1	486.80	486.80	10.00	438.12	Replace	1	438.12	Replace	✓ CRU
One Time Key In	Main			LENS & BODY ASSY, RR BUMPER, LH	1	486.80	486.80	10.00	438.12	Replace	0	0	Not Give	✓ X Svc
Total Spare Part Cost									3,883.39	Surveyor Total 863.97				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									3,883.39	Final Sur Total 863.97				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			338.00	200.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR LEFT REAR PORTION	338.00	200	
Total:			338.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	
Total:			558.00	200.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0	
2	Main	TO REPLACE SUNDRY PARTS	100.00	20	
3	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
4	Main	TO WASH AND VACUUM	60.00	0	
Total:			360.00	40.00	

Summary

6051 80

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,863.39	863.97
Total Labour Cost	338.00	200.00
Total Spray Painting	558.00	200.00
Other	360.00	40.00
Overall Total	5,139.39	1,303.97
Lump Sum Repair Option		
Lump Sum Total	0.00	1,303.97
Surveyor Approved Amount		1,303.97
No of Repair Days*	5	3
Remarks		P/P Repair, Take before spray photo.

Estimator Assessment(\$)

Surveyor Assessment(\$)

Surveyor Name

Sun Pin (LKK)

Signature


3/12/19

Save

Clear

Survey Date

28/11/2019

Repair day - 3 days.

P/P Repair.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer



Signature:

Date:

Section A - Accident Details

Registration Number	SHB5263U
Case Reference Number	TAX/11/19/2116
Registration Date	10/10/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	TAN LYE TECK
Type of Accident	Head to Rear
Accident Date and Time	24/11/2019 9:25 AM
Accident Reported Date and Time	25/11/2019 12:04 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24104521
Special Instruction to ARC, if any	TP / DROVE IN/ NTUC - LKK
Prepared Date and Time	26/11/2019 6:13 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$338.00	\$200.00
Total Spray Cost	\$558.00	\$200.00
Total Spare Part Cost	\$3,883.39	\$893.98
Total Other Cost	\$360.00	\$40.00
TOTAL COST	\$5,139.39	\$1,333.98 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Fong Soon Loh	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	26/11/2019 6:52 PM	28/11/2019 3:55 PM
Signature		
Remarks	P/P Repair, Take before spray photo.	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63865592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 26/12/2019

User ID : PohSuan

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1912-0255	Invoice Number	
Quotation Date	17.12.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LEFT REAR PORTION	\$338.00	\$200.00
Total Labour	\$338.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$558.00	\$200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$360.00	\$40.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5202347030	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Check X
		5215947913	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace ✓
		5219147030	SEAL, RR BUMPER ARM, RH & LH	1.00	\$11.00	25.00	\$8.25	Replace	Replace ✓
		5246247030	PAD, RR BUMPER, RH & LH, 1	1.00	\$3.80	25.00	\$2.85	Replace	Replace ✓
		5246247020	PAD, RR BUMPER, RH & LH, 2	1.00	\$3.80	25.00	\$2.85	Replace	Replace ✓
		5246247010	PAD, RR BUMPER, RH & LH, 3	1.00	\$3.80	25.00	\$2.85	Replace	Replace ✓
		5257547040	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Check X
		5257647040	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Not Given X
		5259147050	SEAL, RR BUMPER, RH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given X
		5259247040	SEAL, RR BUMPER, LH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given X
		5216116010	CLIPS PIECE, FRT & RR BUMPER	1.00	\$1.50	25.00	\$1.13	Replace	Replace ✓
		5245347010	GUARD, RR BUMPER, LOWER	0.00	\$558.30	0.00	\$0.00	Replace	Not Given X
		5256547900	FILLER, RR BUMPER, RH	1.00	\$119.90	100.00	\$0.00	Replace	Repair ✓
		5256647900	FILLER, RR BUMPER, LH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given X
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace ✓
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given X

58398470 50	COVER, REAR FLOOR UNDER, RH	0.00	\$169.50	0.00	\$0.00	Replace	Not Given	X
58399470 30	COVER, REAR FLOOR UNDER, LH	0.00	\$234.30	0.00	\$0.00	Replace	Not Given	X
66259470 10	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	Replace	Not Given	X
89997301 00	ANTENNA, ELECTRICAL KEY	0.00	\$60.30	0.00	\$0.00	Replace	Not Given	X
81551472 81	LENS & BODY, REAR COMBINATION LAMP, RH	0.00	\$438.10	0.00	\$0.00	Replace	Not Given	X
81561471 51	LENS & BODY, REAR COMBINATION LAMP, LH	0.00	\$438.10	0.00	\$0.00	Replace	Not Given	X
81581470 10	LENS & BODY ASSY, RR BUMPER, RH	1.00	\$486.80	10.00	\$438.12	Replace	Replace	✓
81591470 10	LENS & BODY ASSY, RR BUMPER, LH	0.00	\$486.80	0.00	\$0.00	Replace	Not Given	X
Total			\$4,735.80		\$893.98			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

893.98
+ 200.00
+ 240.00

1333.98

P/P \$ 1333.98

3 days



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19021088/Qsf3e2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 21-01-2020

189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKH 1940H	Veh. Inspected	SHB 5263U
Policy No.	5105692345	Coverage (\$)	0.00
Claim No.	MT/1072887-002	Excess (\$)	0.00
Assign From		Assign Date	26/11/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU303572290	Colour	MAROON
Odometer	317655	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	WEST LAKE	5 mm
L/H Front Tyre	195/65 R15	WEST LAKE	5 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	24/11/2019	Inspection Date	26/11/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5263U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER, RR BUMPER ASSY (DISC 25%)	SCRATCHED	423.90	317.93
1	SEAL, RR BUMPER ARM, RH & LH (DISC 25%)	NECESSARY	11.00	8.25
1	PAD, RR BUMPER, RH & LH, 1 (DISC 25%)	NECESSARY	3.80	2.85
1	PAD, RR BUMPER, RH & LH, 2 (DISC 25%)	NECESSARY	3.80	2.85
1	PAD, RR BUMPER, RH & LH, 3 (DISC 25%)	NECESSARY	3.80	2.85
1	CLIPS PIECE, FRT & RR BUMPER (DISC 25%)	NECESSARY	1.50	1.13
1	LENS & BODY ASSY, RR BUMPER, RH (DISC 10%)	CRUMPLED	486.80	438.12
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	318.80	-
1	RETAINER, RR BUMPER, RH	SERVICEABLE	112.70	-
1	RETAINER, RR BUMPER, LH	SERVICEABLE	111.50	-
1	SEAL, RR BUMPER, RH	SERVICEABLE	85.20	-
1	SEAL, RR BUMPER, LH	SERVICEABLE	85.20	-
1	GUARD, RR BUMPER, LOWER	SERVICEABLE	558.30	-
1	FILLER, RR BUMPER, LH	SERVICEABLE	119.90	-
1	SENSOR REVERSE	SERVICEABLE	180.00	-
1	COVER, REAR FLOOR UNDER, RH	SERVICEABLE	169.50	-
1	COVER, REAR FLOOR UNDER, LH	SERVICEABLE	234.30	-
1	COVER, REAR FLOOR UNDER CENTER	SERVICEABLE	222.60	-
1	ANTENNA, ELECTRICAL KEY	SERVICEABLE	60.30	-
1	LENS & BODY, REAR COMBINATION LAMP, RH	SERVICEABLE	438.10	-
1	LENS & BODY, REAR COMBINATION LAMP, LH	SERVICEABLE	438.10	-
1	LENS & BODY ASSY, RR BUMPER, LH	SERVICEABLE	486.80	-
1	FILLER, RR BUMPER, RH	TO REPAIR SEE LABOUR	119.90	-
			4,795.80	893.98
LABOUR				
PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF FILLER, RR BUMPER, RH.			338.00	200.00
SPRAY PAINT.			558.00	200.00

Report Ref No. NS/INC19021088/Qsf3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	NOT NECESSARY	120.00	-
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			1,256.00	440.00
GRAND TOTAL			6,051.80	1,333.98
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,333.98

Report Ref No. NS/INC19021088/Qsf3e2

OI SUN PIN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.