55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP: 21071

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183

Reference : PA/OD/1413/2019/NS

Date : 29-Nov-19

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Regina Liem King In Address : 135 Sunset Way

#09-14

Singapore 597158

 Telephone
 : HP +65 97326036

 Type of Claim
 : Own Damage Claims

 Policy No.
 : 1900246291

 Vehicle No
 : SVE 435 V

Vehicle No : SKE 435 Y
Model Code - Audi 03 1 45 U

Model / Year : Audi Q3 1.4 S LINE TFSI S

Nov-19

Engine No : CZD 886385

Chassis No : WAUZZZF37L1012161

Date In .

Estimated By : Johnny Boo / Allan Wu

Accident Date : 26-Nov-19
Place of Accident : Newton Circus

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKE 435 Y

			Estimated	Surveyor's
S/N	Nature of Jobs		Charges	Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N	\$ 480.00	
2	To dismantle and renew front bumper and lhs front fender. Re-organise crash management components. Reinstall all parts removed.		\$ 2,400.00	500
3	To respray front bumper, front bumper lower spoiler, lhs front fender and both front wheel arch trims.		\$ 3,900.00	1925
4	To carry out diagnostic check.	S/N	\$ 192.00	
	TOTAL LABOUR CHARGES	•	\$ 6,972.00	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKE 435 Y

S/N Parts Description 1 FRONT BUMPER X R 2 FRONT BUMPER FIXING PARTS X S/NETT \$ 2,411.00 389.00	Remarks
1 FRONT BUMPER X R 5 2,411.00	
1 FRUNT BUMPER X Y	
S 389.00	
2 FRONT BUMPER FIXING PARTS A	
3 FRONT BUMPER CLOSING ELEMENT - LH X \$ 53.00	
4 MOLDING \$ 324.00	
5 FRONT BUMPER FRONT SPOILER & \$ 693.00	
6 FRONT BUMPER AIR GUIDE GRILLE - LH 🗶 \$ 139.00	
7 MOLDING-LH / \$ 150.00	
8 ULTRASOUND SENSOR SUPPORT - LH X \$ 24.00	
9 FRONT BUMPER GUIDE SECTION - LH X \$ 35.00	
10 FRONT PARKING AID SENSOR X \$ 231.00	
11 PARKING AID SENSOR SEAL RING / MC 4 \$ 12.00	
12 FRONT FENDER - LH \times R \$ 1,174.00	
13 FRONT FENDER ATTACHMENT PARTS 😾 \$ 57.00	
14 FRONT FENDER BRACE - LH 🗸 \$ 80.00	
15 SOUND ABS - LH UPPER 🗡 \$ 27.00	
16 FRONT WHEEL HOUSING LINER - LH X \$ 223.00	
17 WHEEL HOUSING LINER ATTACHMENT PARTS X \$ 635.00	
18 FRONT WHEEL COVER - LH / RH / MC 2 \$ 982.00	
19 SUNDRIES (\$ 300.00	
TOTAL SPARE PARTS : \$ 7,939.00	
TOTAL LABOUR CHARGES : \$ 6,972.00	
GRAND TOTAL : \$ 14,911.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost Liability

Remarks

99/11/19, 10.30 an : Steve (LKK) OD - Not Author (Re.) 3 chys

Please Note

This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Freudice" basis
- No illegal modification in is allowed
- Supplementary item(s. ust be insurveyed and is subject to final approximation insurance Company)

Admowledged by Repairer

Johnny Boo **Body Repair Manager** Allan Wu Claims Consultant