

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

JTJBAMCA502 007013

NEO SOON WAH

BLK 821 YISHUN ST 81

#04-646

S 760821

TPMS16.

None.

Date

:06.12.2019

Vehicle No

:SGD 7307 R

Make/Model

:TOYOTA LEXUS RX200T

Accident date

:28.11.2019

No	DESCRIPTION	Qty	Amount (\$)
<u>List Items</u>			
1	Rear windscreen rubber <i>new</i>	1	\$ 41.2 ✓
2	Rear tailgate <i>Dented</i>	1	\$ 2624.6 2453
3	Rear tailgate upper lock <i>new</i>	1	\$ 1071.4 x
4	Rear tailgate lower lock <i>new</i>	1	\$ 57.6 x
5	Rear tailgate shock absorber @ \$390.50 <i>new</i>	2	\$ 781 x
6	Rear tailgate inner cover <i>new</i>	1	\$ 761.6 x
7	Rear tailgate inner handle <i>new</i>	1	\$ 93.1 x
8	Rear tailgate inner side rubber @ \$409.00 <i>new</i>	2	\$ 818 x
9	Rear tailgate inner side rubber garnish @ \$414.30 <i>new</i>	2	\$ 828.6 x
10	Rear tailgate hinges @ \$148.50 <i>new</i>	2	\$ 297 x
11	Rear tailgate side reflector @ \$452.10 <i>new</i>	2	\$ 904.2 x
12	Rear tailgate centre emblem <i>new</i>	1	\$ 215.2 ✓
13	Rear tailgate Lexus emblem <i>new</i>	1	\$ 80.3 ✓
14	Rear tailgate RX emblem <i>new</i>	1	\$ } 82.5 ✓
15	Rear tailgate 200t emblem <i>new</i>	1	\$ }
16	Rear tailgate handle <i>new</i>	1	\$ 310.1 x
17	Rear tailgate weather strip <i>new</i>	1	\$ 486.2 x
18	Rear end panel <i>Dented</i>	1	\$ 875.6 ✓
19	Rear end panel inner top garnish <i>curled</i>	1	\$ 470.3 ✓
20	Rear bumper <i>Distorted</i>	1	\$ 1094.5 ✓
21	Rear bumper side holder @ \$127.90 <i>new</i>	2	\$ 255.8 ✓
22	Rear bumper side reflector @ \$65.80 <i>new</i>	2	\$ 131.6 ✓
23	Rear bumper lower centre garnish <i>new</i>	1	\$ 544.5 ✓
24	Rear bumper lower side garnish @ \$166.10 <i>new</i>	2	\$ 332.2 ✓
25	Rear bumper reinforcement <i>Best</i>	1	\$ 474.8 ✓
26	Rear bumper sponge <i>curled</i>	1	\$ 137.5 ✓
27	Rear bumper bracket @ \$48.40 <i>new</i>	2	\$ 96.8 x
28	Rear exhaust pipe chrome @ \$135.10 <i>new</i>	2	\$ 270.2 x
29	Rear bumper clips (1 set) <i>new</i>	1	\$ 66 30.
			\$ 14202.4
Less 10% Disc			\$ 1420.24
Total			\$ 12782.16

7219

649710

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

NEO SOON WAH

BLK 821 YISHUN ST 81

#04-646

S 760821

Date :06.12.2019

Vehicle No :SGD 7307 R

Make/Model :TOYOTA LEXUS RX200T

Accident date :28.11.2019

No	DESCRIPTION	Qty	Amount (\$)
----	-------------	-----	-------------

Special Nett Items

1	Rear tailgate camera <i>NE Rev</i>	1	\$ 800 ^x
2	Rear bumper reverse sensor @ \$467.50 <i>2 pieces dyed</i>	4	\$ 1870 520.
3	Rear tailgate lock sensor <i>Carb'd</i>	1	\$ 181.5 [✓]
		Total	\$ 2851.5

Labour Cost

1 To supply rear windscreen sealant	\$ 50 ✓
2 To supply rear end panel sealant	\$ 200 60
3 Remove & reinstall rear windscreen	\$ 150 60
4 Remove & reinstall bootlid inner garnish	\$ 200 80
5 Remove & reinstall reverse sensor	\$ 150 60
6 Remove & reinstall exhaust pipe	2020 \$ 150 x
7 Remove ,replace & repair consistent to the accident	\$ 1800 800
8 Respray painting	\$ 1400 850
9 Tuff kote	\$ 150 60
Total	\$ 4250

Grand Total \$ 19883.66

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 9148.45
L/S: 7.3K
06 Days.

1st Feb 2020 3000