

PAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT DOOR LH			
2	1	FRONT DOOR SIDE MIRROR LH	757.20	-20.00	605.76 <i>Rx dd</i>
3	1	FRONT DOOR SIDE MIRROR MOTOR LH	527.10	-20.00	421.68 <i>Cua</i>
4	1	FRONT DOOR SIDE MIRROR GLASS LH	384.90	-20.00	307.92 <i>500 h</i>
5	1	FRONT DOOR SIDE MIRROR COVER LH	214.30	-20.00	171.44 <i>mis</i>
6	1	FRONT DOOR SIDE MIRROR SIGNAL LAMP LH	108.60	-20.00	86.88 <i>dx</i>
			119.40	-20.00	95.52
7	1	FRONT FENDER LH	435.80	-20.00	348.64 <i>xR</i>
8	1	FRONT FENDER QUARTER GLASS LH	358.60	-20.00	286.88 <i>Cua</i>
9	1	FRONT FENDER QUARTER GLASS GARNISH LH	112.80	-20.00	90.24 <i>xR</i>
10	1	FRONT FENDER QUARTER GLASS MOULDING LH	58.60	-20.00	46.88 <i>neu</i>
11	1	REAR DOOR LH	799.50	-20.00	639.60 <i>dd</i>
12	1	REAR FENDER LH	0.00	0.00	0.00 <i>Rx</i>
Total Parts (\$\$)					3,101.44

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT FENDER QUARTER GLASS SEALANT LH	35.00	0.00	35.00 <i>neu</i>
Sub Total (\$\$)					35.00

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Dismantle and Refit Front Fender Glass.	60.00	0.00	60.00 <i>40</i>
2	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	680.00	0.00	680.00 <i>500</i>
Gross Labour Cost (\$\$)					740.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	800.00	0.00	800.00 <i>650</i>
Gross Labour Cost (\$\$)					800.00

< END OF ESTIMATES >

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Estimate Report

Block 6 Woodlands Road 399F, Yew Tee Industrial Estate
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : INDIA INTERNATIONAL INSURANCE PTE LTD

PARTICULARS OF CLAIM

Claim Type:	TP	Ref. No:	YTHQ/TP/1911/014
Policy No:	5079341740-03	Date of Loss:	22/11/2019
Vehicle Reg. No.:	SJL4939J	Driveable?	no
Driver Age:		Third Party Vehicle No.:	SHC8934S
Any Injuries?	no	Contact No:	
Insured/Claimant:	NURULAFIAH BINTE NIZLAN	Driver:	KAMAL ADAM LITAK

Make/Model:	Honda, JAZZ - GK3 / GK5	Vehicle Reg. Date:	28 Nov 2008
Vehicle Colour:	WHITE	Engine Number:	L13Z11005819
Chassis No:	JHMGE68509S205816	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	7

Description of Accident/loss: COLLISION-OPENING DOOR OF VEHICLE
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

COST OF CLAIMS

	Amount
Parts	3,101.44
Miscellaneous Items	35.00
Labour	740.00
Paintwork Labour	800.00
Towing	0.00

Gross Total(S\$):	4,676.44
GST 7.00%(S\$):	327.35
Nett Amount(S\$):	5,003.79

This claim is handled by: SHUYI

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanphik 97495749/
'WP' 67418437

29/4/19 @ 1130

Lumpsum

Resurvey after repair

tanphik@lkkauto.com
05 days.