



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

TANG HEE KHOON
BLK 203A COMPASSVALE ROAD #07-19
SINGAPORE 541203

Attention : THE OWNER
Contact : 97911162

Estimate : ES006852

Date : 29/11/2019
Vehicle Num. : SLE1444C
Make/Model : BMW 730LI-2011
Chassis/Eng# : WBAKB22080C951196/04397837N52I
Accident Date : 20/11/2019
Claim No. :
Reference :
Policy No. :

Not Authorized
11/2/19
Resurvey After Repair
2 days

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	NETT ITEMS :		
2.	6	REAR BUMPER	12.50	1,876.00 ✓
3.	1	REAR BUMPER CLIP		75.00 ✓
4.	1	REAR BUMPER REINFORCEMENT		738.00 ?
5.	1	REAR BUMPER CENTRE GUIDE		366.00 ?
6.	2	REAR BUMPER LOWER INNER ADAPTOR		421.00 ?
7.	2	REAR BUMPER BRACKET	186.00	372.00 X
8.	2	REAR BUMPER SIDE RETAINER	267.00	534.00 X
9.	1	REVERSE SENSOR	263.70	527.40 ?
		REAR END PANEL		871.00 X
Nett Total S\$:				5,780.40
5.00% Discount S\$:				289.02
				5,491.38
LABOUR :				
RUST PROOFING TREATMENT				100.00 X
SPRAY PAINT DAMAGED AREA AFFECTED				900.00 300d
TO CUT OFF REAR END PANEL, KNOCK AND STRAIGHTEN REAR				
CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS				950.00 250d
Labour Total S\$:				1,950.00

SingDollars : Seven Thousand Four Hundred Forty-One & Cents Thirty-Eight Only

Total S\$: 7,441.38

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: