

		PARTS TOTAL		\$ 5,226.71	
SPECIAL NETT			QTY	PRICE	
1	REAR WINDSCREEN SEALANT	11X	1	\$ 120.00	X
2	TAILGATE INNER BOARD CLIPS	11X	10	\$ 100.00	X
3	TAILGATE RUBBER PROTECTOR	11X	1	\$ 850.00	X
4	TAIL LAMP CLIPS	11X	4	\$ 80.00	X
5	REAR CARPLATE	11X	1	\$ 120.00	X
6	REAR CARPLATE FRAME	11X	1	\$ 120.00	X
7	REAR BUMPER CLIPS	11X	10	\$ 100.00	45
8	REAR BUMPER REFLECTOR (L+R)	0/5 CRG 280 1set	2	\$ 1,600.00	280
9	REAR BUMPER REVERSE SENSOR	11X	2	\$ 300.00	X
10	REAR FENDER SEALANT	11X	1	\$ 120.00	X
11	REAR FENDER QUARTER WINDOW SEALANT	11X	1	\$ 120.00	X
12	REAR FENDER INNER TRIM CLIPS	11X	10	\$ 100.00	X
13	REAR FENDER COWLING CLIPS	11X	10	\$ 100.00	X
14	REAR QUARTER PANEL SEALANT	11X	1	\$ 120.00	X
15	END PANEL SEALANT	11X	1	\$ 120.00	X
16	SPAREWHEEL PANEL SEALANT	11X	1	\$ 120.00	X
SPECIAL NETT TOTAL				\$ 4,190.00	
LABOUR			QTY	PRICE	
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN	300	1	\$ 3,300.00	
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	400	1	\$ 2,200.00	
3	TO RUST PROOF ACCIDENT AFFECTED AREA	11X	1	\$ 250.00	
4	TO RNR REAR WINDSCREEN	11X	1	\$ 400.00	
5	TO RNR REAR FENDER QUARTER WINDOW	11X	1	\$ 400.00	
6	TO RNR UPHOSTERY, GARNISH AND ATTACHMENT PARTS	11X	1	\$ 400.00	
7	TO RNR REVERSE SENSOR & CHECK FUNCTION.	50	1	\$ 150.00	
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	11X	1	\$ 250.00	
9	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION	20	1	\$ 150.00	
10	TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE.		1	\$ 400.00	
11	TO DO WATER LEAK TEST.	11X	1	\$ 120.00	
TOTAL				\$ 8,020.00	
GRAND TOTAL COST				\$ 17,436.71	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PAGE 2 OF 2

P-1214.60
252
P-910.95
S.N- 32500
L- 770.00
2025.95
1604.80



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060
VEHICLE NUM: SLJ 4436 E
MAKE & MODEL: TOYOTA WISH
MILEAGE:
TYRE:
CHASSIS NUM:

Not Authorized
N/A
29/11/18
Tehyphie Attyy

2/s#1600

3 day

ATTN:			QTY	PRICE	
NO.	DESCRIPTION - PARTS				
1	REAR WINDSCREEN MOULDING	11 X	1		X
2	TAILGATE	11 X	1		X
3	TAILGATE LOGO (TOYOTA)	11 X	1		X
4	TAILGATE EMBLEM (VALVE MATIC)	11 X	1		X
5	TAILGATE LAMP (L+R)	0/scr 1/c X	2		X
6	TAILGATE HANDLE CHROME	11 X	1		X
7	TAILGATE CARPLATE LAMP (L+R)	11 X	2		X
8	TAILGATE HANDLE SWITCH	11 X	1		X
9	TAILGATE LOCK	11 X	1		X
10	TAILGATE LOCK CATCH	11 X	1		X
11	TAILGATE INNER BOARD	11 X	1		X
12	TAILGATE STOPPER (L+R)	11 X	2		X
13	TAILGATE WEATHERSTRIP	11 X	1		X
14	REAR BUMPER	Deep cut ✓	1	\$ 891.70	✓
15	REAR BUMPER RETAINER (L+R)	0/scr 1/c	2	\$ 131.40	1/c
16	REAR BUMPER REINFORCEMENT BAR	11 X	1	\$ 633.70	X
17	REAR BUMPER BRACKET (L+R)	11 X	2	\$ 150.00	X
18	REAR BUMPER BEAM	11 X	1	\$ 178.60	X
19	REAR BUMPER SPONGE	11 X	1	\$ 272.90	X
20	TAIL LAMP (RH)	Scr ✓	1	\$ 497.80	✓
21	TAIL LAMP PANEL (RH)	11 X	1	\$ 182.25	X
22	REAR FENDER (RH)	11 X	1	\$ 1,456.80	X
23	REAR FENDER QUARTER WINDOW MOULDING (RH)	11 X	1	\$ 415.00	X
24	REAR FENDER INNER TRIM UPPER (RH)	11 X	1	\$ 442.10	X
25	REAR FENDER INNER TRIM LOWER (RH)	11 X	1	\$ 798.10	X
26	REAR FENDER AIR VENT (RH)	11 X	1	\$ 76.80	X
27	REAR FENDER COWLING (RH)	11 X	1	\$ 85.00	X
28	REAR FENDER MUDFLAP (RH)	11 X	1	\$ 97.10	X
29	REAR QUARTER PANEL (RH)	11 X	1	\$ 659.70	X
30	END PANEL	11 X	1		X
31	END PANEL TOP GARNISH	11 X	1		X
32	SPAREWHEEL PANEL	11 X	1		X
33	SPAREWHEEL PANEL TOP BOARD	11 X	1		X
34	EXHAUST PIPE	11 X	1		X
35	EXHAUST GASKET	11 X	1		X
36	EXHAUST BRACKET (L+R)	11 X	2		X
37	EXHAUST HEAT SHIELD	11 X	1		X
SUBTOTAL				\$ 6,968.95	
LESS 25%				\$ 1,742.24	