

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

Not Authorized

26/11/2019

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA NOAH 1.8X - SJV3335E

1pc	rear tailgate	<i>Ry</i> \$ 1,712.85 ✓
2pcs	rear tailgate hinge @\$178.10	\$ <i>Ry</i> 356.20 ✓
1pc	rear tailgate "HYBRID" emblem	\$ <i>me</i> 132.25 ✓
1pc	rear tailgate windscreen glass	<i>Shatter</i> \$ 1,217.85 ✓
1pc	rear tailgate windscreen moulding	<i>me</i> \$ 172.80 ✓
1pc	rear tailgate outer chrome	<i>CM</i> \$ 581.90 ✓
1pc	rear tailgate outer door switch	<i>Tn</i> \$ 181.90 ✓
1pc	rear tailgate "TOYOTA" logo	<i>me</i> \$ 121.10 ✓
2pcs	rear tailgate number plate lamp @\$121.40	<i>C</i> \$ 242.80 ?
1pc	rear tailgate inner lock	\$ <i>Tn</i> 581.90 ✓
1pc	rear tailgate inner rubber	\$ <i>Gr</i> 371.85 ✓
1pc	rear tailgate inner garnish	\$ <i>Bu</i> 371.75 ✓
2pcs	rear tailgate inner side garnish @\$289.90	\$ <i>D17</i> 579.80 ✓
1pc	rear tailgate inner top garnish	<i>D17</i> \$ 271.85 ✓
2pcs	rear tailgate inner stopper @\$44.45	\$ <i>Tn</i> 88.90 ✓
1pc	rear tailgate inner handle garnish	\$ 121.10 ?
2pcs	rear taillamp @\$781.55	<i>m3cm</i> \$ 1,563.10 ✓
2pcs	rear taillamp panel @\$375.85	\$ <i>Ry</i> 751.70 ✓
2pcs	rear taillamp panel inner panel @\$371.85	\$ <i>Ry</i> 743.70 ✓
2pcs	rear taillamp lower garnish @\$371.85	\$ <i>Ry</i> 743.70 ✓
2pcs	rear taillamp lower garnish side retainer @\$172.25	\$ <i>D17</i> 344.50 ✓
2pcs	rear taillamp lower garnish stopper @\$43.50	\$ <i>me</i> 87.00 ✓
1pc	rear bumper	<i>Ry</i> \$ 1,217.45 ✓
2pcs	rear bumper side retainer @\$172.10	<i>D17</i> \$ 344.20 ✓
2pcs	rear bumper side reflector @\$181.90	\$ <i>Bu</i> 363.80 ✓
1pc	rear bumper towing cover	\$ <i>D17</i> 43.50 ✓
10pcs	rear bumper clip @\$5.00	\$ <i>me</i> 50.00 ✓
1pc	rear end panel	<i>Ry</i> \$ 781.10 ✓
1pc	rear end panel inner garnish	<i>CM</i> \$ 378.85 ✓
1pc	rear end panel inner sensor	\$ <i>Bu</i> 381.50 ✓
1pc	rear end panel outer sensor	\$ <i>Bu</i> 381.50 ✓
1pc	rear end panel outer hardness	<i>Tn</i> \$ 1,217.10 ✓
1pc	rear floor panel	<i>Ry</i> \$ 972.10 ✓
1pc	rear floor panel inner trim	<i>Tn</i> \$ 581.90 ✓
1pc	rear floor panel top board trim	<i>Return</i> \$ 1,238.00 ✓
balance c/f		\$ 19,291.50



輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

26/11/2019

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA NOAH 1.8X - SJV3335E

	balance b/f		\$ 19,291.50	
1pc	rear floor panel battery garnish	\$ <i>Del</i>	121.10	✓
5pcs	rear floor panel panel stopper rubber @\$43.50	\$	217.50	?
2pcs	rear seat assy @\$2850.50	<i>Del/Bu</i>	\$ 5,701.00	✓
2pcs	rear seat side garnish @\$371.50	\$	743.00	?
2pcs	rear fender @\$1218.50	<i>Ry/Bu</i>	\$ 2,437.00	✓
2pcs	rear fender top panel @\$581.10	\$	1,162.20	?
2pcs	rear fender inner garnish @\$731.35	<i>Return</i>	\$ 1,462.70	✓
2pcs	rear fender inner holder bracket @\$137.75	\$	275.50	?
1pc	roof top panel	<i>R</i>	\$ 1,712.50	X
1pc	roof top inner rear panel	\$ <i>R</i>	581.50	X
2pcs	rear door @\$1512.50	\$ <i>R</i>	3,025.00	X
4pcs	rear door firm sticker @\$121.50	\$ <i>An</i>	486.00	X
1pc	rear HYBRID battery	\$	13,800.50	?
1pc	front bonnet	<i>Bu</i>	\$ 781.90	✓
2pcs	front bonnet hinge @\$171.45	\$ <i>Del</i>	342.90	✓
1pc	front bonnet outer garnish	\$ <i>Buy</i>	375.50	✓
1pc	front bonnet outer garnish chrome	\$ <i>Ma</i>	281.90	✓
1pc	front bonnet inner cardboard	\$ <i>Sn</i>	377.10	X
8pcs	front bonnet inner cardboard clip @\$5.00	\$ <i>an</i>	40.00	X
1pc	front bonnet inner lock	\$ <i>Ry</i>	282.10	✓
2pcs	front bonnet inner stopper @\$43.10	\$ <i>Sn</i>	86.20	X
1pc	front wiper garnish	\$	374.10	?
2pcs	front wiper garnish side garnish @\$123.05	\$	246.10	?
2pcs	front windscreen side moulding @\$278.85	\$	557.70	?
2pcs	front headlamp @\$2751.10	<i>My Bu</i>	\$ 5,502.20	✓
2pcs	front headlamp panel @\$374.45	<i>Bu</i>	\$ 748.90	✓
2pcs	front headlamp garnish @\$289.90	<i>CM</i>	\$ 579.80	✓
1pc	front centre grille	<i>CM</i>	\$ 581.10	✓
3pcs	front centre grille outer garnish @\$231.31	<i>CM</i>	\$ 693.93	✓
3pcs	front centre grille outer garnish chrome @\$181.85	<i>Ma</i>	\$ 545.55	✓
1pc	front centre grille logo	\$ <i>Ma</i>	271.10	✓
1pc	front centre grille top garnish	\$ <i>Del</i>	381.50	✓
8pcs	front centre grille top garnish clip @\$5.00	\$ <i>Ma</i>	40.00	✓
2pcs	front centre grille side garnish @\$174.45	\$ <i>Ma</i>	348.90	✓
	balance c/f		\$ 64,455.48	



輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

26/11/2019

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA NOAH 1.8X - SJV3335E

	balance b/f		\$ 64,455.48
1pc	front bumper	B1	\$ 1,217.85 ✓
2pcs	front bumper side retainer @\$172.10	\$ D11	344.20 ✓
2pcs	front bumper fog lamp cover @\$181.90	SL	\$ 363.80 ✓
1pc	front bumper sponge	NSP	\$ 172.75 X
1pc	front bumper reinforcement	\$ B1	371.85 ✓
1pc	front bumper lower grille	\$ D11	271.85 ✓
1pc	front support top panel	\$ B1	281.10 ✓
2pcs	front support side panel @\$271.50	\$ B1	543.00 ✓
2pcs	front support side panel garnish @\$172.10	\$	344.20 ?
1pc	front support panel centre pillar	\$ B1	258.50 ✓
1pc	front support panel lower panel	\$	272.50 ?
1pc	front support hardness	\$	5,820.80 ?
2pcs	front horn @\$181.90	\$ B1	363.80 ✓
1pc	front buzzer	\$ D11	172.10 ?
1pc	front air-con condensor	pu	\$ 1,217.45 ✓
1pc	front air-con condensor pipe 1	\$	281.90 ?
1pc	front air-con condensor pipe 2	\$	290.20 ?
1pc	front air-con condensor fan	\$	371.85 ?
1pc	front air-con condensor fan motor	\$	581.90 ?
1pc	front HYBRID radiator	\$	972.10 ?
1pc	front HYBRID radiator spare tank	\$	281.90 ?
1pc	front HYBRID radiator spare tank hose	\$	171.85 ?
1pc	front HYBRID inverter	\$	16,500.25 ?
1pc	front radiator	\$	1,217.85 ?
1pc	front radiator top hose	\$	172.10 ?
1pc	front radiator lower hose	\$	182.10 ?
1pc	front radiator cowling	\$	252.10 ?
1pc	front radiator cowling motor	\$	561.60 ?
1pc	front radiator cowling motor fan	\$	370.50 ?
1pc	front radiator spare tank	\$ D11	271.70 ✓
1pc	front air cleaner tank	\$	581.50 ?
1pc	front air cleaner tank cover	\$	181.50 ?
1pc	front air cleaner tank spare tank	\$	371.85 ?
1pc	front air cleaner spare tank hose	\$	123.05 ?
1pc	front air cleaner filter	\$	75.20 ?

less 25%

balance c/f



\$ 100,284.23

\$ 25,071.06

\$ 75,213.17

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

26/11/2019

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA NOAH 1.8X - SJV3335E

	balance b/f		\$ 75,213.17
1pc	rear battery	s.nett	\$ 180.00 ?
1set	rear parking sensor	Shon s.nett	\$ 280.00 ✓
2set	rear & front number plate & casing	s.nett	\$ 100.00 90.00
	sealant	s.nett	\$ 180.00
	towing	s.nett	\$ 100.00 60.00
	remove & refit rear cushion	\$	240.00 160.00
	remove & refit rear windscreen glass & rear fender glass	\$	360.00
	remove & refit rear door glass	\$	120.00
	remove & refit roof top tirm	\$	180.00
	remove & refit air-con & radiator	\$	220.00 160.00
	remove & refit front HYBRID inverter	\$	580.00 ?
	reprogramme ECU & HYBRID system	\$	450.00 250.00
	wiring	\$	350.00
	tuffkote	\$	450.00
	spray painting	\$	3,500.00
	labour charges	\$	3,500.00
	Total	\$	86,003.17

remark:

almost no parts in singapore, estimate waiting date
3 to 4 months.



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Efficient Towing Services

403 Sin Ming Avenue #13-307, Sin Ming Garden, Singapore 570403

Ah Di Mobile: 8588 8877

Email: efficienttowing.sg@gmail.com

Business Reg. No.: 53349344K

NO. 41817

Date: 26/11/19

CASH SALE / JOB ORDER

Messrs: Cash
车牌 SV 3335 E 车型 Toyota
Vehicle No. SV 3335 E Model No. Toyota
时间 (日/夜) 04-02 联络号码 9074038
Time (day/night): 04-02 Contact No: 9074038
由 Toa Payh
Location: Toa Payh
到 04-02 Autocare
To: 04-02 Autocare
银额 1001 其他 Autocare
Cash \$ 1001 Others: Autocare
经手人 Autocare
Authorised By: Autocare Tow Truck Driver Name: Autocare

- ☐ Jump Start/Changing of battery
- ☐ Tyre Replacement
- ☒ Accident/Breakdown
- ☐ Multi/Basement
- ☐ With Load/Cargo Box
- ☒ King Dolly
- ☐ Transport Charge
- ☐ Low Body Kit
- ☐ Door Opening Service
- ☐ Crane Up/Winch Out
- ☐ Collect Doc/Key
- ☐ Repo
- ☐ Woodlands and Tuas Checkpoint

注意: 本公司对所拖之车辆, 在進行中如有任何损失或破坏, 一概由车主自行负责。

Note: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

E. & O. E.