

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19021159/FBA3Q2

**Date:** 18/03/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**  
**Vehicle No :** SHD1112M **Insured Vehicle No :** SKH4852J

**Date of Loss:** 25/10/2019 **Nature of Claim:** TP **Claim No:** 1558988561SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHD1112M</b>	Engine No:	D4FDFH314492
Make & Model:	KIA OPTIMA, 1.7 D (A)	Chassis No:	KNAGM414MF5658403
Reg. Date:	15/01/2016 (Man. Year: 2015)	Odometer:	347994 km
Colour:	Silver		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	Achilles 6 mm	Rear Left Side:	Achilles 7 mm
Front Right Side:	Achilles 6 mm	Rear Right Side:	Achilles 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,046.50	204.00	2,842.50	93.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,840.00	720.00	2,120.00	74.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$)</b>	<b>5,886.50</b>	<b>924.00</b>	<b>4,962.50</b>	<b>84.30</b>
<b>Approved Total (Overridden) (\$)</b>		<b>700.00</b>		
<b>(S\$)</b>	5,886.50	700.00	5,186.50	88.11
<b>+ GST 7.00/7.00% (S\$)</b>	412.06	49.00	363.06	88.11
<b>Nett Amount (S\$)</b>	<b>6,298.56</b>	<b>749.00</b>	<b>5,549.56</b>	<b>88.11</b>
<b>+ Loss of Use (2.0 x S\$50.00/day) (S\$)</b>		100.00		
<b>+ Car Rental (2.0 x S\$99.51/day) (S\$)</b>		199.02		
<b>(S\$)</b>		1,048.02		
<b>Liabile Amount (50.00%) (S\$)</b>		<b>524.01</b>		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>526.01</b>		
<b>Global Sum Settlement (S\$)</b>		<b>520.00</b>		

### INSPECTION

Date of Assignment: 28/11/2019

Date Inspected: 28/11/2019 Inspected At:

Premier Automotive Services Pte Ltd  
(HQ)  
23 Changi South Ave 2, #01-02  
Singapore 486443

Estimated Period of Repair: 2.0 days

---

**Adjuster:** PARASURAM SHANMUGAM

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT N/S HEAD LAMP	Repair	1,028.00 FL	*- FL
2	1		*FRONT BUMPER	Repair	531.00 FL	*- FL
3	1		*FRONT BUMPER EMBLEM	Necessary	44.00 FL	*44.00 FL
4	1		*FRONT BUMPER N/S SIDE RETAINER	Not Necessary	16.00 FL	*- FL
5	1		*FRONT N/S FENDER	Repair	384.00 FL	*- FL
6	1		*FRONT N/S FENDER INNER SHIELD	Not Necessary	120.00 FL	*- FL
7	1		*N/S MIRROR ASSY	Repair	590.00 FL	*- FL
8	2		*FRONT & REAR N/S WHEEL COVER	Scratched (1 PCS ONLY)	232.00 FL	*116.00 FL
9	1		*SET FRONT BUMPER CLIPS	Not Necessary	48.00 FS	*- FS
10	1		*FRONT N/S FENDER STICKER	Necessary	30.00 FS	*30.00 FS
11	1		*SET FRONT N/S FENDER INNER SHIELD CLIPS	Not Necessary	28.00 FS	*- FS
12	1		*SET N/S DOOR STICKERS	Not Necessary	100.00 FS	*- FS
13	1		*REAR N/S FENDER STICKER	Not Necessary	60.00 FS	*- FS
14	1		*REAR BUMPER TOP PROTECTOR	Not Necessary	80.00 FS	*- FS
15	1		*SUNDRY	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,341.00</b>	<b>220.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	294.50	16.00

<b>Total Parts (\$\$)</b>	<b>3,046.50</b>	<b>204.00</b>
---------------------------	-----------------	---------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CHECK WHEEL ALIGNMENT -FRONT & REAR	New	160.00	0.00
2	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	0.00
3	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE FRONT N/S DOOR ,REAR N/S DOOR ,REAR N/S FENDER ,REAR BUMPER ETC	New	950.00	360.00
4	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,FRONT N/S FENDER ,N/S SIDE MIRROR ,FRONT N/S DOOR,REAR N/S DOOR ,REAR N/S FENDER REAR BUMPER	New	1,400.00	360.00
5	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	150.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>2,840.00</b>	<b>720.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >