

114-JU PIP

COMFORTDELGRO ENGINEERING PTE LTD

Date: 28.11.2019

Time: 17:17:59

Page: 1

WIP

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305357820
REGN NO : SHA4645M
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 22.12.2016
DATE/TIME IN : 28.11.2019 15:10
ACCIDENT DATE : 27.11.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT	Notes
1		553.00	20.00	442.40	TR CR ✓
10 L		22.00	20.00	17.60	TR nec ✓
1		228.00	20.00	182.40	scr ✓
1 N		50.00	2.00	50.00	TR nec ✓ (CSN)
1		103.50	20.00	82.80	? Xnn
				SUB-TOTAL	: 775.20

JOB NATURE

0000 PB	PANEL BEATING	300.00	\$240	✓
0001 SP	SPRAYPAINT CHARGE	200.00	\$	✓
0002 17-01	CHECK ALL LIGHTING	50.00	\$20	✓
0003 20-05	RENEW ADVERTISEMENT BUMPER STICKER	50.00	nec	✓
0004 20-05	RENEW ADVERTISEMENT FENDER STICKER-	200.00	nec	✓
0005 L	REMOVE/REFIX REVERSE SENSOR	80.00	\$30	✓

Parts : \$803
Parts - 20% discount : \$642.40
SIN : \$50
Labour : \$740
Total : \$1,432.40 (P/P X 2 days)

Ram (LKK)
29/11/19
2 repair days
\$740
bef paint photo
Parasurama LKka.com
8862277814

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305357820
 REGN NO : SHA4645M
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 22.12.2016
 DATE/TIME IN : 28.11.2019 15:10
 ACCIDENT DATE : 27.11.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 880.00

TOTAL : 1,655.20

Jumani

MVA NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: