					COMFORTDELGRO ENGINEERING			
Our J	ob Ref		357715	- Sla	Comfo	rtDelGro Engineering Pte Ltd		
Date		: 9. De	c. 2019	. circur	59 Loy Fax: 6	ng Drive Singapore 508969 46 8156		
FINA	LIZATIO	ON FORM	10	ciran star				
То	*	l	KK		Fax:			
Attn			RAM					
	le Reg	No. : SHB4	948J	Date	of Accident:	28. Nov. 2019		
			ne repairs of the at	ove-mentioned	vehicle are as	follows:-		
1.	The re	epair job shall bill	to:	AIG		GBG5680T		
2.	The fi	nalized amount st	nall be:					
	(a)	Spare Parts afte	r List discount					
	(b)	Labour Charges						
	. ,	Total for Part-B	it					
	(c.)	Lumpsum Repai Total for Lumpsu Final Lumpsum	ım repair cost after	Less:		\$1,700.00		
3. 4.	We si	ated normal perional treat the about 7 working days	ve amount as Co		rking days.	is no reply from you		
5.	Thank	you for your ass	istance.	We fina	stimates and			
	Signa	turo :	L.M	Sic	Signature:			
	Name		Larry Ng	_	me :	Ram		
	Tel : 6214 8316		6	— Da	-	9/12/19		
	Fax	6546 8156		_				
For C	Official	Use Only						
		Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks		
1. R	Rental Rate P/Day			YES				
Loss of Income Paid								
3. S	urvey F	ees						
4. LTA Search Fee			\$7.49					
		ees (on behalf if applicable)						
	verrun							
Rema	arks:							

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

EHICLE NO : SHB4948J

3/1045403

DATE: 28. Nov. 2019

MAKE : HYUNDAI

EL	: 140	DOA:	28. Nov. 2019	AIG
Qty	Parts Description/ Labour	Туре	Unit Price	Amount
~-1	1 Rear Bumper & Buc			\$553.00
	10 Rear Bumper Clips vec		\$2.20	\$22.00
	1 Rear Bumper Sponge Cva			\$103.50
	1 Rear Bumper Reinforcement 7 XNN			\$428.40
	1 Rear Bumper Undercover Scv			\$228.00
	1 Rear Bumper Reflector – RH 6			\$32.00
	1 Boot Lid i40 emblem nec			\$27.90
	1 Boot Lid CRDI emblem vec			\$27.90
	1 Boot Lid H emblem NeC			\$28.70
	1 Boot Lid Lower Garnish ★(化)			\$227.90
	SUB TOTAL		- Smatter o	\$1,679.30
	LESS 20%			\$335.86
	DISCOUNTED TOTAL			\$1,343.44
	1 Comfort Doloro Sticker 205			\$15.00
	1 Comfort Delgro Sticker NCC			\$15.00
	1 Comfort Tel No. Nec			
	1 Rear Bumper Rubber Mat nec			\$50.00
	1 Reverse Sensor XXX			\$135.70
	1 Advertisement – Rear Bumper vec		¢100.00	\$50.00
	2 Advertisement – Rear Fenders Nec		\$100.00	\$200.00
	1 Advertisement – Boot ne			\$100.00
	Labour Charge	Pay	19 1100mm 19 1100mm att repair proto att repair proto 22778 ml	\$565.70
	1 Panel Beating	100	119 1100	\$840.00
	1 Spray Painting Charge	29 11	1005 100	\$500.00
	1 Tuff Kote	2 0	In any bu	OM \$80.00
	1 Wiring Charge	Zver	attrop outo.	\$60.00
	1 Remove/refix Reverse Sensor	(15)	Queen	\$100.00
	1		rame ne	
หอ	TOTAL LABOUR	poras	22118	\$1,580.00
Nã	ESTIMATE TOTAL	Q.C		\$3,489.14