

NGS AUTOMOTIVE

Blk 10 Ang Mo Kio Ind. Pk 2a #02-01 AMK AutoPoint Singapore 568047
Tel: 64815727 Fax: 64815772 Email: evelyn191ngsautomotive@gmail.com
Reg No.: 53405718K

QUOTATION

No. : AQT-0004

INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOU BLDG
SINGAPORE 049711

TEL : 6347 6100

FAX :

Your Ref. :

Our Ref : AQT-004/SMD6423

C. C. :

Date : 27-11-2019

Page : 1 of 2

Description	Qty	U/ Price S\$	Amount S\$
ACCIDENT ON 26/11/2019@07:15 INVOLVING SMD6423Z & SKX4568X ALONG FERNVALE LINK CLAIMS AGAINST SKX4568X (INDIA INT'L) REPLACEMENT PART: HD SHUTTLE <i>Not Authorise Repair By paint 4 days</i>			
REAR BOOT LID	1	1,131.00	1,131.00
REAR BOOT RUBBER	1	146.30	146.30
REAR BUMPER	1	936.00	936.00
REAR BUMPER RETAINER LH	1	30.00	30.00
SubTotal			2,243.30
LESS 20%	1	226.20	226.20
PARKING SENSOR S.NETT	1	280.00	280.00
LOGO 'SHUTTLE' S.NETT	1	63.00	63.00
LOGO 'HYBRID' S.NETT	1	75.00	75.00
LOGO 'BADGE' S.NETT	1	40.00	40.00
NO PLATE 'RED' S.NETT	1	50.00	50.00
OFF PEAK CAR SEAL S.NETT	1	25.00	25.00
TO REMOVE ALL DAMAGED PART WITH ALL NECESSARY COMPONENT/ATTACHMENT. STRAIGHTEN CHASSIS MEMBER, REPAIR/RESHAPE DENTED BODY PANEL. REPLACE DAMAGED PART. REFIT INTO POSITION.	1	900.00	900.00
TO SPRAY PAINT REPLACE/REPAIR BODY PART	1	800.00	800.00
TRANSFER DOOR MECHANISM	1	150.00	150.00
CHECK WIRING & LIGHT FUNCTION	1	50.00	50.00
APPLICATION TO LTA BREAK SEAL FOR OFF PEAK CAR. SEND FOR REINSPECTION WHEN CAR READY	1	100.00	100.00

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature: _____

Date: _____