



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SMA 6532 H

*Not Authorized
Repair by pain*

Parts	(a) Cost / List Price Items	\$	6,587.16
	Plus/Less 25%	\$	1,646.79
	Total of Cost / List	\$	4,940.37
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost			
Labour		\$	1,420.00
Total		\$	6,360.37

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor	:	<u>Kenneth</u>
Company	:	<u>CLIC</u>
Survey conducted on	:	<u>2/12/18</u> at _____
<u>Remarks By Surveyor</u>		
(a)	The repair of this vehicle is <u>authorized</u> / is not authorized until further notice.	
(b)	Recommended Days of Repair	: <u>04</u> day(s)
(c)	Resurvey	: Required / <u>Not Required</u>
(d)	Excess	: \$ _____
(e)	Signature of surveyor	: <u>Le</u> Date: <u>2/12/18</u>



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SMA 6532 H**
Make & Model : **TOYOTA PRIUS**
Chassis No : **ZVW508036536**

Submit By : **Carmen Lim**
Year Manufacture : **2016**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Headlamp RH <i>Sn</i>	1	\$2,531.60		X
2	Front bumper	1	\$450.80		?
3	Front bumper clip	10	\$40.00		?
4	Front bumper reinforcement - upper <i>Sn</i>	1	\$711.50		X
5	Front bumper side retainer RH <i>Sn</i>	1	\$107.20		X
6	Front bumper side retainer LH <i>Sn</i>	1	\$107.20		X
7	Front bumper upper grille <i>Sn</i>	1	\$321.90		X
8	Front bumper emblem <i>Sn</i>	1	\$87.10		X
9	Fog lamp RH	1	\$910.70		?
10	RH front fender <i>B1</i>	1	\$868.70		✓
11	RH front fender undershield <i>Sn</i>	1	\$185.64		X
12	RH front fender undershield clip <i>Sn</i>	10	\$25.00		X
13	RHF fender wording "HYBRID" <i>Sn</i>	1	\$44.17		✓
14	RH front hub cab <i>Sn</i>	1	\$195.65		✓
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

