



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 669638.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SMA 6532 H

Parts	(a) Cost / List Price Items	\$ 6,587.16
	Plus/Less 25%	\$ 1,646.79
	Total of Cost / List	\$ 4,940.37
	(b) Nett Price Items	
	Less	
	Total of Nett Item	
	(c) Special Nett Items	
	Total Parts Cost	
Labour		\$ 1,420.00
Total		\$ 6,360.37

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor

Company

Survey conducted on

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$

(e) Signature of surveyor

Date: 2/12/18

Partse No. : SMA 6532 H
e & Model : TOYOTA PRIUS
assis No : ZVW508036536Submit By : Carmen Lim
Year Manufacture : 2016
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Headlamp RH	1	\$2,531.60		X
2	Front bumper	1	\$450.80		X
3	Front bumper clip	10	\$40.00		X
4	Front bumper reinforcement - upper	1	\$711.50		X
5	Front bumper side retainer RH	1	\$107.20		X
6	Front bumper side retainer LH	1	\$107.20		X
7	Front bumper upper grille	1	\$321.90		X
8	Front bumper emblem	1	\$87.10		X
9	Fog lamp RH	1	\$910.70		X
10	RH front fender	1	\$868.70		✓
11	RH front fender undershield	1	\$185.64		X
12	RH front fender undershield clip	10	\$25.00		X
13	RHF fender wording "HYBRID"	1	\$44.17		✓
14	RH front hub cap	1	\$195.65		✓
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

110752

