

INS. CASE OWNER:

CC4/LPC19021166/R1ha3 n2

LKK:

IDAC:

Surveyor:

RASUL

DOI:

ASSIGNMENT

Date / Time

28/11/2019

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : YP 7154M

Claim No. : 19/19/VC05/022711

Name of Insured : SPM SERVICES

Policy No. :

Insured Tel No. : HP:

Make / Model :

Excess Sec II : \$\$ D.O.A : 21.11.2019

Place of Accident : LOWER DELTA RD > BT TIMAH

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SJQ 7602J

INSRS:
WSP: CL Auto
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	SJQ 7602J- X	YP 7154M - X	STAGE	DATE / PIC
			Non-Reporting hr (1st):	
			Non-Reporting hr (2nd):	
			Non-Reporting hr (Final):	
			Notification hr (if non-pickup):	
			Call OI:	
			After call hr to OI:	
			Documentation Check List: Handler	Typist
			Notification hr (if non-pickup)	
			After call hr to OI:	
			Authorisation To Act:	
			Release Voucher:	
			Final Repair Bill:	
			Car Rental Invoice:	
			Towing Invoice:	
			LTA / GIA:	
			Medical Bill:	
			PIR:	
			Mandate/Reject Instruction:	
			LOD	
			Payment Breakdown Form:	
			Post-Repair Photos:	
			Others:	
PRELIMINARY ADVICE Date/Time: 21/01/2020 Sent By: 03				
FINALIZATION Date/Time: Confirm with: Confirm by:				
Repair Cost: 46 \$5,000.00 (12 days) Reduction: 73 % Email ☐ Call ☐				
FINAL SETTLEMENT Date/Time: 28/03/20 Confirm with: PAUL Email ☒ Call ☐				
Final Liability: % 100 (Assessed) BOLA S/N No.: 28 If NO or B 28, Ass. Lia: 100%				
Repair Cost: \$5,000.00 CB VEH. C.C., OIB (MOT)				
Loss of Rental (LOR): \$5 (days)				
Loss of Use (LOU): \$5 840.00 x 14 days				
Loss of Income (LOI): \$5 (5 x days)				
LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]				
GIA/LTA Search \$5 2.00				
Medical: \$5 -				
Disbursement: \$5 - (e.g. Tow/ Independent)				
Legal Cost \$5 -				
Total: \$5 5,842.00 Global Sum \$5: 5,840.00				
FINAL PAYMENT Date/Time: Confirm with: Email ☐ Call ☐				
Payee 1: \$5 5,840.00 Name 1: C L AUTO PTE LTD				
Payee 2: (Strike if N.A.) \$5 - Name 2: -				
Payee 3: (Strike if N.A.) \$5 - Name 3: -				

COPY SENT
11/4/2020



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 19/19/19/VC05/022711
Our ref: CC4/LPC19021166/R1ha3

Date: 21.02.2020

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SJQ 7602J

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 29.11.2019 at the premises of M/s C L AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$	18,241.02
Revised Estimate Amount	: S\$	5,000.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	40,000.00
LTA Reimbursement Value	: S\$	24,633.00
Nett Value	: S\$	15,367.00

Description of Damage:

The vehicle sustained damages at the
Front & Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 12 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Information	
Owner ID Type:	Business
Owner ID:	052D
Vehicle Details	
Vehicle No.:	SJQ7602J
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOSE AUTO
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	1NZX908817
Chassis No.:	MR053HY9305113390
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,468.00
Original Registration Date:	26 May 2009
First Registration Date:	26 May 2009
Transfer Count:	2
Actual ARF Paid:	\$12,468.00
PARF Eligibility	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Information	
COE Expiry Date:	30 Apr 2029
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$26,175.00
COE Rebate Amount:	\$24,633.00
Total Rebate Amount:	\$24,633.00

The information contained herein is correct as at 02 Dec 2019

OK

40,000
24,633

15,367

FOR SURVEYOR

C L Auto Pte Ltd

48 TOH GUAN ROAD EAST #02-125 ENTERPRISE HUB SINGAPORE 608586

TEL: 6795 6125 FAX: 6795 0920 Email: vincent@clauto.com.sg

RCB NO:198800292M

M/S :

ATTN: Motor Claim Department \ MR.

Your Ref No: SJQ7602J

Claim Type: Third Party

Accident Date:

Estimate No: EST1900266

Date: 22 Nov 2019

Policy No:

Veh Reg No: SJQ7602J

Make/Model: TOYOTA VIOS E AUTO

Chassis No: MR053HY9305113390

Engine No: 1NZX908817

Reg. Date: 26/05/2009

Estimate Repair Cost to Vehicle No :SJQ7602J

Description	Quantity	List Price	Amount
		SS	SS
List Price:			
1 FRONT BUMPER RETAINER LH <i>no</i>	1 PC		
2 FRONT BUMPER RETAINER RH <i>no</i>	1 PC		
3 FRONT BUMPER REINFORCEMENT <i>h</i>	1 PC		
4 FRONT SUPPORT TOP PANEL <i>repair</i>	1 PC		
5 FRONT SUPPORT LOWER PANEL <i>X</i>	1 PC		
6 FRONT BUMPER CLIPS <i>no</i>	1 PC		
7 CAR HORN <i>X</i>	1 PC		
8 FRONT BUMPER TOWING COVER <i>mis</i>	1 PC		
9 HEADLAMP RH <i>X</i>	1 PC		
10 HEADLAMP LH <i>X</i>	1 PC		
11 FOG LAMP RH <i>X</i>	1 PC		
12 FOG LAMP LH <i>X</i>	1 PC		
13 FOG LAMP COVER RH <i>X</i>	1 PC		
14 FOG LAMP COVER LH <i>X</i>	1 PC		
15 CONDENSER <i>h</i>	1 PC		
16 RADIATOR <i>X</i>	1 PC		
17 FAN MOTOR <i>X</i>	1 PC		
18 FAN COWLING <i>X</i>	1 PC		
19 WASHER TANK TOP <i>X</i>	1 PC		
20 WASHER TANK LOWER <i>X</i>	1 PC		
21 FRONT FENDER RH <i>X</i>	1 PC		
22 FRONT FENDER LH <i>X</i>	1 PC		
23 AIR FILTER <i>X</i>	1 PC		
24 FRONT CAR NUMBER PLATE <i>cor</i>	1 PC		
25 FRONT CAR NUMBER PLATE FRAME <i>cor</i> <i>3 s/n</i>	1 PC		
26 FRONT BUMPER LOGO (TOYOTA) <i>no</i>	1 PC		
27 FRONT BONNET LOCK <i>X</i>	1 PC		
28 AIR CON DISCHARGE PIPE <i>X</i>	1 PC		
29 AIR CON LIQUID PIPE <i>X</i>	1 PC		
30 AIR CON SUCTION PIPE <i>X</i>	1 PC		
31 LOWER RIGHT ENGINE CENTER COVER <i>cor</i>	1 PC		
32 CROSS MEMBER <i>X</i>	1 PC		
33 FRONT BUMPER SPONGE <i>X</i>	1 PC		
34 FRONT BUMPER GARNISH RIGHT <i>mis</i>	1 PC		
35 FRONT BUMPER GARNISH LEFT <i>X</i>	1 PC		
36 FRONT BUMPER GARNISH TOP <i>de</i>	1 PC		
37 FRONT BUMPER GARNISH LOWER <i>de</i>	1 PC		
38 FRONT GRILLS TOP PART <i>cor</i>	1 PC		
39 FRONT GRILLS LOWER PART <i>X</i>	1 PC		

C L Auto Pte Ltd

48 TOH GUAN ROAD EAST #02-125 ENTERPRISE HUB SINGAPORE 608586
TEL: 6795 6125 FAX: 6795 0920 Email: vincent@clauto.com.sg
RCB NO:198800292M

M/S : MR. EDWARD
APT BLK 65 YUNG KUANG ROAD #01-99
SINGAPORE 610065

Estimate No: EST1900267
Date: 22 Nov 2019
Policy No:
Veh Reg No: SJQ7602J
Make/Model: TOYOTA VIOS E AUTO
Chassis No: MR053HY9305113390
Engine No: 1NZX908817
Reg. Date: 26/05/2009

ATTN: MR. EDWARD
Your Ref No: SJQ7602J
Claim Type: Third Party
Accident Date:

Estimate Repair Cost to Vehicle No :SJQ7602J

Description	Quantity	List Price	Amount
		SS	SS
40 EXHAUST MUFFLER MOUNTING Xsu	1 PC	76.00 X	
41 BOOTLID OUTER GARNISH ? Xsu	1 PC	510.00 X	
		9,535.00	9,535.00
Total			SS 9,535.00

TOTAL: SINGAPORE DOLLAR NINE THOUSAND FIVE HUNDRED THIRTY FIVE ONLY

For C L Auto Pte Ltd



AUTHORISED SIGNATURE

C L Auto Pte Ltd

48 TOH GUAN ROAD EAST #02-125 ENTERPRISE HUB SINGAPORE 608586
TEL: 6795 6125 FAX: 6795 0920 Email: vincent@clauto.com.sg
RCB NO:198800292M

M/S : MR. EDWARD
APT BLK 65 YUNG KUANG ROAD #01-99
SINGAPORE 610065

Estimate No: EST1900268
Date: 23 Nov 2019
Policy No:
Veh Reg No: SJQ7602J
Make/Model: TOYOTA VIOS E AUTO
Chassis No: MR053HY9305113390
Engine No: 1NZX908817
Reg. Date: 26/05/2009

ATTN: MR. EDWARD
Your Ref No: SJQ7602J
Claim Type: Third Party
Accident Date:

Estimate Repair Cost to Vehicle No :SJQ7602J

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
40 REAR TYPE MUDFLAME LH <i>scat</i>	1 PC		
41 REAR TYPE MUDFLAME RH <i>scat</i>	1 PC		
42 TAIL LAMP SEAL LH <i>X</i>	1 PC		
43 TAIL LAMP SEAL RH <i>X</i>	1 PC		
44 REAR BUMPER REFLECTOR LH <i>X</i>	1 PC		
45 REAR BUMPER REFLECTOR RH <i>X</i>	1 PC		
46 SPARETYPE PANEL WELL <i>X</i>	1 PC		
		0.00	0.00
Labour Charges:			
47 TO REFIR & REPLACE AIR CONDENSER , AIRCON PIPE , REPLACE HOSE. TO TOP UP AIRCON GAS & VACUMM. TO CHECK AIRCON COOLING SYSTEM. TO REFIT & REPLACE TOP AIRCON COOLANT. TO REFIT & REPLCE ALIGN LEADLAMP.	1 JOB	350.00 <i>100 X m</i>	
		350.00	350.00
Total			S\$ 350.00

TOTAL: SINGAPORE DOLLAR THREE HUNDRED FIFTY ONLY

For C L Auto Pte Ltd

AUTHORISED SIGNATURE



C L Auto Pte Ltd

48 TOH GUAN ROAD EAST #02-125 ENTERPRISE HUB SINGAPORE 608586
TEL: 6795 6125 FAX: 6795 0920 Email: vincent@clauto.com.sg
RCB NO:198800292M

M/S : MR. EDWARD
APT BLK 65 YUNG KUANG ROAD #01-99
SINGAPORE 610065

Estimate No: EST1900267
Date: 22 Nov 2019
Policy No:
Veh Reg No: SJQ7602J
Make/Model: TOYOTA VIOS E AUTO
Chassis No: MR053HY9305113390
Engine No: 1NZX908817
Reg. Date: 26/05/2009

ATTN: MR. EDWARD
Your Ref No: SJQ7602J
Claim Type: Third Party
Accident Date:

Estimate Repair Cost to Vehicle No :SJQ7602J

Description	Quantity	List Price	Amount
		SS	SS
Special Net:			
1 REAR NO PLATE LAMP RH <i>X } sue</i>	1 PC	102.00 <i>X</i>	
2 REAR NO PLATE LAMP LH <i>X } sue</i>	1 PC	102.00 <i>X</i>	
3 REAR BUMPER <i>de -</i>	1 PC	522.00 <i>-</i>	
4 REAR BUMPER CLIP <i>ne -</i>	1 <i>pe set</i>	43.00 <i>15</i>	
5 REAR BUMPER SIDE RETAINER RH <i>ne -</i>	1 PC	94.00 <i>- 63.14</i>	
6 REAR BUMPER SIDE RETAINER LH <i>ne -</i>	1 PC	94.00 <i>- 63.14</i>	
7 REAR BUMPER BRACKET RH <i>X } sue</i>	1 PC	161.00 <i>X</i>	
8 REAR BUMPER BRACKET LH <i>X } sue</i>	1 PC	161.00 <i>X</i>	
9 REAR BUMPER REFLECTOR RH <i>Reflector X } sue</i>	1 PC	115.00 <i>X</i>	
10 REAR BUMPER REFLECTOR LH <i>X } sue</i>	1 PC	115.00 <i>X</i>	
11 BOOTLID <i>bt -</i>	1 PC	933.00	
12 BOOTLID LOCK <i>bt -</i>	1 PC	93.00	
13 BOOTLID LOCK CABLE <i>X } sue</i>	1 PC	88.00 <i>X</i>	
14 BOOTLID LOCK CATCH <i>bt -</i>	1 PC	75.00	
15 BOOTLID HINGE RH <i>X } sue</i>	1 PC	158.00 <i>X</i>	
16 BOOTLID HINGE LH <i>X } sue</i>	1 PC	158.00 <i>X</i>	
17 BOOTLID LOGO <i>ne -</i>	1 PC	104.00	
18 BOOTLID EMBLEM 'VIOS' <i>ne -</i>	1 PC	94.00	
19 BOOTLID EMBLEM 'E' <i>ne -</i>	1 PC	76.00	
20 BOOTLID REFLECTOR RH <i>X } sue</i>	1 PC	115.00 <i>X</i>	
21 BOOTLID REFLECTOR LH <i>X } sue</i>	1 PC	115.00 <i>X</i>	
22 BOOT WEATHERSTRIP <i>ne -</i>	1 PC	102.00	
23 REAR END PANEL <i>bt -</i>	1 PC	627.00	
24 REAR END PANEL GARNISH <i>X } sue</i>	1 PC	200.00 <i>X</i>	
25 REAR END PANEL GARNISH CLIP - SET <i>X } sue</i>	1 PC	43.00 <i>X</i>	
26 REAR FENDER INNER TRIM RH <i>X } sue</i>	1 PC	458.00 <i>X</i>	
27 REAR FENDER INNER TRIM LH <i>X } sue</i>	1 PC	458.00 <i>X</i>	
28 REAR FENDER INNER TRIM CLIP - SET <i>X } sue</i>	1 PC	86.00 <i>X</i>	
29 TAIL LAMP RH <i>bro -</i>	1 PC	296.00	
30 TAIL LAMP LH <i>bro -</i>	1 PC	296.00	
31 TAIL LAMP CLIP - SET <i>ne -</i>	1 PC	43.00	
32 TAIL LAMP PANEL RIGHT <i>X repair</i>	1 PC	160.00 <i>X R</i>	
33 TAIL LAMP PANEL LEFT <i>X repair</i>	1 PC	160.00	
34 SPARE TYRE WELL PANEL <i>X repair</i>	1 PC	846.00 <i>X R</i>	
35 SPARE TYRE WELL PANEL <i>X repair</i>	1 PC	217.00 <i>X</i>	
36 SPARE TYRE PANEL SPONGE RIGHT <i>X } sue</i>	1 PC	217.00 <i>X</i>	
37 SPARE TYRE PANEL SPONGE LEFT <i>X } sue</i>	1 PC	217.00 <i>X</i>	
38 SPARE TYRE PANEL SPONGE CENTRE <i>X } sue</i>	1 PC	388.00 <i>X</i>	
39 EXHAUST MUFFLER <i>X</i>	1 PC	617.00 <i>X</i>	

C L Auto Pte Ltd

48 TOH GUAN ROAD EAST #02-125 ENTERPRISE HUB SINGAPORE 608586
TEL: 6795 6125 FAX: 6795 0920 Email: vincent@clauto.com.sg
RCB NO:198800292M

M/S :

ATTN: Motor Claim Department \ MR.
Your Ref No: SJQ7602J
Claim Type: Third Party
Accident Date:

Estimate No: EST1900266
Date: 22 Nov 2019
Policy No:
Veh Reg No: SJQ7602J
Make/Model: TOYOTA VIOS E AUTO
Chassis No: MR053HY9305113390
Engine No: 1NZX908817
Reg. Date: 26/05/2009

Estimate Repair Cost to Vehicle No :SJQ7602J

Description	Quantity	List Price	Amount
		SS	SS
40 LOWER LEFT ENGINE CENTRE COVER <i>ca</i>	1 PC		<i>166.12</i>
		0.00	0.00
Labour Charges:			
41 TO STRAIGHTEN & PULL FRONT TWO WHEELHOUSE, CHASIS / BUMPER TO DO COTTING / WELDING FOR SUPPORT PANEL & HEAD PANEL	1 JOB	1,800.00	<i>400</i>
42 TO DISMANTLE RADIATOR, FAN MOTOR & COOLING FAN.	1 JOB	280.00	<i>X 11</i>
		2,080.00	2,080.00
Total			SS 2,080.00

TOTAL: SINGAPORE DOLLAR TWO THOUSAND EIGHTY ONLY

Rasul
Hp 90010068
12 days
L/S
29/11/19 A 1550
Resu after repair

For C L Auto Pte Ltd

AUTHORISED SIGNATURE



C L Auto Pte Ltd

48 TOH GUAN ROAD EAST #02-125 ENTERPRISE HUB SINGAPORE 608586
TEL: 6795 6125 FAX: 6795 0920 Email: vincent@clauto.com.sg
RCB NO:198800292M

M/S : MR. EDWARD
APT BLK 65 YUNG KUANG ROAD #01-99
SINGAPORE 610065

Estimate No: EST1900274
Date: 25 Nov 2019
Policy No:
Veh Reg No: SJQ7602J
Make/Model: TOYOTA VIOS E AUTO
Chassis No: MR053HY9305113390
Engine No: 1NZX908817
Reg. Date: 26/05/2009

ATTN: MR. EDWARD
Your Ref No: SJQ7602J
Claim Type: Third Party
Accident Date:

Estimate Repair Cost to Vehicle No :SJQ7602J

Description	Quantity	List Price	Amount
		SS	SS
Labour Charges:			
1 TO PUTTY, RESPRAY PAINTING & POLISH ACCIDENT AREA. <u>FRONT</u> PORTION.	1 JOB	2,180.00 400	
2 TO SPRAY RUST PROOFING	1 JOB	280.00 80	
3 TO REMOVE & REFIT REAR WINDSCREEN & MOULDING & WINDSCREEN INNERSHIELD.	1 JOB	295.00 Xnn	
4 TO REMOVE & FIX IN REVERSE SENSOR	1 JOB	180.00 60	
5 TO REMOVE & REFIT EXHAUST & HEATSHIELD.	1 JOB	250.00 X	
6 TO CUT & WELD TAIL LAMP PANEL LEFT & RIGHT, END PANEL, SPARE TYRE PANEL WELL, CHASSIS LEFT & RIGHT, REAR LEFT FENDER. REAR DOOR ALIGNMENT & BOOT COVER.	1 JOB	2,800.00 800	
7 UNDERCOATING	1 JOB	280.00 60	
8 TO REMOVE & REFIT REAR AXLE.	1 JOB	450.00 X	
9 WHEEL ALIGNMENT	1 JOB	80.00 X } nn	
10 TO REMOVE & REFIT FUEL TANK	1 JOB	250.00 X	
		7,045.00	7,045.00
		Total	SS 7,045.00

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND FORTY FIVE ONLY

For C L Auto Pte Ltd

AUTHORISED SIGNATURE



18,241.02

C L Auto Pte Ltd

48 TOH GUAN ROAD EAST #02-125 ENTERPRISE HUB SINGAPORE 608586
 TEL: 6795 6125 FAX: 6795 0920 Email: vincent@clauto.com.sg
 RCB NO:198800292M

M/S : MR. EDWARD
 APT BLK 65 YUNG KUANG ROAD #01-99
 SINGAPORE 610065

Estimate No: EST1900266
 Date: 22 Nov 2019
 Policy No: PNCV2019-00000452
 Veh Reg No: SJQ7602J
 Make/Model: TOYOTA VIOS E AUTO
 Chassis No: MR053HY9305113390
 Engine No: 1NZX908817
 Reg. Date: 26/05/2009
 Payment Term: NORMD

ATTN: MR. EDWARD
 Your Ref No: SJQ7602J
 Claim Type: Third Party
 Accident Date: 21/11/2019
 TP Veh Reg No: YP7154M

Estimate Repair Cost to Vehicle No :SJQ7602J

Description	Quantity	List Price	Amount
		S\$	S\$
Special Net:			
1 FRONT CAR NUMBER PLATE <i>ca</i>	1 PC	45.00 <i>35</i>	<i>35</i>
2 FRONT CAR NUMBER PLATE FRAME	1 PC	45.00	
3 FRONT BUMPER LOGO (TOYOTA) <i>(LIST ITEM)</i>	1 PC	45.00 <i>neu</i>	
		135.00	135.00
List Price:			
4 FRONT BUMPER RETAINER LH <i>neu</i>	1 PC	63.14	
5 FRONT BUMPER RETAINER RH <i>neu</i>	1 PC	63.14	
6 FRONT BUMPER CLIPS <i>neu</i>	1 SET	15.00	
7 FRONT BUMPER TOWING HOOK <i>mis</i>	1 PC	24.96	
8 AIRCON CONDENSER <i>bt</i>	1 PC	1,300.00	
9 LOWER RIGHT ENGINE CENTER COVER <i>ca</i>	1 PC	110.00	
10 FRONT BUMPER GARNISH RIGHT <i>mis</i>	1 PC	100.00	
11 FRONT BUMPER GARNISH TOP <i>de</i>	1 PC	250.00	
12 FRONT BUMPER GARNISH LOWER <i>de</i>	1 PC	100.00	
13 REAR BUMPER <i>de</i>	1 PC	522.00	
14 REAR BUMPER CLIPS <i>neu</i>	1 SET	43.00	
15 REAR BOOTLID <i>bt</i>	1 PC	933.00	
16 REAR BOOTLID LOCK <i>bt</i>	1 PC	93.00	
17 REAR BOOTLID LOCK CATCH <i>bt</i>	1 PC	75.00	
18 REAR BOOTLID LOGO (TOYOTA) <i>neu</i>	1 PC	104.00	
19 REAR BOOTLID EMBLEM (TOYOTA VIOS) <i>neu</i>	1 PC	94.00	
20 REAR BOOTLID WEATHERSTRIP <i>neu</i>	1 PC	102.00	
21 REAR END PANEL <i>bt</i>	1 PC	627.00	
22 TAIL LAMP RH <i>bro</i>	1 PC	296.00	
23 TAIL LAMP LH <i>bro</i>	1 PC	296.00	
24 TAIL LAMP CLIPS <i>neu</i>	1 SET	43.00	
25 REAR TYPE MUDFLAP R/H <i>scr</i>	1 PC	100.00	
26 REAR TYPE MUDFLAME L/H <i>scr</i>	1 PC	100.00	
27 FRONT GRILLE CENTER MOULDING <i>ca</i>	1 PC	112.10	
28 REAR R/H TAIL LAMP SEAL <i>Xm</i>	1 PC	60.00	
29 REAR L/H TAIL LAMP SEAL <i>Xm</i>	1 PC	60.00	
30 LOWER LEFT ENGINE CENTER COVER <i>ca</i>	1 PC	166.12	
		5,852.46	
	Less 25%	1,463.12	34
			4,389.36
Labour Charges:			
31 TO REMOVE & REPLACE AIRCON CONDENSER, AIRCON PIPE & REPLACE AIR CON HOSE	1 JOB	100.00	X

C L Auto Pte Ltd

48 TOH GUAN ROAD EAST #02-125 ENTERPRISE HUB SINGAPORE 608586
 TEL: 6795 6125 FAX: 6795 0920 Email: vincent@clauto.com.sg
 RCB NO: 198800292M

M/S: MR. EDWARD
 APT BLK 65 YUNG KUANG ROAD #01-99
 SINGAPORE 610065

ATTN: MR. EDWARD
 Your Ref No: SJQ7602J
 Claim Type: Third Party
 Accident Date: 21/11/2019
 TP Veh Reg No: YP7154M

Estimate No: EST1900266
 Date: 22 Nov 2019
 Policy No: PNCV2019-00000452
 Veh Reg No: SJQ7602J
 Make/Model: TOYOTA VIOS E AUTO
 Chassis No: MR053HY9305113390
 Engine No: 1NZX908817
 Reg. Date: 26/05/2009
 Payment Term: NORMD

Estimate Repair Cost to Vehicle No :SJQ7602J

Description	Quantity	List Price	Amount
		SS	SS
32 TO PUTTY, RESPRAY PAINTING & POLISH ACCIDENT AREA FRONT PORTION	1 JOB	400.00 ✓	
33 TO RESPRAY RUST PROOFING	1 JOB	80.00 ✓	
34 TO REMOVE & REFIT REAR WINDSCREEN & MOULDING & WINDSCREEN INNERSHIELD	1 JOB	120.00 ✓	
35 TO REMOVE & REFIT REVERSE SENSOR	1 JOB	60.00 ✓	
36 TO CUT & WELD TAIL LAMP PANEL LEFT & RIGHT, END PANEL, SPARE TYRE PANEL WELL, CHASSIS LEFT & RIGHT, REAR LEFT FENDER, REAR DOOR ALIGNMENT & BOOT COVER	1 JOB	800.00 ✓	
37 UNDERCOATING	1 JOB	60.00 ✓	
		1,620.00	1,620.00
Others			
38 REAR BOOTLID EMBLEM "E" <i>re (LIST ITEM)</i>	1 PC	76.00 ✓	
39 TO STRAIGHTEN & PULL FRONT TWO WHEELHOUSE, CHASSIS / BUMPER TO DO COATING, WELDING FOR SUPPORT PANEL & HEAD PANEL	1 JOB	400.00 ✓	
		476.00	476.00

Total SS 6,620.36 34
 Lump Sum Less 20% -1,324.07

Total Amount Payable SS 5,296.29

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND TWO HUNDRED NINETY SIX AND CENTS TWENTY NINE ONLY

LIST parts - 4333.09
 OTHERS LIST parts - 57.00
 special net - 35.00
 Labour - 1800.00
 Total - 6225.09
 20%
 4980.07

45.5000

For C L Auto Pte Ltd

the Reparer of the following:
 • To respray damaged parts during survey
 • To display damaged parts during survey
 • Parts must be subject to confirmation
 • To supply a list of parts on a "Without Prejudice" basis
 • Supplementary items must be surveyed and
 is subject to final approval from Insurance Company

AUTHORISED SIGNATURE

Acknowledged by Reparer
 Signature:

Date:

12 days

2166/1603

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Thursday, 28 November 2019 3:44 PM
To: 'assignments@lkkauto.com'
Cc: MT_Claim_SG; 'claim1@clauto.com.sg'
Subject: FW: Notice Of Accident & PRS Ref Vehicle No SJQ7602J [External Confidential]

Lonpac External - Confidential

Our Ref : 19/19/19/VC05/022711

Dear Nivitha,

Kindly proceed as arranged.

Our insured has yet to lodge the report and we are making enquiries.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: claim1@clauto.com.sg [mailto:claim1@clauto.com.sg]
Sent: Thursday, 28 November 2019 3:30 pm
To: GERALD POH WEE BIN
Cc: MT_Claim_SG
Subject: Re: Notice Of Accident & PRS Ref Vehicle No SJQ7602J [External General]

Good Evening Mr. Gerald,

Thanks for your prompt reply.

We choose No: 9 Mr. Mohd Rasul

Kindly let us know the date and time of the scheduled pre-repair survey.

The car SJQ7602J is in our workshop.

Thank you very much

Best Regards,

Paul Antony Fernandez

Insurance Claims Assistant

CL Auto Pte Ltd

48 Toh Guan Road East

4:05pm @ 28/11/19
P. Edmund
v: In
agreed survey on 28/11/19

#02-125 Enterprise Hub,
Singapore 608586
Tel: +65 67956125
Fax: +65 67950920
Email: claim1@clauto.com.sg

On 2019-11-28 15:09, GERALD POH WEE BIN wrote:

Lonpac External - General

WITHOUT PREJUDICE

Our Ref : 19/19/19/VC05/022711

Dear Paul,

Please see attached and revert.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

Lonpac External - General data is for internal / external use.

-----Original Message-----

From: claim1@clauto.com.sg [mailto:claim1@clauto.com.sg]

Sent: Thursday, 28 November 2019 2:32 pm

To: MT_Claim_SG

Subject: Fwd: Notice Of Accident & PRS Ref Vehicle No SJQ7602J

----- Original Message -----

Subject: Notice Of Accident & PRS Ref Vehicle No SJQ7602J

Date: 2019-11-28 14:29

From: claim1@clauto.com.sg

To: mt_claim@lonpac.com.sg

Cc: Claim3 <claim3@clauto.com.sg>

Good Afternoon Claims Department,

Attached herewith are the documents notifying your office Notice of Accident and Pre-Repair Survey.

Kindly revert back to us within 2 working days upon receipt of this email and the documents attached informing the date, time of pre-repair survey and contact details of assigned surveyor.

Thank you

Best Regards,

Paul Antony Fernandez

Insurance Claims Assistant

CL Auto Pte Ltd
48 Toh Guan Road East
#02-125 Enterprise Hub,
Singapore 608586

Tel: +65 67956125
Fax: +65 67950920
Email: claim1@clauto.com.sg

P.S. Do take note please that due to the large file exceeding the allowable 14MB, multiple emails on same subject matter will be sent to your office. Thank you

--
Best Regards,
Paul Antony Fernandez
Insurance Claims Assistant

CL Auto Pte Ltd
48 Toh Guan Road East
#02-125 Enterprise Hub,
Singapore 608586
Tel: +65 67956125
Fax: +65 67950920
Email: claim1@clauto.com.sg

--
Best Regards,
Paul Antony Fernandez
Insurance Claims Assistant

CL Auto Pte Ltd
48 Toh Guan Road East
#02-125 Enterprise Hub,
Singapore 608586
Tel: +65 67956125
Fax: +65 67950920
Email: claim1@clauto.com.sg

Mei Kwan (LKKAuto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Saturday, 7 December, 2019 11:40 AM
To: Mei Kwan (LKKAuto)
Cc: MT_Claim_SG
Subject: PRE-REPAIR SURVEY - SJQ7062J [External Confidential]
Attachments: YP 7154M REPORT.pdf


Lonpac External - Confidential

Our Ref : 19/19/19/VC05/022711
Your Ref : CC4/LPC19021166/R1ha3

Dear Mei Kwan,

Attached copy of insured's report for your attention.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC19021166/R1ha3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 02-04-2020	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 7154M	Veh. Inspected	SJQ 7602J	
Policy No.	Z19VC05003290	Coverage (\$)	0.00	
Claim No.	19/19/19/VC05/022711	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	28/11/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS E AUTO	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	MR053HY9305113390	Colour	BLACK	
Odometer	237100	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	5 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	5 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	5 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/11/2019	Inspection Date	29/11/2019	
Survey held at	C L AUTO PTE LTD 48 TOH GUAN ROAD EAST #02-127 ENTERPRISE HUP SINGAPORE 608586			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJQ 7602J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER RETAINER LH	NECESSARY	63.14	63.14
1	FRONT BUMPER RETAINER RH	NECESSARY	63.14	63.14
1	SET FRONT BUMPER CLIPS	NECESSARY	15.00	15.00
1	FRONT BUMPER TOWING HOOK	MISSING	24.96	24.96
1	AIRCON CONDENSER	BENT	1,300.00	1,300.00
1	LOWER RIGHT ENGINE CENTER COVER	CRACKED	110.00	110.00
1	FRONT BUMPER GARNISH RIGHT	MISSING	100.00	100.00
1	FRONT BUMPER GARNISH TOP	DEFORMED	250.00	250.00
1	FRONT BUMPER GARNISH LOWER	DEFORMED	100.00	100.00
1	REAR BUMPER	DEFORMED	522.00	522.00
1	SET REAR BUMPER CLIPS	NECESSARY	43.00	43.00
1	REAR BOOTLID	BENT	933.00	933.00
1	REAR BOOTLID LOCK	BENT	93.00	93.00
1	REAR BOOTLID LOCK CATCH	BENT	75.00	75.00
1	REAR BOOTLID LOGO (TOYOTA)	NECESSARY	104.00	104.00
1	REAR BOOTLID EMBLEM (TOYOTA VIOS)	NECESSARY	94.00	94.00
1	REAR BOOTLID WEATHERSTRIP	NECESSARY	102.00	102.00
1	REAR END PANEL	BENT	627.00	627.00
1	TAIL LAMP RH	BROKEN	296.00	296.00
1	TAIL LAMP LH	BROKEN	296.00	296.00
1	SET TAIL LAMP CLIPS	NECESSARY	43.00	43.00
1	REAR TYRE MUDFLAP R/H	SCRATCHED	100.00	100.00
1	REAR TYRE MUDFLAME L/H	SCRATCHED	100.00	100.00
1	FRONT GRILLE CENTER MOULDING	CRACKED	112.10	112.10
1	REAR R/H TAIL LAMP SEAL	NOT NECESSARY	60.00	-
1	REAR L/H TAIL LAMP SEAL	NOT NECESSARY	60.00	-
1	LOWER LEFT ENGINE CENTER COVER	CRACKED	166.12	166.12
	LESS 25% DISCOUNT		-1,463.12	-1,433.12
			4,389.34	4,299.34



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER LOGO (TOYOTA)	NECESSARY	45.00	45.00
1	REAR BOOTLID EMBLEM 'E'	NECESSARY	76.00	76.00
	LESS 25% DISCOUNT		-	-30.25
			121.00	90.75
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT CAR NUMBER PLATE (SN))	CRACKED	45.00	35.00
1	FRONT CAR NUMBER PLATE FRAME (SN))		45.00	-
			90.00	35.00
	<u>LABOUR</u>			
	TO REMOVE & REPLACE AIRCON CONDENSER ,AIRCON PIPE & REPLACE AIR CON HOSE.	NOT NECESSARY	100.00	-
	TO PUTTY,RESPRAY PAINTING & POLISH ACCIDENT AREA FRONT PORTION .		400.00	400.00
	TO RESPRAY RUST PROOFING.		80.00	80.00
	TO REMOVE & REFIT REAR WINDSCREEN & MOULDING & WINDSCREEN INNERSHIELD .	NOT NECESSARY	120.00	-
	TO REMOVE & REFIT REVERSE SENSOR .		60.00	60.00
	TO CUT & WELD TAIL LAMP PANEL LEFT & RIGHT ,END PANEL,SPARE TYRE PANEL WELL,CHASSIS LEFT & RIGHT ,REAR LEFT FENDER,REAR DOOR ALIGNMENT & BOOT COVER.		800.00	800.00
	UNDERCOATING.		60.00	60.00
	TO STRAIGHTEN & PULL FRONT TWO WHEELHOUSE ,CHASSIS/BUMPER TO DO COATING ,WELDING FOR SUPPORT PANEL & HEAD PANEL.		400.00	400.00
			2,020.00	1,800.00
GRAND TOTAL			6,620.34	6,225.09
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,000.00

Report Ref No. CC4/LPC19021166/R1ha3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.