

C L Auto Pte Ltd

48 TOH GUAN ROAD EAST #02-125 ENTERPRISE HUB SINGAPORE 608586

TEL: 6795 6125 FAX: 6795 0920 Email: vincent@clauto.com.sg

RCB NO:198800292M

M/S : MR. EDWARD

APT BLK 65 YUNG KUANG ROAD #01-99
SINGAPORE 610065

Estimate No: EST1900266

Date: 22 Nov 2019

Policy No: PNCV2019-00000452

Veh Reg No: SJQ7602J

Make/Model: TOYOTA VIOS E AUTO

Chassis No: MR053HY9305113390

Engine No: 1NZX908817

Reg. Date: 26/05/2009

Payment Term: NORMD

ATTN: MR. EDWARD

Your Ref No: SJQ7602J

Claim Type: Third Party

Accident Date: 21/11/2019

TP Veh Reg No: YP7154M

Estimate Repair Cost to Vehicle No :SJQ7602J

Description	Quantity	List Price	Amount
		SS	SS
Special Net:			
1 FRONT CAR NUMBER PLATE <i>cr</i>	1 PC	45.00	
2 FRONT CAR NUMBER PLATE FRAME	1 PC	45.00	
3 FRONT BUMPER LOGO (TOYOTA) <i>(LIST ITEM)</i>	1 PC	45.00	
		135.00	135.00
List Price:			
4 FRONT BUMPER RETAINER LH <i>nee</i>	1 PC	63.14	
5 FRONT BUMPER RETAINER RH <i>nee</i>	1 PC	63.14	
6 FRONT BUMPER CLIPS <i>nee</i>	1 SET	15.00	
7 FRONT BUMPER TOWING HOOK <i>mis</i>	1 PC	24.96	
8 AIRCON CONDENSER <i>bt</i>	1 PC	1,300.00	
9 LOWER RIGHT ENGINE CENTER COVER <i>cr</i>	1 PC	110.00	
10 FRONT BUMPER GARNISH RIGHT <i>mis</i>	1 PC	100.00	
11 FRONT BUMPER GARNISH TOP <i>de</i>	1 PC	250.00	
12 FRONT BUMPER GARNISH LOWER <i>de</i>	1 PC	100.00	
13 REAR BUMPER <i>de</i>	1 PC	522.00	
14 REAR BUMPER CLIPS <i>nee</i>	1 SET	43.00	
15 REAR BOOTLID <i>bt</i>	1 PC	933.00	
16 REAR BOOTLID LOCK <i>bt</i>	1 PC	93.00	
17 REAR BOOTLID LOCK CATCH <i>bt</i>	1 PC	75.00	
18 REAR BOOTLID LOGO (TOYOTA) <i>nee</i>	1 PC	104.00	
19 REAR BOOTLID EMBLEM (TOYOTA VIOS) <i>nee</i>	1 PC	94.00	
20 REAR BOOTLID WEATHERSTRIP <i>nee</i>	1 PC	102.00	
21 REAR END PANEL <i>bt</i>	1 PC	627.00	
22 TAIL LAMP RH <i>bro</i>	1 PC	296.00	
23 TAIL LAMP LH <i>bro</i>	1 PC	296.00	
24 TAIL LAMP CLIPS <i>nee</i>	1 SET	43.00	
25 REAR TYPE MUDFLAP R/H <i>see</i>	1 PC	100.00	
26 REAR TYPE MUDFLAME L/H <i>see</i>	1 PC	100.00	
27 FRONT GRILLE CENTER MOULDING <i>cr</i>	1 PC	112.10	
28 REAR R/H TAIL LAMP SEAL <i>Xm</i>	1 PC	60.00	
29 REAR L/H TAIL LAMP SEAL <i>Xm</i>	1 PC	60.00	
30 LOWER LEFT ENGINE CENTER COVER <i>cr</i>	1 PC	166.12	
		5,852.46	
	Less 25%	1,463.12	4,389.36
Labour Charges:			
31 TO REMOVE & REPLACE AIRCON CONDENSER, AIRCON PIPE & REPLACE AIR CON HOSE	1 JOB	100.00	

5777.46
25%
4333.09

C L Auto Pte Ltd

48 TOH GUAN ROAD EAST #02-125 ENTERPRISE HUB SINGAPORE 608586

TEL: 6795 6125 FAX: 6795 0920 Email: vincent@clauto.com.sg

RCB NO:198800292M

M/S : MR. EDWARD

APT BLK 65 YUNG KUANG ROAD #01-99

SINGAPORE 610065

Estimate No: EST1900266

Date: 22 Nov 2019

Policy No: PNCV2019-00000452

Veh Reg No: SJQ7602J

Make/Model: TOYOTA VIOS E AUTO

Chassis No: MR053HY9305113390

Engine No: 1NZX908817

Reg. Date: 26/05/2009

Payment Term: NORMD

ATTN: MR. EDWARD

Your Ref No: SJQ7602J

Claim Type: Third Party

Accident Date: 21/11/2019

TP Veh Reg No: YP7154M

Estimate Repair Cost to Vehicle No :SJQ7602J

Description	Quantity	List Price	Amount
		SS	SS
32 TO PUTTY, RESPRAY PAINTING & POLISH ACCIDENT AREA FRONT PORTION	1 JOB	400.00 ✓	
33 TO RESPRAY RUST PROOFING	1 JOB	80.00 ✓	
34 TO REMOVE & REFIT REAR WINDSCREEN & MOULDING & WINDSCREEN INNERSHIELD	1 JOB	120.00 XAN	
35 TO REMOVE & REFIT REVERSE SENSOR	1 JOB	60.00 ✓	
36 TO CUT & WELD TAIL LAMP PANEL LEFT & RIGHT, END PANEL, SPARE TYRE PANEL WELL. CHASSIS LEFT & RIGHT, REAR LEFT FENDER. REAR DOOR ALIGNMENT & BOOT COVER	1 JOB	800.00 ✓	
37 UNDERCOATING	1 JOB	60.00 ✓	
		1,620.00	1,620.00
Others			
38 REAR BOOTLID EMBLEM "E" <i>re - (LIST ITEM)</i>	1 PC	76.00 ✓ - 25% = 57	
39 TO STRAIGHTEN & PULL FRONT TWO WHEELHOUSE, CHASSIS / BUMPER TO DO COATING, WELDING FOR SUPPORT PANEL & HEAD PANEL	1 JOB	400.00 ✓	
		476.00	476.00

Total SS 6,620.36
Lump Sum Less 20% -1,324.07

Total Amount Payable SS 5,296.29

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND TWO HUNDRED NINETY SIX AND CENTS TWENTY NINE ONLY

For C L Auto Pte Ltd

AUTHORISED SIGNATURE

List parts - 4333.09
 others list parts - 57.00
 special ref - 35.00
 Labour - 1800.00
 Total - 6225.09
 20%
 4980.07
 45-5000 12 days