

CL Auto Pte Ltd

48 TOH GUAN ROAD EAST #02-125 ENTERPRISE HUB SINGAPORE 608586
TEL: 6795 6125 FAX: 6795 0920 Email: vincent@clauto.com.sg
RCB NO:198800292M

M/S : MR. EDWARD
APT BLK 65 YUNG KUANG ROAD #01-99
SINGAPORE 610065

Estimate No: EST1900267
Date: 22 Nov 2019
Policy No:
Veh Reg No: SJQ7602J
Make/Model: TOYOTA VIOS E AUTO
Chassis No: MR053HY9305113390
Engine No: 1NZX908817
Reg. Date: 26/05/2009

ATTN: MR. EDWARD
Your Ref No: SJQ7602J
Claim Type: Third Party
Accident Date:

Estimate Repair Cost to Vehicle No :SJQ7602J

Description	Quantity	List Price	Amount
		SS	SS
Special Net:			
1 REAR NO PLATE LAMP RH <i>X } su</i>	1 PC	102.00 <i>X</i>	
2 REAR NO PLATE LAMP LH <i>X } su</i>	1 PC	102.00 <i>X</i>	
3 REAR BUMPER <i>de -</i>	1 PC	522.00	
4 REAR BUMPER CLIP <i>ne -</i>	1 PC <i>set</i>	43.00	
5 REAR BUMPER SIDE RETAINER RH <i>ne -</i>	1 PC	94.00	
6 REAR BUMPER SIDE RETAINER LH <i>ne -</i>	1 PC	94.00	
7 REAR BUMPER BRACKET RH <i>X } su</i>	1 PC	161.00 <i>X</i>	
8 REAR BUMPER BRACKET LH <i>X } su</i>	1 PC	161.00 <i>X</i>	
9 REAR BUMPER REFLECTOR RH <i>Reflector X } su</i>	1 PC	115.00 <i>X</i>	
10 REAR BUMPER REFLECTOR LH <i>X } su</i>	1 PC	115.00 <i>X</i>	
11 BOOTLID <i>bt -</i>	1 PC	933.00	
12 BOOTLID LOCK <i>bt -</i>	1 PC	93.00	
13 BOOTLID LOCK CABLE <i>X } su</i>	1 PC	88.00 <i>X</i>	
14 BOOTLID LOCK CATCH <i>bt -</i>	1 PC	75.00	
15 BOOTLID HINGE RH <i>X } su</i>	1 PC	158.00 <i>X</i>	
16 BOOTLID HINGE LH <i>X } su</i>	1 PC	158.00 <i>X</i>	
17 BOOTLID LOGO <i>ne -</i>	1 PC	104.00	
18 BOOTLID EMBLEM 'VIOS' <i>ne -</i>	1 PC	94.00	
19 BOOTLID EMBLEM 'E' <i>ne -</i>	1 PC	76.00	
20 BOOTLID REFLECTOR RH <i>X } su</i>	1 PC	115.00 <i>X</i>	
21 BOOTLID REFLECTOR LH <i>X } su</i>	1 PC	115.00 <i>X</i>	
22 BOOT WEATHERSTRIP <i>ne -</i>	1 PC	102.00	
23 REAR END PANEL <i>bt -</i>	1 PC	627.00	
24 REAR END PANEL GARNISH <i>X } su</i>	1 PC	200.00 <i>X</i>	
25 REAR END PANEL GARNISH CLIP - SET <i>X } su</i>	1 PC	43.00 <i>X</i>	
26 REAR FENDER INNER TRIM RH <i>X } su</i>	1 PC	458.00 <i>X</i>	
27 REAR FENDER INNER TRIM LH <i>X } su</i>	1 PC	458.00 <i>X</i>	
28 REAR FENDER INNER TRIM CLIP - SET <i>X } su</i>	1 PC	86.00 <i>X</i>	
29 TAIL LAMP RH <i>bro -</i>	1 PC	296.00	
30 TAIL LAMP LH <i>bro -</i>	1 PC	296.00	
31 TAIL LAMP CLIP - SET <i>ne -</i>	1 PC	43.00	
32 TAIL LAMP PANEL RIGHT <i>X repair</i>	1 PC	160.00 <i>X</i>	
33 TAIL LAMP PANEL LEFT <i>X repair</i>	1 PC	160.00	
34 SPARE TYRE WELL PANEL <i>X repair</i>	1 PC	846.00 <i>X</i>	
35 SPARE TYRE WELL PANEL <i>X repair</i>	1 PC	217.00 <i>X</i>	
36 SPARE TYRE PANEL SPONGE RIGHT <i>X } su</i>	1 PC	217.00 <i>X</i>	
37 SPARE TYRE PANEL SPONGE LEFT <i>X } su</i>	1 PC	217.00 <i>X</i>	
38 SPARE TYRE PANEL SPONGE CENTRE <i>X } su</i>	1 PC	388.00 <i>X</i>	
39 EXHAUST MUFFLER <i>X</i>	1 PC	617.00 <i>X</i>	

C L Auto Pte Ltd

48 TOH GUAN ROAD EAST #02-125 ENTERPRISE HUB SINGAPORE 608586
TEL: 6795 6125 FAX: 6795 0920 Email: vincent@clauto.com.sg
RCB NO:198800292M

M/S :

ATTN: Motor Claim Department \ MR.
Your Ref No: SJQ7602J
Claim Type: Third Party
Accident Date:

Estimate No: EST1900266
Date: 22 Nov 2019
Policy No:
Veh Reg No: SJQ7602J
Make/Model: TOYOTA VIOS E AUTO
Chassis No: MR053HY9305113390
Engine No: 1NZX908817
Reg. Date: 26/05/2009

Estimate Repair Cost to Vehicle No :SJQ7602J


Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
40 LOWER LEFT ENGINE CENTRE COVER <i>cm</i>	1 PC	0.00	0.00
Labour Charges:			
41 TO STRAIGHTEN & PULL FRONT TWO WHEELHOUSE, CHASIS / BUMPER TO DO COTTING / WELDING FOR SUPPORT PANEL & HEAD PANEL.	1 JOB	1,800.00 <i>for</i>	
42 TO DISMANTLE RADIATOR, FAN MOTOR & COOLING FAN.	1 JOB	280.00 <i>X 11</i>	
		2,080.00	2,080.00
Total			S\$ 2,080.00

TOTAL: SINGAPORE DOLLAR TWO THOUSAND EIGHTY ONLY

RASUL
HP 90010068
12 days
L/S
29/11/19 P 1550
Resy after repair

For C L Auto Pte Ltd


AUTHORISED SIGNATURE



C L Auto Pte Ltd

48 TOH GUAN ROAD EAST #02-125 ENTERPRISE HUB SINGAPORE 608586
TEL: 6795 6125 FAX: 6795 0920 Email: vincent@clauto.com.sg
RCB NO:198800292M

M/S : MR. EDWARD
APT BLK 65 YUNG KUANG ROAD #01-99
SINGAPORE 610065

Estimate No: EST1900274
Date: 25 Nov 2019
Policy No:
Veh Reg No: SJQ7602J
Make/Model: TOYOTA VIOS E AUTO
Chassis No: MR053HY9305113390
Engine No: 1NZX908817
Reg. Date: 26/05/2009

ATTN: MR. EDWARD
Your Ref No: SJQ7602J
Claim Type: Third Party
Accident Date:

Estimate Repair Cost to Vehicle No :SJQ7602J

Description	Quantity	List Price	Amount
		SS	SS
Labour Charges:			
1 TO PUTTY, RESPRAY PAINTING & POLISH ACCIDENT AREA. <u>FRONT</u> PORTION.	1 JOB	2,180.00	400 400
2 TO SPRAY RUST PROOFING	1 JOB	280.00	80
3 TO REMOVE & REFIT REAR WINDSCREEN & MOULDING & WINDSCREEN INNERSHIELD.	1 JOB	295.00	100 100
4 TO REMOVE & FIX IN REVERSE SENSOR	1 JOB	180.00	60
5 TO REMOVE & REFIT EXHAUST & HEATSHIELD.	1 JOB	250.00	X
6 TO CUT & WELD TAIL LAMP PANEL LEFT & RIGHT, END PANEL, SPARE TYRE PANEL WELL, CHASSIS LEFT & RIGHT, REAR LEFT FENDER. REAR DOOR ALIGNMENT & BOOT COVER.	1 JOB	2,800.00	800
7 UNDERCOATING	1 JOB	280.00	100 60
8 TO REMOVE & REFIT REAR AXLE.	1 JOB	450.00	X
9 WHEEL ALIGNMENT	1 JOB	80.00	X
10 TO REMOVE & REFIT FUEL TANK	1 JOB	250.00	X
		7,045.00	7,045.00
		Total	SS 7,045.00

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND FORTY FIVE ONLY

For C L Auto Pte Ltd

AUTHORISED SIGNATURE

