

**YEW HOCK MOTOR**

Reg. no: 251827/00C

Blk 9006 Tampines Street 93 #01-210 Singapore 528840

Tel: 67472384 Fax: 67482758

LKK (Nibita called on: 29/11/2019  
@ : 10.45 AmTo Arrange For Survey. Surveyor will  
Come In The Afternoon.DATE: 28/11/2019  
(To Be Survey by LKK)MS GAN YUE LYE TRINA  
BLK 9006 TAMPINES STREET 93  
#01-210  
SINGAPORE 528840

|                  |   |              |
|------------------|---|--------------|
| VEHICLE NUMBER   | : | SMN 7912 U   |
| MODEL            | : | BMW 428I "15 |
| DATE OF ACCIDENT | : | 25/11/2019   |
| THIRD PARTY      | : | GBH 206 H    |

(TAMPINES)

**REPLACEMENT OF PARTS****(NETT ITEMS)**

|        |                                                    |          |
|--------|----------------------------------------------------|----------|
| 1 PC   | FRONT BONNET / BT                                  | 1,537.40 |
| 2 PCS  | FRONT BONNET HINGE @\$90.10 X                      | 180.20   |
| 2 PCS  | FRONT BONNET ABSORBER @\$142.40 X                  | 284.80   |
| 1 PC   | FRONT BONNET LOCK X                                | 106.10   |
| 1 PC   | FRONT BONNET INSULATOR ?                           | 221.10   |
| 15 PCS | FRONT BONNET INSULATOR CLIPS @\$6.00 / Mc.         | 90.00    |
| 1 PC   | FRONT HEAD LAMP / Cwt - BT.                        | 2,130.35 |
| 1 PC   | FRONT HEAD LAMP BRACKET / BT.                      | 132.15   |
| 1 PC   | FRONT FENDER - Bnc                                 | 702.65   |
| 1 PC   | FRONT FENDER COWLING (FRONT) ?                     | 67.95    |
| 1 PC   | FRONT FENDER COWLING (CENTRE) ??                   | 117.15   |
| 1 PC   | FRONT FENDER COWLING (REAR) ??                     | 117.15   |
| 15 PCS | FRONT FENDER COWLING CLIPS @\$5.00 / Mc.           | 75.00    |
| 1 PC   | FRONT FENDER M LOGO - Mc.                          | 98.80    |
| 1 PC   | FRONT FENDER GARNISH ?                             | 58.25    |
| 1 PC   | FRONT FENDER TOP SIDE MOULDING ?                   | 33.20    |
| 6 PCS  | FRONT FENDER TOP SIDE MOULDING CLIPS @\$5.00 / Mc. | 30.00    |
| 1 PC   | FRONT FENDER BRACKET / BT                          | 42.10    |
| 1 PC   | FRONT FENDER CENTRE BRACKET ?                      | 42.10    |
| 1 PC   | ROCKER PANEL SIDE SKIRT X                          | 466.90   |
| 10 PCS | ROCKER PANEL SIDE SKIRT CLIPS @\$6.00 X            | 60.00    |
| 1 PC   | FRONT BUMPER ?                                     | 1,568.10 |
| 2 PCS  | FRONT BUMPER SIDE BRACKET @\$48.20 ?               | 96.40    |
| 10 PCS | FRONT BUMPER CLIPS @\$6.00 / Mc.                   | 60.00    |

# YEW HOCK MOTOR

Reg. no: 251827/00C

Blk 9006 Tampines Street 93 #01-210 Singapore 528840

Tel: 67472384 Fax: 67482758

LABOUR CHARGES TO REMOVE AND REPLACE ALL  
DAMAGED PARTS.

SPRAY PAINTING ON AFFECTED AREAS.

TOTAL BEFORE GST :

650.00


800.00

\$ 9,767.85

500

750.

YOURS FAITHFULLY,



5 Days -

part by part.

Get all paint photos.

Guo Qiang - 82880282

29/11/19.

**LINK Auto Consultants hence notify  
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: