

S9 MOTOR TRADING PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 29 November 2019

To : LKK

By Fax: 6256-4315

Attn :

Tel:

VEHICLE NO : FBE 3129T

Piaggio Gilera Runner ST200

ACCIDENT DATE: 24 November 2019

Description	Qty	Quotation \$
1 Horn Cover <i>broken</i>	1	90.00 ✓
2 Handle Bar <i>hhl</i>	1	260.00 X
3 Brake Lever <i>end</i>	1	165.00 ✓
4 Front Panel <i>broken</i>	1	170.00 ✓
5 Head Lamp Assy <i>broken</i>	1	450.00 ✓
6 Front Side Cover L/RH <i>end / broken</i>	2	350.00 ✓
7 Front Signal <i>broken</i>	2	140.00 ✓
8 Front Mudguard <i>end</i>	1	250.00 ✓
9 Front Rim <i>hhl</i>	1	280.00 X
10 Fork Tube <i>hhl</i>	1 set	480.00 X
11 Fork Under Bracket <i>hhl</i>	1	155.00 X
12 Brake Disc <i>hhl</i>	1	165.00 X
13 Belly Pan <i>broken</i>	1	155.00 ✓
14 Front RH/LH Gilera Cover (Black) <i>end broken</i>	2	560.00 ✓
15 Leg Shield - Inner <i>broken o/s h/s</i>	1	165.00 ✓
16 Rear RH Side Panel <i>end</i>	1	175.00 ✓
17 Exhaust Guard <i>end</i>	1	258.00 ✓
18 Rear Mudguard <i>broken</i>	1	280.00 ✓
19 Rear Signal <i>h/s broken</i>	2	140.00 ✓
20 Shock Absorber <i>hhl</i>	2	360.00 X

Sub-Total 5,048.00

Less 10% 504.80

Sub-Total 4,543.20

21.) Rider Seat *hhl* ✓

Signature: _____
Date: _____

Acknowledged by Repairer

is subject to final approval from Insurance Company and
Supplementary items must be received and
No illegal modification(s) is allowed
Third Party survey is on a "Without Prejudice" basis
Parts prices are subject to confirmation
To identify damaged parts during repair
the Repairer is following:
LKK Auto confirms hence notify

VEHICLE NO : FBE 3129T

Piaggio Gilera Runner ST200

Nett Items

1	Rear box <i>broken</i>	380.00 180/-
2	Rear number plate <i>1st</i>	15.00 ✓
3	Towing fee <i>1st</i>	40.00 X
4	Remove & replace necessary parts, align & etc	380.00 200/-
5	Remove & replace fork assy, rim, brake disc, shock absorber, align & etc	250.00 <i>44</i>
6	Putty & respray paint	480.00 180/-
7	Check electric wiring	80.00 30/-
8	Front number plate <i>44</i>	15.00 X

Sub-Total 1,640.00
Nett Total 6,183.20

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion.
Thank you

S9 MOTOR TRADING PTE LTD

:LG

29/11/2019 @ 1300h
NA Andrew
L/Prm
R yan 4 days
Check MV
LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: