



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

QBE INSURANCE (SINGAPORE) PTE LTD
1 RAFFLES QUAY #29-10 SOUTH TOWER
SINGAPORE 048583

INV No. AC2007443
INV Date 06/11/2020
Reference CC6/QBE19021171/Aka3q2
Code QBE



PROFESSIONAL SERVICE FEE

Vehicle No. SJF 7076K
Insured Veh. SMD 1572J
Claim No. VC013195
Policy No. 8-V0023172-MVA
Accident Date 13/11/2019
Inspection Date 27/11/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

QBE INSURANCE (SINGAPORE) PTE LTD

Ref : CC6/QBE19021171/Aka3q2

1 RAFFLES QUAY #29-10 SOUTH
TOWERSINGAPORE 048583

Date : 06-11-2020



Code : QBE

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMD 1572J	Veh. Inspected	SJF 7076K
Policy No.	8-V0023172-MVA	Coverage (\$)	0.00
Claim No.	VC013195	Excess (\$)	0.00
Assign From		Assign Date	27/11/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA CIVIC	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	MRHFC5650JT000094	Colour	BLUE
Odometer	36287	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R16	HANKOOK	6 mm
L/H Front Tyre	215/55 R16	HANKOOK	6 mm
R/H Rear Tyre	215/55 R16	HANKOOK	6 mm
L/H Rear Tyre	215/55 R16	HANKOOK	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	13/11/2019	Inspection Date	27/11/2019
Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJF 7076K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT RH DOOR SIDE MIRROR	NOT NECESSARY	84.50	-
1	FRONT RH DOOR SIDE MIRROR COVER	MISSING	149.80	149.80
1	FRONT RH DOOR SIDE MIRROR HOUSING	CRACKED	278.50	278.50
	LESS 20% DISCOUNT		-102.56	-85.66
			410.24	342.64
	<u>LABOUR</u>			
	REMOVE ,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT .		800.00	100.00
	RESPRAY PAINTING.		800.00	200.00
			1,600.00	300.00
GRAND TOTAL			2,010.24	642.64
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				500.00

Report Ref No. CC6/QBE19021171/Aka3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJF 7076K

INSPECTION






LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJF 7076K

RE-INSPECTION

