Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19021187/UKA3Q2

Date: 12/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900150165

Claimant Vehicle No: SKV9336B Insured Vehicle No: SMN5892G

Date of Loss: 01/12/2019 Nature of Claim: TP Claim No: 9402262612SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKV9336B

Make & Model: VOLKSWAGEN TOURAN, 1.4 TSI (A) Engine No: CTH005905

Reg. Date: 31/10/2012 (Man. Year: 2012) Chassis No: WVGZZZ1TZDW031318

Colour: Silver Odometer: 112473 km

Engine Capacity: 1390 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45Z R17 Rear Tyre Size: 225/45Z R17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,205.80	2,005.20	1,200.60	37.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,145.00	1,255.00	890.00	41.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,350.80	3,260.20	2,090.60	39.07
Approved Total (Overridden) (S\$)		2,600.00		
(S\$)	5,350.80	2,600.00	2,750.80	51.41
+ GST 7.00/7.00% (S\$)	374.56	182.00	192.56	51.41
Nett Amount (S\$)	5,725.36	2,782.00	2,943.36	51.41
+ Loss of Use (4.0 x S\$	240.00			
+ Doc/S	2.00			
Ne	3,024.00			
Global Sum S	3,020.00			

INSPECTION

Date of Assignment: 02/12/2019

Date Inspected: 02/12/2019 Inspected At: NPH Auto Service (HQ)

Blk 9005 Tampines Steet 93, #01-

246/254

Singapore 528839

Estimated Period of Repair: 4.0 days

Adjuster Report Page 2 of 4

Adjuster: MARCUS CHUA Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	. Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT TSI EMBLEM	Necessary	90.00 FL	*90.00 FL
2	1		*REAR BOOT TOURAN EMBLEM	Necessary	90.00 FL	*90.00 FL
3	1		*REAR LAMP ASSY RH	Scratched	250.00 FL	*250.00 FL
4	1		*REAR LAMP LOWER BUMPER RETAINER	Not Necessary	38.00 FL	*- FL
5	1		*REAR BUMPER SIDE RETAINER	Not Necessary	45.00 FL	*- FL
6	1		*REAR BUMPER	Dented	1,040.00 FL	*1,040.00 FL
7	1		*REAR BUMPER REINFORCEMENT	Bent	532.00 FL	*532.00 FL
8	1		*REAR BUMPER PARKING SENSOR (3 PCS)	Shorted (1 PCS ONLY)		*170.00 FL
9	1		*REAR BUMPER TOWING HOOK	Not Necessary	42.00 FL	*- FL
10	1		*REAR BUMPER REFLECTOR LAMP	Scratched	56.00 FL	*56.00 FL
11	1		*REAR BOOT RUBBER	Not Necessary	325.00 FL	*- FL
12	1		*REAR PARKING SENSOR WIRE	Not Necessary	544.00 FL	*- FL
F=Fra	anchise	part. L=List	ItemDisc.			
Sub Total (S\$)					3,562.00	2,228.00
- List Item Discount on L Items 10.00/10.00% (S\$)						222.80
				Total Parts (S\$)	3,205.80	2,005.20
			Report was unsubmitted duri	ng this print-out.		

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount					
Lab	<u>Labour Items</u>								
1	REMOVE & INSTALL R/LAMP ,R/BUMPER ,KNOCK R/BOOT,R/FENDER ,R/LAMP CENTER PANEL ,R/LA PANEL AND RESTRAIGHTEN BODY & CHASSIS	New MP	850.00	500.00					
2	SPRAY PAINTING	New	1,000.00	600.00					
3	CHECK WIRING SYSTEM & RE-WIRING	New	25.00	25.00					
4	RESET PARKING SENSOR	New	150.00	50.00					
5	REMOVE & INSTALL REAR BOOT CARPET	New	120.00	80.00					
	Gross	Labour Cost (S\$)	2,145.00	1,255.00					

Report was unsubmitted during this print-out.

< END OF ESTIMATES >