



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref :

Our Ref : TP0087/12/19

Page : 1/2

Date : 03/12/2019

M/S :

THIRD PARTY CLAIM

LIONEL GAN HSIEN WEI
BLK 245 TAMPINES STREET 21
#09-317
SINGAPORE 521245

Attn :

Dear Sir/Madam

RE: ACCIDENT REPAIR ON : SKV9336B - VOLKWAGON TOURAN
INSURED : LIONEL GAN HSIEN WEI
DATE OF ACCIDENT : 01/12/2019
POLICY NO : MP308318

ENGINE# :
CHASSIS# :

not Arthur
2/12/19
1/3 \$2600
4 day

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
Replacement of Parts				
1 rear boot TSI emblem	10	90.00	90.00	90.00 ✓
2 rear boot TOURAN emblem	10	90.00	90.00	90.00 ✓
3 rear lamp assy RH	10	250.00	250.00	250.00 ✓
4 rear lamp lower bumper retainer	11	38.00	38.00	38.00 X
5 rear bumper side retainer	11	45.00	45.00	45.00 X
6 rear bumper	10	1040.00	1040.00	1,040.00 ✓
7 rear bumper reinforcement	10	532.00	532.00	532.00 ✓
8 rear bumper parking sensor	30	170.00	170.00	510.00 ✓
9 rear bumper towing hook	11	42.00	42.00	42.00 X
10 rear bumper reflector lamp	10	56.00	56.00	56.00 ✓
11 rear boot rubber	11	325.00	325.00	325.00 X
12 rear parking sensor wire	11	544.00	544.00	544.00 X
				3,562.00
Less 10%				-356.20
Total Material				\$3,205.80
Labour & Misc				

- 1 Remove & install r/lamp, r/bumper, knock r/boot, r/fender, r/lamp center panel, r/lamp panel and restraighthen body & chassis.
- 2 Spray painting.
- 3 Check wiring system & re- wiring.
- 4 Reset parking sensor.
- 5 Remove & install rear boot carpet.

850.00 500
1,000.00 600
25.00
150.00 50
120.00 80
2,145.00

Total Labour

Nett Total Before Gst

\$2,145.00

\$5,350.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-2228
102
2025.20
3260.20