

HUA CHIN (2000) TRADING MOTOR SERVICE CENTRE

50, Bukit Batok Street 23, #02-02 Midview Building, Singapore 659578

TEL : 6896 6619

M/S : FWD INSURANCE
6 Temasek Blvd, #18-01 Suntec Tower Four,
Singapore 038986
Email : contact.sg@fwd.com
Tel : 6820 8888 (Hotline)
Your Ref No : FBK1798T
Claim Type : Third-Party
Accident Date : 28.11.2019 16:55HRS
TP Veh Reg No : SGW34225

Estimate No : Y.005
Date : 02.12.2019
Policy No : -
Veh Reg No : FBK1798T
Make/Model : HONDA MSX125
Chasis No : MLHJC61A0F5200181
Engine No : JC61E2201619
Reg Date : 02.12.2019

Estimate Repair Cost to Vehicle No : FBK1798T

Description	Quantity	Amount
<u>List Price</u>		
1 Side Mirror <i>SCA</i>	1 pc	\$80.00 <i>40</i>
2 Rear Signal, L/R <i>X nn</i>	2 pc	\$240.00 <i>X</i>
3 Front signal, L/R <i>X nn</i>	2 pc	\$240.00 <i>X</i>
4 Handle Bar <i>bt</i>	1 pc	\$60.00
5 Brake Lever <i>X nn</i>	2 pc	\$80.00 <i>X</i>
6 Body Cover, LH <i>SCA</i>	1 pc	\$400.00
7 Body Cover Screw Set <i>SCA</i>	1 set	\$50.00
8 Front Fender <i>SCA</i>	1 pc	\$100.00 <i>X</i>
9 Engine Cover <i>SCA</i>	1 pc	\$120.00
10 Body Lower Cover, LH <i>SCA</i>	1 pc	\$220.00
11 Front Lamp <i>X nn</i>	1 pc	\$480.00 <i>X</i>
12 Gear Lever <i>bt</i>	1 pc	\$130.00
13 Throttle Cable <i>X nn</i>	1 pc	\$80.00 <i>X</i>
		\$2,280.00
	Less 10%	\$228.00
	Total	\$2,052.00
<u>S/NETT ITEMS</u>		
14 Rear Number Plate <i>bt</i>	1 pc	\$50.00 <i>30</i>
15 Front Number Plate <i>bt</i>	1 pc	\$50.00 <i>30</i>
16 Front Camera <i>X nn</i>	1 pc	\$180.00 <i>X</i>
17 Rear Camera <i>X nn</i>	1 pc	\$180.00 <i>X</i>
18 Camera Bracket <i>X nn</i>	1 set	\$45.00 <i>X</i>
		\$505.00
<u>Labour</u>		
12 To provide labour charges, workman ship to dismatle above damage parts.		\$500.00 <i>300</i>
13 To align main body frame.		\$200.00 <i>X</i>
14 To conduct wheel alignments.		\$150.00 <i>X</i>
15 To spray painting on affected area.		\$350.00 <i>250</i>
16 To spray anti-rust coating on new and affected area.		\$150.00 <i>60</i>
17 To check eletrical wiring.		\$80.00 <i>30</i>
		\$1,430.00
	Total	\$3,987.00

TOTAL : THREE THOUSAND NINE HUNDRED EIGHTY SEVEN ONLY.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Paul
Hp 90010068
4 days
W/S
02/12/2019
@ 1420
Resurvey after repair

Name :

Tel :

Date :

Sign :

1008
60
640
1708
202
1366
W/S - 1,350
4 days