

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Dec 2019 Edit Reg		29 Nov 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: LOW LEE PEOW , ID: S0233826B									
Main Claimant: KHAIRUL NIZAM BIN HASHIM , ID: S9902521B									
Vehicle Reg. No.: FBN9099J		Date of Loss: 26/11/2019 00:00 - :59 [10 Months and 26 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 2119159028SG		Policy/Cover Note No.: 2100459791 (Comprehensive)							
Vehicle Reg. No. (Insured): SJZ6248H		Policy No. (Claimant): D19MTMC01000140							
		Excess:							
Repairer: Hua Chin (2000) Trading Motor Service Centre (HQ) 50 BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING, 659578 Bukit Batok - Tel: 68966619									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Goh, Jeremy-CX] Jeremy.Goh@aig.com									
Claimant's Insurer: Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 11/12/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG (03/12/2019): TP GIA report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBN9099J (2119159028SG)**
[SJZ6248H]

TP

KHAIRUL NIZAM BIN HASHIM

Nov 26 2019 12:00AM

[LOW LEE PEOW]

Hua Chin (2000) Trading Motor Service Centre

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View
[View in Browser](#)

Photos/Images					
			3 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/04/20 15:41	Odometer Reading		Load JPG	
2	28/04/20 15:42	General View		Load JPG	
3	28/04/20 15:42	General View		Load JPG	
4	28/04/20 15:42	General View		Load JPG	
5	28/04/20 15:42	General View		Load JPG	
6	28/04/20 15:42	General View		Load JPG	
7	28/04/20 15:42	General View		Load JPG	
8	28/04/20 15:42	General View		Load JPG	
9	28/04/20 15:42	General View		Load JPG	
10	28/04/20 15:42	General View		Load JPG	
11	28/04/20 15:42	General View		Load JPG	
12	28/04/20 15:42	General View		Load JPG	
13	28/04/20 15:42	General View		Load JPG	
14	28/04/20 15:42	General View		Load JPG	
15	28/04/20 15:42	General View		Load JPG	
16	28/04/20 15:42	General View		Load JPG	
17	28/04/20 15:42	General View		Load JPG	
18	28/04/20 15:42	General View		Load JPG	
19	28/04/20 15:42	General View		Load JPG	
20	28/04/20 15:42	General View		Load JPG	
21	28/04/20 15:42	General View		Load JPG	
22	28/04/20 15:42	General View		Load JPG	
23	28/04/20 15:42	General View		Load JPG	
24	28/04/20 15:42	General View		Load JPG	
25	28/04/20 15:42	General View		Load JPG	
26	28/04/20 15:42	General View		Load JPG	
27	28/04/20 15:42	General View		Load JPG	
28	28/04/20 15:42	General View		Load JPG	
29	28/04/20 15:42	General View		Load JPG	
30	28/04/20 15:42	General View		Load JPG	
31	28/04/20 15:42	General View		Load JPG	
32	28/04/20 15:42	General View		Load JPG	
33	28/04/20 15:42	General View		Load JPG	
34	28/04/20 15:42	General View		Load JPG	
35	28/04/20 15:42	General View		Load JPG	
36	28/04/20 15:42	General View		Load JPG	
37	28/04/20 15:42	General View		Load JPG	
38	28/04/20 15:42	General View		Load JPG	
39	28/04/20 15:42	General View		Load JPG	
40	28/04/20 15:42	General View		Load JPG	

Photos/Images			3 per page	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
41	28/04/20 15:42	General View		Load JPG ✓
42	28/04/20 15:42	General View		Load JPG ✓
43	28/04/20 15:42	General View		Load JPG ✓
44	28/04/20 15:42	General View		Load JPG ✓
45	28/04/20 15:42	General View		Load JPG ✓
46	28/04/20 15:42	General View		Load JPG ✓
47	28/04/20 15:42	General View		Load JPG ✓
48	28/04/20 15:42	General View		Load JPG ✓
49	28/04/20 15:42	General View		Load JPG ✓
50	28/04/20 15:42	General View		Load JPG ✓
51	28/04/20 15:42	General View		Load JPG ✓
52	28/04/20 15:42	General View		Load JPG ✓
53	28/04/20 15:42	General View		Load JPG ✓
54	28/04/20 15:42	General View		Load JPG ✓
55	28/04/20 15:42	General View		Load JPG ✓
56	28/04/20 15:42	General View		Load JPG ✓
57	28/04/20 15:42	General View		Load JPG ✓
58	28/04/20 15:42	General View		Load JPG ✓
59	28/04/20 15:42	General View		Load JPG ✓
60	28/04/20 15:42	General View		Load JPG ✓
61	28/04/20 15:42	General View		Load JPG ✓
62	28/04/20 15:42	General View		Load JPG ✓
63	28/04/20 15:42	General View		Load JPG ✓
64	28/04/20 15:42	General View		Load JPG ✓
65	28/04/20 15:42	General View		Load JPG ✓
66	28/04/20 15:42	General View		Load JPG ✓
67	28/04/20 15:42	General View		Load JPG ✓
Documentation			1 per page	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	05/12/19 15:49	EMAIL FROM AIG DD 29112019		Load PDF
2	13/12/19 09:10	TP GIA REPORT		Load PDF
3	29/07/20 17:07	Email to AIG on 29072020		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	03/12/19 16:03	OI GIA REPORT		Load PDF
2	12/05/20 09:48	PIR		Load JPG ✓

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG19021192/R1DA3S2**Date:** 06/08/2020**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100459791
Claimant Vehicle No :	FBN9099J	Insured Vehicle No :	SJZ6248H
Date of Loss:	26/11/2019	Nature of Claim:	TP
		Claim No:	2119159028SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN9099J	Engine No:	G3E6E0443393
Make & Model:	YAMAHA MX KING T150, 150cc	Chassis No:	MH3UG0710JK280299
Reg. Date:	31/12/2018 (Man. Year: 2018)	Odometer:	13483 km
Colour:	Red		
Engine Capacity:	150 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	80/80-17	Rear Tyre Size:	90/80-17
Front Left Side:	Maxxis 3 mm	Rear Left Side:	Maxxis 3 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	29/11/2019	Hua Chin (2000) Trading Motor Service Centre (HQ)
Date Inspected:	02/12/2019 Inspected At:	50 BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING
Estimated Period of Repair:	3.0 days	Singapore 659578

Adjuster: MOHD RASUL**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WING MIRROR RH	Missing	0.00 F	*- F
2	1		*CLUTCH LEVER	Scratched	0.00 F	*- F
3	1		*FRONT FOOT REST LH	Scratched	0.00 F	*- F
4	1		*CLUTCH ENGINE COVER	Scratched	0.00 F	*- F
5	1		*FOOT GEAR SHIFTER	Bent	0.00 F	*- F
6	1		*EXHAUST MUFFLER HEAT SHIELD	Scratched	0.00 F	*- F
7	1		*EXHAUST MUFFLER ASSY	Bent	0.00 F	*- F
8	1		*REAR FENDER WHEEL GUARD	Deformed	0.00 F	*- F
9	1		*SWING ARM	Repair	0.00 F	*- F
10	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
11	1		*REAR NUMBER PLATE LIGHT	Scratched	0.00 F	*- F
					Total Parts (S\$)	0.00 0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >