

ASS. REC. BY:

REF:

TMI / CC3 TMI19021194 / Ktd3n2

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Trans Cab

Insured: SLK 5a13H

Policy No. MK000574

Claims No. m1909308


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Soon: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 2 1/2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: S110 9970A Yr Regn: 061 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Latitude c.c. 1995

Colour M. White/Red A/C: Insured / Std / NI / NA

Sp. Reading 107770 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: V11 ABL15AUC 278259

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: MH S/Rlm / STD A/Rlm or

Tyre Size: F: 215/80R16 R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Pailun

Front

R/Bal. 2 mm

L/Bal. 2 mm

D.O.A. 27/11/19

Survey held at: \_\_\_\_\_

Rear

R/Bal. 2 mm

L/Bal. 2 mm

D.O.I. 29/11/19

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 / File pass to

11/12 - Revert via email preliadvise GIA & est. 11/12 @ 3poch (Red: 26/66.39; 87%)

S110 9970A - X  
SLK 5a13H - CS1195918001530 / Syby 2

DOA: 20/11/2018

RECEIVED 11 DEC 2018

Date/Time, File Pass to?

: Prell. Report  
 : Final Report

1) 11/12 Typist

Date/Time, File Return to?

Days Of Repair: 2.5

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation:

S - RS \$

Fees

Others

TOTAL

Add Fee:  : Site Insp (\$)  
 : Interview (\$)  
 : Tech Invs (\$)  
 : Weekend (\$)

250
11
261

Report Format :

Lump Sum / I.B.I. (\$) 3900/-



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 2/12/2019

Our Ref: CC3/TMI19021194/Ktd3

The Motor Claims Department  
MS FIRST CAPITAL INSURANCE LTD

Dear Sirs/Mdm


**PRELIMINARY ADVICE OF VEHICLE NO. SHD 9970A.**

Please be informed that we had conducted the inspection of the above-mentioned vehicle on 29/11/2019 at the premises of M/s Trans Cab and have the following to report: -

Workshop Estimate Amount	: S\$ <u>30,066.39</u>
Revised Estimate Amount	: S\$ <u>4,894.12</u>
"Check" Items Amount	: S\$ <u>0.00</u>
Market Value	: S\$ <u>          </u>
LTA Reimbursement Value	: S\$ <u>          </u>
Nett Value	: S\$ <u>          </u>

**Description of Damage:**

The vehicle sustained damages at the n/s front portion.



Repair days: 2.5

**Comments/ Present Status:**

Damages Consistent.

Yours faithfully

Kenneth

Automotive Assessor

## Denise Tay (LKKAuto)

---

**From:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Sent:** Wednesday, 4 December 2019 9:19 AM  
**To:** Denise Tay (LKKAuto)  
**Subject:** RE: SHD 9970A DOA: 28/11/2019 -- AAD1911-226

WITHOUT PREJUDICE

Dear Denise

Amount confirmed \$ 3,900 (before GST).

Thank You  
Best Regards,  
**Ng Wai Yin**  
Finance Department  
TEL: 6603 1265 Ext.308

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**

TRANS-CAB SERVICES PTE LTD  
No. 2 Ang Mo Kio Street 63  
Singapore 569111  
Tel: 6287 6666 Fax: 6287 7764

---

**From:** Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]  
**Sent:** Tuesday, 3 December, 2019 2:11 PM  
**To:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Subject:** RE: SHD 9970A DOA: 28/11/2019

Dear Wai Yin,

Can confirm?

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Monday, 2 December 2019 2:29 PM  
**To:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Subject:** SHD 9970A DOA: 28/11/2019

Dear Wai Yin,

Lump sum \$3900, 2.5days.

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Monday, 2 December 2019 2:23 PM  
**To:** motorclaims@tokiomarine.com.sg  
**Cc:** SUR  
**Subject:** RE: DIRECT SURVEY INSPECTION ON WORKSHOP -TRANS-CAB AUTO SERVICES PTE LTD, DOA: 28/11/2019, SHD 9970A (TP VEHICLE), SLK 5913H (OI VEHICLE)  
**Attachments:** PRELI ADVISED OF SHD 9970A.pdf; SHD 9970A ESTIMATE.pdf; GIA.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHD 9970A at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 12/11/2019.

Enclosed herewith a copy of TP's GIA, police report and estimated cost of repair.

Kindly create claim in merimen for our necessary action.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> [Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	878K
<b>Vehicle Details</b>	
Vehicle No.:	SHD9970A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	28 Nov 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001576
Chassis No.:	VF1ABL15AUC278259
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	05 Jun 2014
First Registration Date:	05 Jun 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Jun 2022
PARF Rebate Amount:	\$8,748.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	04 Jun 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$57,338.00
COE Rebate Amount:	\$18,055.00
<b>Total Rebate Amount:</b>	<b>\$26,803.00</b>
<b>Message</b>	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 28 Nov 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	28/11/2019 09:24
Date Of Accident	28/11/2019 00:10
Exact Location Of Accident	ORCHARD LINK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD9970A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P1680520
Cover Note Number	

### Driver

Name of Driver	TAN LIN SIN
NRIC No	S0188802A
Date Of Birth	27/02/1954
Occupation	OUTDOOR
Date Of Driving Pass	10/10/1983
Driving Experience	36 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98578509
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 468 ANG MO KIO AVE 10 #04-982
Postcode	560468
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

On 28.11.2019 at about 0007hours, I was stationary on the extreme right lane along Orchard Link to pick up my passenger with hazel light on. While stationary, suddenly I felt an impact. Vehicle B (SLK5913H) hit onto my taxi's rear portion.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLK5913H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**SKETCH PLAN**


**IMPORTANT NOTICE**


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


as see attach GA Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9970A**

AAD1911-226

*Not Authorised*  
*1/1/2014 @ 3900*

Vehicle No.:  
Chassis No.:  
Vehicle Make:  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :  
Date of Registration :

**SHD 9970A**  
VF1ABL15AUC278259  
RENAULT  
LATITUDE  
28.11.19  
**TOKIO MARINE**  
5/6/2014

	<b>PART</b>		<b>LIST</b>	
1	1 BUMPER COVER REAR	\$	<i>Bu</i> 561.70	✓
2	1 BUMPER LOWER REAR	\$	<i>Weld</i> 411.90	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sm</i> 98.10	} X
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>Sm</i> 82.10	
5	1 BUMPER RETAINER RH REAR	\$	<i>Sm</i> 59.80	
6	1 BUMPER REFLECTOR RH	\$	<i>Sm</i> 16.60	
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>Sm</i> 80.80	
8	1 BUMPER RETAINER LH REAR	\$	<i>Sm</i> 54.20	
9	1 BUMPER REFLECTOR LH	\$	<i>Sm</i> 16.60	
10	1 BUMPER BEAM REAR	\$	<i>Bu</i> 547.80	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>K</i> 114.50	X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>K</i> 100.90	X
13	1 OUTER PANEL REAR (End Panel)	\$	<i>K</i> 745.80	X
14	1 OUTER PANEL REAR (End Panel) TRIM	\$	<i>Sm</i> 404.56	X
15	1 TAILLAMP RH	\$	<i>Sm</i> 313.10	X
16	1 TAILLAMP PANEL RH	\$	<i>K</i> 401.40	X
17	1 TAILLAMP LH	\$	<i>Sm</i> 401.40	X
18	1 TAILLAMP PANEL LH	\$	<i>K</i> 401.40	X
19	1 BOOT REAR	\$	<i>Bu</i> 1,677.20	✓
20	1 BOOT FINISHER	\$	<i>Sm</i> 344.70	X
21	1 BOOT WHEATERSTRIP	\$	<i>Sm</i> 178.20	X
22	1 BOOT REFLECTOR LAMP LH	\$	<i>Sm</i> 277.70	X
23	1 BOOT REFLECTOR LAMP RH	\$	<i>Sm</i> 277.70	X
24	1 BOOT BADGE 'RENAULT'	\$	<i>Sm</i> 82.40	✓
25	1 BOOT BADGE	\$	<i>Sm</i> 95.80	✓
26	1 BOOT STRUT LH	\$	<i>Sm</i> 145.10	X

**Trans-cab Auto Services Pte Ltd**

AAD1911-226

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9970A**

27	1	BOOT STRUT RH	\$	Sn	145.10	}
28	1	BOOT HINGE LH	\$	n	254.20	
29	1	BOOT HINGE RH	\$	n	253.80	
30	2	BOOT RUBBER PLUG	\$	Sn	139.90	
31	2	BOOT BUFFER	\$	Sn	26.80	
32	1	BOOT LOCK LINKAGE	\$	Sn	20.60	
33	1	BOOT LOCK LINKAGE HOLDER	\$	Sn	99.50	
34	1	BOOT INNER TRIM BOARD	\$	Sn	611.00	
35	1	BOOT SWITCH	\$	Sn	113.00	
36	1	BOOT LOCK	\$	n	246.60	
37	1	BOOT LOCK CATCH	\$	n	41.70	
38	1	EXHAUST REAR	\$	n	5,263.60	
39	1	EXHAUST CAP REAR	\$	n	125.40	
<b>TOTAL</b>			<b>\$</b>		<b>15,232.66</b>	
			<b>10%</b>	<b>\$</b>	<b>1,523.27</b>	
				<b>\$</b>	<b>13,709.39</b>	

**Special Nett**

1	1SET	PARKING AID	\$	phot	700.00	400sn
2	1SET	REAR BUMPER CLIP	\$	na	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00	—
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1	BOOT STICKER "Trans-cab"	\$	na	30.00	—
11	1	BOOT STICKER "6555-3333"	\$	na	30.00	—
12	2	REAR WINDSCREEN SEALANT	\$	na	80.00	}
13	1	WINDSCREEN MOULDING	\$	na	100.00	
14	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
15	1	BOOT INNER TRIM CLIP	\$	na	45.00	
16	1SET	BOOT FINISHER CLIP	\$	na	24.20	
17	1	TAILLAMP CLIP LH	\$	na	5.00	X

**Trans-cab Auto Services Pte Ltd**

AAD1911-226

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9970A**

18	1	TAILLAMP CLIP RH	\$	<i>na</i> 5.00	X
19	1	Rear Bumper Protector	\$	<i>na</i> 100.00	X
20	1	EXHAUST MOUNTING REAR	\$	<i>na</i> 16.00	X
21	1	EXHAUST BRACKET REAR	\$	<i>na</i> 24.80	X
<b>TOTAL</b>			<b>\$</b>	<b>1,507.00</b>	

<b>TOTAL PARTS</b>	<b>\$</b>	<b>15,216.39</b>
--------------------	-----------	------------------

**LABOUR**

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	<i>601</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>301</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	<i>601</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>4001</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>na</i> 170.00	X
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00	X

**Trans-cab Auto Services Pte Ltd**

**AAD1911-226**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9970A**

To repair and realign rear exhaust pipe.	\$	<i>~</i> 170.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>~</i> 170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>~</i> 380.00	X
Putty and spray painting of the affected portion.	\$	6,000.00	<i>6601</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>~</i> 170.00	X
Towing Fees	\$	<i>~</i> 170.00	X
<b>TOTAL</b>	<b>\$</b>	<b>14,850.00</b>	
<b>Over All Total</b>	<b>\$</b>	<b>30,066.39</b>	

**LUMP SUM ( REPAIR DAY)**

**20 DAYS**

*2 1/2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19021194/KTD3N2

Date: 06/12/2019

**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MK000574
Claimant Vehicle No :	SHD9970A	Insured Vehicle No :	SLK5913H
Date of Loss:	27/11/2019	Nature of Claim:	TP
		Claim No:	M1909308

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	SHD9970A	Engine No:	M9R8839C001576
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC278259
Reg. Date:	05/06/2014 (Man. Year: 2014)	Odometer:	107770 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Sailun 8 mm	Rear Left Side:	Sailun 8 mm
Front Right Side:	Sailun 8 mm	Rear Right Side:	Sailun 8 mm

The above values represent the remaining tyre treads depth

**COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %	
Parts	15,216.39	3,664.12	11,552.27	75.92	
Miscellaneous Items	0.00	0.00	0.00		
Labour	14,850.00	1,230.00	13,620.00	91.72	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
<b>Calculated Gross Total (S\$)</b>	<b>30,066.39</b>	<b>4,894.12</b>	<b>25,172.27</b>	<b>83.72</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>3,900.00</b>			
	(S\$)	30,066.39	3,900.00	26,166.39	87.03
<b>+ GST 7.00/7.00% (S\$)</b>	2,104.65	273.00	1,831.65	87.03	
<b>Nett Amount (S\$)</b>	<b>32,171.04</b>	<b>4,173.00</b>	<b>27,998.04</b>	<b>87.03</b>	

**INSPECTION**

Date of Assignment:	02/12/2019	
Date Inspected:	29/11/2019	Inspected At:
		Trans Cab Auto Services Pte Ltd - Amk (HQ)
		No 2 Ang Mo Kio St 63
		Singapore 569111
Estimated Period of Repair:	2.5 days	

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 06 Dec 2019)
<b>Parts:</b> 143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD9970A)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	561.70 FL	*561.70 FL
2	1		*BUMPER LOWER REAR	Dented/Distorted	411.90 FL	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*-FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*-FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*-FL
6	1		*BUMPER REFLECTOR RH	Serviceable	16.60 FL	*-FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	*-FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*-FL
9	1		*BUMPER REFLECTOR LH	Serviceable	16.60 FL	*-FL
10	1		*BUMPER BEAM REAR	Bent	547.80 FL	*547.80 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	114.50 FL	*-FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	100.90 FL	*-FL
13	1		*OUTER PANEL REAR (END PANEL)	Repair	745.80 FL	*-FL
14	1		*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	404.56 FL	*-FL
15	1		*TAILLAMP RH	Serviceable	313.10 FL	*-FL
16	1		*TAILLAMP PANEL RH	Repair	401.40 FL	*-FL
17	1		*TAILLAMP LH	Serviceable	401.40 FL	*-FL
18	1		*TAILLAMP PANEL LH	Repair	401.40 FL	*-FL
19	1		*BOOT REAR	Bent	1,677.20 FL	*1,677.20 FL
20	1		*BOOT FINISHER	Serviceable	344.70 FL	*-FL
21	1		*BOOT WEATHERSTRIP	Serviceable	178.20 FL	*-FL
22	1		*BOOT REFLECTOR LAMP LH	Serviceable	277.70 FL	*-FL
23	1		*BOOT REFLECTOR LAMP RH	Serviceable	277.70 FL	*-FL
24	1		*BOOT BADGE RENAULT	Necessary	82.40 FL	*82.40 FL
25	1		*BOOT BADGE	Necessary	95.80 FL	*95.80 FL
26	1		*BOOT STRUT LH	Serviceable	145.10 FL	*-FL
27	1		*BOOT STRUT RH	Serviceable	145.10 FL	*-FL
28	1		*BOOT HINGE LH	Repair	254.20 FL	*-FL
29	1		*BOOT HINGE RH	Repair	253.80 FL	*-FL
30	2		*BOOT RUBBER PLUG	Serviceable	139.90 FL	*-FL
31	2		*BOOT BUFFER	Serviceable	26.80 FL	*-FL
32	1		*BOOT LOCK LINKAGE	Serviceable	20.60 FL	*-FL
33	1		*BOOT LOCK LINKAGE HOLDER	Serviceable	99.50 FL	*-FL
34	1		*BOOT INNER TRIM BOARD	Serviceable	611.00 FL	*-FL
35	1		*BOOT SWITCH	Serviceable	113.00 FL	*-FL
36	1		*BOOT LOCK	Repair	246.60 FL	*-FL
37	1		*BOOT LOCK CATCH	Repair	41.70 FL	*-FL
38	1		*EXHAUST REAR	Repair	5,263.60 FL	*-FL
39	1		*EXHAUST CAP REAR	Repair	125.40 FL	*-FL
40	1		*SET PARKING AID	Shorted	700.00 FS	*400.00 FS
41	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
42	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
43	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*-FS
44	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*-FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*-FS
46	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*-FS
47	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*-FS
48	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
49	1		*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
50	1		*BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS
51	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*-FS
52	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*-FS
53	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*-FS
54	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*-FS
55	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*-FS
56	1		*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*-FS
57	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*-FS
58	1		*REAR BUMPER PROTECTOR	Not Necessary	100.00 FS	*-FS
59	1		*EXHAUST MOUNTING REAR	Not Necessary	16.00 FS	*-FS
60	1		*EXHAUST BRACKET REAR	Not Necessary	24.80 FS	*-FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>16,739.66</b>	<b>4,001.80</b>
- List Item Discount on L Items 10.00/10.00% (\$)	1,523.27	337.68
<b>Total Parts (\$)</b>	<b>15,216.39</b>	<b>3,664.12</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	0.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
5	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
7	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	6,000.00	400.00
8	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
11	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
12	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
13	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH TO FACILITATE REPAIR	New	380.00	0.00
14	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	660.00
15	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
16	TOWING FEES	New	170.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>14,850.00</b>	<b>1,230.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >