

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD5090R - AIG**ROEL**

76	1	n/s front passenger seat LH	\$
77	1	Front Door RH	\$
78	1	Front side view mirror RH	\$
79	1	Front Door outer moulding RH	\$
80	1	Front Door outer handle RH	\$
81	1	Front Door outer handle inner seal RH	\$
82	1	Front Door outer key lock RH	\$
83	1	Front Door hinge upper RH	\$
84	1	Front Door hinge lower RH	\$
85	1	Front Door inner lock RH	\$
86	1	Front Door inner lock latch RH	\$
87	1	Front Door check / arrestor RH	\$
88	1	Front Door weatherstrip RH	\$
89	1	Front Door glass channel weatherstrip RH	\$
90	1	Front Door inner trim board RH	\$
91	1	Front Door window glass RH	\$
92	1	Front Door power motor RH	\$
93	1	Front Door power motor switch RH	\$
94	1	Front Door regulator gear RH	\$
95	1	Front Door channel felt / moulding RH	\$
96	1	Front Door benq locker bulk RH	\$
97	1	Front Door LH	\$
98	1	Front side view mirror LH	\$
99	1	Front Door outer moulding LH	\$
100	1	Front Door outer handle LH	\$
101	1	Front Door outer handle inner seal LH	\$
102	1	Front Door outer key lock LH	\$
103	1	Front Door hinge upper LH	\$
104	1	Front Door hinge lower LH	\$
105	1	Front Door inner lock LH	\$
106	1	Front Door inner lock latch LH	\$
107	1	Front Door check / arrestor LH	\$
108	1	Front Door weatherstrip LH	\$
109	1	Front Door glass channel weatherstrip LH	\$
110	1	Front Door inner trim board LH	\$
111	1	Front Door window glass LH	\$
112	1	Front Door power motor LH	\$
113	1	Front Door power motor switch LH	\$
114	1	Front Door regulator gear LH	\$
115	1	Front Door channel felt / moulding LH	\$
116	1	Front Door benq locker bulk LH	\$
117	1	Roof top panel	\$

R	2,458.45x
R	1,295.00 ✓
Sm	722.50 x ✓
Sm	161.40 x ✓
Sm	79.60 x ✓
Sm	38.70 x ✓
Sm	216.70 x ✓
R	96.30 x ✓
R	96.30 x ✓
Sm	426.60 ✓ ✓
R	98.20 x ✓
Sm	200.00 x ✓
78.90	157.80 50sm
	166.40 ? } NNX
	1,211.70 ? } NNX
Sm	399.70 x ✓
Sm	401.90 ✓ ✓
	361.20 7xNN
R	131.80 ✓
	291.90 7xNN
	301.20 7xNN
R	1,295.00 ✓
R	722.50 ✓
Sm	161.40 x ✓
Del	79.60 ✓ ✓
Sm	38.70 x ✓
	216.70 7xNN
R	96.30 x ✓
R	96.30 x ✓
Sm	426.60 ✓ ✓
R	98.20 x ✓
Sm	200.00 x ✓
78.90	157.80 50sm
Sm	166.40 x ✓
	1,211.70 7xNN
Sm	399.70 x ✓
	401.90 7xNN
	361.20 7xNN
	131.80 7xNN
Sm	291.90 x ✓
Sm	301.20 x ✓
R	2,899.70 x ✓

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD5090R - AIG**ROEL**

118	1	Roof top inner side panel outer LH	\$
119	1	Roof top inner side panel outer RH	\$
120	1	Roof side moulding - roof gutter LH	\$
121	1	Roof side moulding - roof gutter RH	\$
122	1	Roof lining	\$
123	1	Centre pillar outer LH	\$
124	1	Centre pillar inner LH	\$
125	1	Centre pillar outer RH	\$
126	1	Centre pillar inner RH	\$
127	1	Centre pillar reinforcement RH	\$
128	1	Centre pillar inner garnish - top RH	\$
129	1	Centre pillar inner garnish - lower RH	\$
130	1	Rocker panel outer RH	\$
131	1	Rocker panel outer LH	\$
132	1	Rear door RH	\$
133	1	Rear door weatherstrip RH	\$
134	1	Rear door top hinge RH	\$
135	1	Rear door bottom hinge RH	\$
136	1	Rear door inner lock RH	\$
137	1	Rear door check / arrestor RH	\$
138	1	Rear door lock striker / latch RH	\$
139	1	Rear door outer weatherstrip moulding RH	\$
140	1	Rear door outer handle RH	\$
141	1	Rear door outer handle - rubber seal RH	\$
142	1	Rear door inner opening handle RH	\$
143	1	Rear door inner trim board RH	\$
144	1	Rear door kicking plate / step garnish RH	\$
145	1	Rear door window glass channel weatherstrip RH	\$
146	1	Rear door window glass channel holder RH	\$
147	1	Rear door channel weatherstrip / felt RH	\$
148	1	Rear door interior light switch RH	\$
149	1	Rear door regulator gear RH	\$
150	1	Rear door regulator handle RH	\$
151	1	Rear door LH	\$
152	1	Rear door weatherstrip LH	\$
153	1	Rear door top hinge LH	\$
154	1	Rear door bottom hinge LH	\$
155	1	Rear door inner lock LH	\$
156	1	Rear door check / arrestor LH	\$
157	1	Rear door lock striker / latch LH	\$
158	1	Rear door outer weatherstrip moulding LH	\$
159	1	Rear door outer handle LH	\$

R ₁	166.70	✓
R	166.70	X
M ₁	201.30	✓
S ₁	201.30	X
S ₁	1,898.60	X
R	321.40	X
R	431.70	X
R ₁	321.40	✓
R ₁	431.70	✓
R ₁	511.90	✓
	201.70	? } XAN
	296.30	? } XAN
R ₁	711.90	✓
R	711.90	X
R ₁	1,198.00	✓
C ₁	161.40	508m
R ₁	76.40	✓
R ₁	76.40	✓
J ₁	426.60	✓
D ₁	121.40	✓
R	98.20	X
R ₁	96.40	✓
S ₁	78.40	X
S ₁	36.40	X
S ₁	79.60	X
	1,021.90	? }
	231.90	? } XAN
	121.30	? } XAN
	101.30	? }
	139.70	? }
	96.40	? }
R ₁	198.40	✓
S ₁	96.20	X
R ₁	1,198.00	✓
C ₁	161.40	508m
R	76.40	X
R	76.40	X
J ₁	426.60	✓
S ₁	121.40	X
R	98.20	X
R ₁	96.40	✓
R ₁	78.40	✓

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD5090R - AIG**ROEL**

160	1	Rear door outer handle - rubber seal LH	\$	36.40 X
161	1	Rear door inner opening handle LH	\$	79.60 X
162	1	Rear door inner trim board LH	\$	1,021.90 7 X AN
163	1	Rear door kicking plate / step garnish LH	\$	231.90 7 X AN
164	1	Rear door glass LH	\$	366.70 X
165	1	Rear door window glass channel weatherstrip LI	\$	121.30 X
166	1	Rear door window glass channel holder LH	\$	101.30 X
167	1	Rear door channel weatherstrip / felt LH	\$	139.70 X
168	1	Rear door interior light switch LH	\$	96.40 X
169	1	Rear door regulator gear LH	\$	198.40 7 X AN
170	1	Rear door regulator handle LH	\$	96.20 X
171	1	Rear Bumper	\$	487.80 X
172	1	Rear Bumper Stay LH	\$	20.00 X
173	1	Rear Bumper Side Retainer LH	\$	57.30 X
174	1	Rear Bumper Side Support LH	\$	87.30 X
175	1	Rear Bumper reflectors LH	\$	55.00 X
176	1	Rear Bumper Side Support RH	\$	87.30 X
177	1	Rear Bumper reflectors RH	\$	55.00 X
178	1	Rear End panel inner	\$	280.70 X
179	1	Rear End Panel Outer	\$	519.80 X
180	1	Rear End Panel Inner Trim	\$	219.87 X
181	1	Rear Luggage Floor Panel	\$	791.70 X
182	1	Rear Luggage Floor Panel Trim Board	\$	311.90 X
183	1	Rear Luggage Floor Panel Insulator	\$	481.40 X
184	1	Tailgate Lid	\$	1,233.70 X
185	1	Tailgate Lid Centre 'TOYOTA' Logo Badge	\$	68.00
186	1	Tailgate Lid Weatherstrip	\$	286.90 X
187	1	Tailgate Lid Lock - Top	\$	388.80 X
188	1	Tailgate Lid Lock - Bottom	\$	32.83 X
189	1	Tailgate Lid Outer Chrome Garnish	\$	214.50 X
190	1	Tailgate Lid Inner Handle	\$	17.47 X
191	1	Tailgate Lid Inner Trim Board	\$	258.28 X
192	1	Tailgate Hinge RH	\$	150.00 X
193	1	Tailgate Hinge LH	\$	150.00 X
194	1	Tailgate lid inner garnish top	\$	204.60 X
195	1	Tailgate lid damper stay RH	\$	224.70 X
196	1	Tailgate lid damper stay LH	\$	224.70 X
197	1	Rear Spoiler	\$	986.10 X
198	1	Tailgate Scuff plate	\$	204.60 X
199	1	Rear Spoiler third brake light	\$	219.40 X
200	1	Rear windscreen glass with heater	\$	988.70
201	1	Rear fender LH	\$	1,013.60

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD5090R - AIG**ROEL**

202	1	Rear fender panel deck trim side LH	\$	Sm	615.00 X
203	1	Rear fender inner wheel house panel LH	\$	R	621.10 X
204	1	Rear fender inner bottom trim LH	\$	Sm	348.70 X
205	1	Rear fender inner cowling LH	\$	Sm	232.10 X
206	1	Rear fender 1/4 glass with moulding LH	\$	Shawlow	429.80 ✓
207	1	Rear fender RH	\$	R	1,013.60 ✓✓
208	1	Rear fender panel deck trim side RH	\$	Sm	615.00 X
209	1	Rear fender inner wheel house panel RH	\$	R	621.10 X
210	1	Rear fender inner bottom trim RH	\$	Sm	348.70 X
211	1	Rear fender inner cowling RH	\$	Sm	232.10 X
212	1	Petrol tank	\$	Sm	961.70 X
213	1	CNG Board Cover	\$	Sm	120.00 X
214	1	Spare tyre fastener bolt	\$	R	362.00 X
215	1	Tyre mechanical jack	\$	R	216.90 X
216	1	Tyre mechanical jack holder bracket	\$	R	166.30 X
217	1	Rear Exhaust Box	\$	R	788.50 X
218	1	Rear shock absorber RH	\$		311.40 7>NN
219	1	Rear axle assembly with axle shaft	\$		2,911.70 7>NN
220	1	Rear axle housing	\$	usp	1,991.70 X
221	1	Rear lamp LH	\$	CMA	496.43 ✓✓
222	1	Rear lamp RH	\$		496.43 7 X>NN
223	1	Rear lamp inner panel LH	\$	R	540.00 ✓
224	1	Rear lamp inner panel RH	\$	R	540.00 X
225	1	Rear Seat Belt RH	\$	Sm	618.50 X
226	1	Rear Seat Belt tension RH	\$	Sm	75.10 X
227	1	Rear Seat Belt LH	\$	Sm	618.50 X
228	1	Front Seat Belt tension LH	\$	Sm	75.10 X
TOTAL			\$		117,530.46 [22,319.77]
25%			\$		29,382.62 16,739.83
			\$		88,147.84

Specical Nett

1	Front licence plate	\$	R	35.00 25sm ✓
1 Set	Front Fender Liner clip LH	\$	sm	12.00 X
1 Set	Front Fender Liner clip RH	\$	sm	12.00 ✓
1	Front tyre RH	\$	R	180.00 60bsm 108.w
1	Front tyre Rim RH	\$	R	120.00 5ain ✓
1	Front tyre Rim hub cap RH	\$	sm	200.00 X
1	Front tyre LH	\$		180.00 7 X AN
1	Front tyre Rim LH	\$		120.00 7 X AN

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD5090R - AIG**ROEL**

1 Front tyre Rim hub cap LH	\$	na 200.00 X
1 Set Radiator Grille clip	\$	na 18.00 X
1 Front windscreen sealant	\$	na 80.00 40sm ✓
1 Front windscreen inner sponge seal	\$	na 60.00 30sm ✓
2 Front ERP Sticker	\$	na 40.00 26sm ✓
1 Set Engine splash cover clip RH	\$	na 12.00 X
1 Set Engine splash cover clip LH	\$	na 12.00 X
1 Set Rear Bumper Fastener Clip	\$	na 30.00 X
1 Set Rear end panel inner trim clip	\$	na 30.00 X
1 Set Rear Bumper Parking Sensor	\$	sm 300.00 X
1 Rear Exhaust Mounting	\$	sm 45.80 X
1 CNG Sticker	\$	na 60.00 15sm ✓
1 Tailgate Sticker 'Trans-cab'	\$	na 30.00 X
1 Tailgate Sticker '6555-3333'	\$	na 30.00 X
1 Tailgate Sticker 'Trans-link'	\$	na 30.00 X
2 Rear Windscreen Sealant	\$	na 80.00 40sm ✓
1 Rear Windscreen Inner Sponge Seal	\$	na 60.00 30sm ✓
1 Set Rear fender inner trim clip	\$	na 24.00 X
1 Set Rear fender inner trim clip	\$	na 24.00 X
1 Rear fender 1/4 glass inner sponge seal	\$	na 80.00 30sm ✓
2 Rear fender 1/4 glass sealant	\$	na 120.00 40sm ✓
1 Rear fender inner cowling clip LH	\$	na 36.00 X
1 Rear fender inner cowling clip RH	\$	na 36.00 X
1 Rear Spare Tyre LH	\$	sm 180.00 X
1 Rear Spare Tyre Rim LH	\$	sm 150.00 X
1 Rear Tyre RH	\$	sm 180.00 X
1 Rear Tyre Rim RH	\$	sm 150.00 X
1 Hub cup RR RH	\$	na 70.00 X
1 Rear Tyre LH	\$	sm 180.00 X
1 Rear Tyre Rim LH	\$	b.p. na 150.00 50sm ✓
1 Hub cup RR LH	\$	na 70.00 X
1 Front door Sticker "Trans-cab" LH	\$	na 80.00 — ✓
1 Rear door Sticker "6555-3333" LH	\$	na 80.00 — ✓
1 Front door Sticker "Trans-cab" RH	\$	na 80.00 — ✓
1 Rear door Sticker "6555-3333" RH	\$	na 80.00 — ✓

TOTAL	\$	3,746.80	[816]
TOTAL PARTS	\$	91,894.64	

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$

16,800.00 320d

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHD5090R - AIG

ROEL

Putty And Spray Painting Of The Affected	\$	16,200.00 ²⁴⁰⁰ ✓
To Rust-Proofing Of The Affected Areas.	\$	220.00 ¹⁸⁰ ✓
To Check Electrical Lighting Concerned.	\$	120.00 ⁴⁰ ✓
To Reseal Sealant On Gap	\$	120.00 ✓
Towing Fee	\$	120.00 ✓
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00 ✓
To check steering geometry and computer wheel alignment	\$	220.00 ⁸⁰ ✓
To transfer of tire, rim and on wheel balancing.	\$	170.00 ⁴⁰ ✓
To vacuum, replace, refix and recharge air condenser	\$	nn 380.00 X
To replace, refix and top up coolant for radiator	\$	nn 170.00 X
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00 ¹²⁰ ✓
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00 ¹⁶⁰ ✓
To check ABS brake efficiency, final checking and testing.	\$	nn 380.00 X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00 ¹²⁰ ✓
To Remove And Refit Rear 1/4 Glass To Facilitate Bodywork Repair.	\$	170.00 ⁶⁰ ✓
To Transfer Of Tailgate Fittings, Attachments And Perform Water Seepage Test.	\$	nn 170.00 X
To reinstall rear bumper parking sensor.	\$	nn 170.00 X

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHD5090R - AIG

ROEL

To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00 / 100
To drop CNG tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	na 440.00 X
To release and refill CNG gas	\$	na 170.00 X
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	380.00 ? XAN
To apply paint protection system (PPS) maintain and enhancement	\$	na 380.00 X
To dismantle and refit rear axle housing assy, remove and renewal of parts, final checking and testing.	\$	380.00 ? XAN
TOTAL	\$	38,220.00 [6,910]
Over All Total	\$	130,114.64

REPAIR DAYS

60 DAYS

24

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1 6 , 7 3 9 . 8 3
 + 8 1 6 . 0 0
 + 6 , 9 1 0 . 0 0
 = 2 4 , 4 6 5 . 8 3
 - - - - -

2 4 , 4 6 5 . 8 3 - 2 0 % = 1 9 , 5 7 2 . 6 6

L / S : \$ 1 9 , 6 0 0 . 0 0 (a l l i n) (b e f o r e G S T)