

Not Authored
Painting B4 paint

King's Auto Spray Paint Pte Ltd
Blk 160 Sin Ming Drive #05-10
Sin Ming Authority Singapore 575722

AH HUAT
96532526

6 days
CHUA KIM CHON

2-12-19

RC: Estimate cost for SLL6374 B ALTIS

SUPPLY OF PARTS:

1pc rear boot lid	M	\$655.50	✓
1pc rear boot lid logo	M	50.20	—
1pc rear boot lid COROLLA emblem	M	42	—
1pc rear boot lid ALTIS emblem	M	44	—
1pc rear boot lid handle	WAP	301.60	✓
2pc rear boot lid reflector @ 301.90	CM	603.80	✓
2pc rear boot lid number plate lamp @ 62.00		124.00	?
1pc rear boot lid lock	Net	382.00	✓
2pc rear boot lid hinges @ 82.80	M	165.60	X
1pc rear boot lid rubber	CM	166.40	✓
1pc rear boot lid inner trim	M	349.30	X
15pc rear boot lid trim clips @ 3.50	M	52.50	X
1pc rear bumper	Bu	482.00	✓
2pc rear bumper retainer @ 92.33	Di	184.66	✓
2pc rear bumper reflector @ 50.92	M	101.84	X
1pc rear bumper beam	M	361.90	✓
2pc rear bumper brackets @ 48.44		96.88	?
8pc rear bumper clips @ 3.50	M	28.00	—
2pc rear tail lamp @ 322.90	Net/W	645.80	✓
1pc rear center panel	M	581.20	✓
1pc rear panel top catch	M	40.00	X
1pc rear panel top trim	M/M	229.00	✓
5pc rear Panel top trim clips @ 3.50	M	17.50	X
1pc rear panel sensor	Star	144.20	✓?
1pc rear spray tyre box	CM	254.00	✓
1pc rear exhaust		800.00	?
2pc rear fender inner trim @ 355	M	\$ 710.00	X
		<hr/>	
		\$ 7613.88	
		1903.47	
		<hr/>	
		\$ 5710.41	

Less 25%

King's Auto Spray Paint Pte Ltd
Blk 160 Sin Ming Drive #05-10
Sin Ming Authority Singapore 575722

Balance b/f...

\$ 5710.41

1st rear bumper sensor

Shan 240.00 N ✓

IPC rear CAMERA

in 700.00 N X

IPC rear number plate

Del 45.00 ✓

LABOUR:

Renew the above mentioned parts
Knocking, cutting, welding & straighten
rear damaged parts

700
900.00

spray paintings

900
\$ 1000.00

8595.41

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: