

INS. CASE OWNER:

CC6 /AIG1901 1212, 11/11/19

LKK:

IDAC

Surveyor:

MARION

DOI:

ASSIGNMENT

1/11/19

Date / Time:

21/11/19

Registered in Merimen:

1/11/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SGY 1717U

Claim No.:

Name of Insured:

PEH YING YU KRISTIN

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :S\$

D.O.A.:

29/11/19

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SLS 31437



INSRS:

WSP:

Tel:

Liability:

RMKS:

Fastech



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE / PIC
		Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	ASHER 05.10.19
		After call ltr to OI:	
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	☐
		After call ltr to OI:	☒
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☒
		Towing Invoice:	☐
		LTA / GIA:	☒
		Medical Bill:	☐
		PIR:	☐
		Mandate/Reject Instruction:	☒
		LOD:	☒
		Payment Breakdown Form:	☐
		Post-Repair Photos:	☐
		Others:	☐

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: OCS

Repair Cost:

S\$5,200

(7 days) Reduction:

13 %

Email ☒Call ☐

FINAL SETTLEMENT

Date/Time: 11-03-20

Confirm with: JPHOM

Email ☒Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia: 0%

Repair Cost:

S\$5,568.00

4 VEN CC ON 3RD

Loss of Rental (LOR):

S\$ 600.00

(6 days) x 400

Loss of Use (LOU):

S\$ -

(\$ x days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only ☒LOU only ☐LOR + LOU ☐LOR + LO ☐

(Tick only one)

GIA/LTA Search

S\$200

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost:

S\$ -

Total:

S\$6,168.00

Global Sum S\$:

FINAL PAYMENT

Date/Time: 11-03-20

Confirm with: JPHOM

Email ☐Call ☐

Payee 1:

S\$6,168.00

Name 1:

FASTECH AUTO PIE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT
12/2/2020

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

VEHICLE NO **5LS3143J**

QTY	PARTICULAR
1 PCS	BOOTLID 929.30
1 PCS	BOOTLID REAR LOGO
2 PCS	BOOTLID REFLECTORS @ \$420.10
1 PCS	BOOTLID INNER LOCK
1 PCS	BOOTLID WEATHERSTRIP 225'
1 PCS	REAR BUMPER 601
1 PCS	REAR BUMPER SPONGE
1 PCS	REAR BUMPER REINFORCEMENT 394.00
2 PCS	REAR BUMPER REINFORCEMENT STAYS @ \$105.00
5 PCS	REAR BUMPER REINFORCEMENT TOP & LOWER BRACKETS @ \$22.00
2 PCS	REAR BUMPER SIDE RETAINERS @ \$48.50
1 PCS	REAR BUMPER LOWER CENTRE GARNISH
1 PCS	REAR BUMPER LOWER SKIRTING 850
1 PCS	REAR END PANEL
1 PCS	REAR END PANEL TOP GARNISH
1 PCS	REAR FLOOR PANEL
1 PCS	REAR FLOOR PANEL TOP BOARD
2 PCS	TAILLAMPS @ \$465.00
2 PCS	TAILLAMP HOUSING PANELS @ \$215.00
2 PCS	REAR FENDERS @ \$1105.00
2 PCS	REAR FENDER INNER TRIMS @ \$399.20
1 SET	REAR FENDER INNER TRIM CLIPS
1 PCS	REAR EXHAUST
2 PCS	REAR EXHAUST MOUNTINGS @ \$45.00

1 SET	S.NETT
1 SET	REAR BUMPER REVERSE SENSOR
1 PCS	REAR REVERSE CAMERA
1 PCS	REAR END PANEL SEALANT
1 PCS	REAR WINDSCREEN SEALANT
	LABOUR CHARGES:
	TO CHECK WIRING
	TO DISMANTLE & REPLACING REVERSE SENSOR
	TO DISMANTLE & REFIX REAR EXHAUST
	TO DISMANTLE & REFIX SEAT CUSHION UPHOLSTREY
	TO DISMANTLE & REFIX REAR WINDSCREEN
	TO DISMANTLE & REFIX BOOTLID MECHANISM
	TO CONDUCT CHASSIS ALIGNMENT
	TO SPRAY RUSF PROOFING
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTENED
	& REPLACING PARTS
	TO PUTTY & SPRAY PAINTING

Not Authorized
Like
2/5 @ 5200/
7dy.
2/12/19

Bent/Buc	\$1,120.30	✓
ru	\$66.80	✓
11	\$840.20	X
twi	\$166.30	✓
twi	\$266.50	✓
DIS	\$845.20	✓
TOA	\$209.30	✓
CNE	\$488.20	✓
Ref	\$210.00	✓
11	\$110.00	X
11	\$97.00	X
NF	\$310.00	X
De	\$1,500.00	✓
S.dg	\$688.20	✓
twi	\$185.00	✓
ru	\$1,100.00	X
magd/TOA	\$365.30	✓
su	\$930.00	X
ru	\$430.00	X
ru	\$2,210.00	X
Del/TOA	\$798.20	✓
11	\$50.00	X
ru	\$820.10	X
11	\$90.00	X
	\$13,876.60	
S.Weld	\$280.00	200
11	\$380.00	X
ru	\$50.00	✓
11	\$50.00	X
	\$50.00	30
	\$80.00	50
11	\$100.00	X
	\$120.00	80
	\$150.00	X
11	\$100.00	X
11	\$380.00	X
	\$120.00	60
	\$1,800.00	1000
	\$1,800.00	1600
TO	\$19,336.60	

(10-2)

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 431G

Vehicle Details

Vehicle No.: SLS3143J

Vehicle to be Exported: No

Intended Deregistration Date: 02 Dec 2019

Vehicle Make: KIA

Vehicle Model: CERATO FORTE KOUP 1.6 AT SX ABS
D/AB SR

Primary Colour: Red

Manufacturing Year: 2010

Engine No.: G4FCAH381762

Chassis No.: KNAFW611MA5224565

Maximum Power Output: 92.7 kW (124 bhp)

Open Market Value: \$15,610.00

Original Registration Date: 07 May 2010

First Registration Date: 07 May 2010

Transfer Count: 2

Actual ARF Paid: \$15,610.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 06 May 2020

PARF Rebate Amount: \$7,805.00

Intended COE Rebate Details

COE Expiry Date: 06 May 2020

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$34,001.00

COE Rebate Amount: \$1,453.00

Total Rebate Amount: \$9,258.00

The information contained herein is correct as at 02 Dec 2019

OK

Google Home Mini

Buy Google Home Mini for hands-free control of your smart home. Shop now at Google Store.

Kia Cerato Price Range Depreciation 2010 Vehicle Type Submit Advanced Search

Home > Used Cars > ValueCars Auto Traders > Kia Cerato Forte Koup 1.6A SX Sunroof

Kia Cerato Forte Koup 1.6A SX Sunroof

Overview Financial Accessories Similar Research Photos Map

Price	\$15,300		
Depreciation	\$11,980 /yr View models with similar depre	Reg Date	21-Jul-2010 (7mths 18days COE left)
Mileage	N.A.	Manufactured	2010
Road Tax	\$738 /yr	Transmission	Auto
Dereg Value	\$9,620 as of today (change)	OMV	\$15,442
COE	\$30,000	ARF	\$15,442
Engine Cap	1,591 cc	Power	92.7 kW (124 bhp)
Curb Weight	1,232 kg	No. of Owners	2
Type of Vehicle	Sports Car		

Features

View specs of the Kia Cerato Forte Koup (2009-2013)

Description

One Of The Most Original Kia Cerato Forte Koup 1.6A SX In Stock Now! Lowest Pricing And Depreciation! Original Paintwork, Stock Condition. Original Interior! Carefully Maintained By Seller! Flexible Loan And Tenure Available! Come View And We Discuss Further Thanks.

Category

PARF Car

Status

Available

Resources



Car Valuation - Free
Find out the market value of your existing car for free. Get started



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more



Location Map

Price Chart

Click on the point to view the vehicle

Shortlist Compare Add note
Report Error More Actions

Seller Information

ValueCars Auto Traders

11 vehicles for sale, 41 sold in past 3 mths

61 Ubi Avenue 2 #02-06
Automobile Megamart
Tel: 68410062

Upfront Payment

> more Financial info

Transfer Fee	\$25	
Down Payment	\$4,590 (change)	Maximum 20% Loan
1st Instalment	\$1,557	Based on 2.98% interest rate

Kia Cerato

Price Range: ▾

Depreciation ▾

2010 ▾

Vehicle Type ▾

Submit

Advanced Search

Home > Used Cars > Highline Automotive > Kia Cerato Forte Koup 1.6M SX

Kia Cerato Forte Koup 1.6M SX

Overview Financial Insurance Accessories Similar Research Photos Map

Price	\$13,800		
Depreciation	\$10,420 /yr View models with similar depre	Reg Date	30-Jul-2010 (7mths 27days COE left)
Mileage	160,000 km (17.1k /yr)	Manufactured	2010
Road Tax	\$738 /yr	Transmission	Manual
Dereg Value	\$9,327 as of today (change)	OMV	\$13,898
COE	\$36,162	ARF	\$13,898
Engine Cap	1,591 cc	Power	92.7 kW (124 bhp)
Curb Weight	1,207 kg	No. of Owners	6
Type of Vehicle	Sports Car		

Features

1.6L 4 Cylinders DOHC 16 Valves Engine, 124 BHP, 5 Speed Manual Transmission, ABS, ABS, Knockdown Rear Seats. View specs of the Kia Cerato Forte Koup (2009-2013)

Accessories

Sunroof, Leather Seats, Factory Fitted Audio System, Steering Controls, Reverse Sensors, Solar Film, Fog Lights.

Description

Manual Car Lovers Look Here! Sporty Car Lovers Look Here. Engine Running In Tip Top Condition! Must View! Call Our Sales Person Today.

Category

PARF Car

Status

Available

Resources



Car Valuation - Free
Find out the market value of your existing car for free. [Get started](#)



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. [Find out more](#)



Shortlist Compare Add note
Report Error More Actions

Seller Information

Highline Automotive

36 vehicles for sale. 37 sold in past 3 mths

📍 31 West Coast Highway Lot 10/20/21
West Coast Car Mart
Tel: 67778887
[Search cars nearby](#)

👤 JC Chua	87115663
Henry Ong	98516566
Harris Tan	96881515

Posted on: 02-Nov-2019 | Last Updated on: 12-Nov-2019

Upfront Payment [+ more Financial info](#)

Transfer Fee \$25

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Thursday, 5 December 2019 5:04 PM
To: 'Jason'
Subject: ACCIDENT INVOLVING SLS 3143J AND SGY 1717U ON 29/11/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir/Madam,

ACCIDENT INVOLVING SLS 3143J AND SGY 1717U ON 29/11/2019

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: asher.sng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	02 Dec 2019 14:49	Cim Dtl Modified	Claimant's Name: -> -.	[A] Lau Shu Pei
2	02 Dec 2019 14:49	Cim Veh Model Changed	(206086) ADIVA AD1 200 190cc 3W.	[A] Lau Shu Pei
3	02 Dec 2019 14:49	Cim Created	Reg No: SLS3143J, Acct Date: 2019/11/29, Claim Type: TP, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Workshop: Fastech Auto Pte Ltd (HQ)	[A] Lau Shu Pei
4	02 Dec 2019 14:49	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ)	[A] Lau Shu Pei
5	02 Dec 2019 14:49	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/12/11	[A] Lau Shu Pei
6	02 Dec 2019 14:49	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Lau Shu Pei
7	02 Dec 2019 14:49	Cim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)	[I] Merimen Administrator
8	02 Dec 2019 14:49	Label Added	(19):Fastlane.	[A] Lau Shu Pei
9	02 Dec 2019 14:49	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] Lau Shu Pei
10	04 Dec 2019 12:35	Cim Dtl Modified	Claimant's Name: - -> GAN WEI YI EDWIN, Claimant's ID: -> S9049431G.	[A] Lau Shu Pei
11	04 Dec 2019 12:35	Cim Veh Model Changed	(206086) -> (205158) KIA CERATO 1.6 (A).	[A] Lau Shu Pei
12	04 Dec 2019 14:09	TP Ins Updated	TPRegNo:SGU1717U -> SGY1717U.	[I] Hor, Yinnul
13	05 Dec 2019 10:06	Cim Registration Modified	Acct Time:00:00:00->20:00:00.	[I] AIG OneClaim Integration User
14	21 Jan 2020 11:37	Adj Rpt Initiated		[A] Asher Sng Rong Yi
15	21 Jan 2020 11:37	Insured Phone No Updated	[None] -> [+6581232103]	[A] Asher Sng Rong Yi
16	21 Jan 2020 11:37	Cim Dtl Modified	Claim Conclusion: -> 1.	[A] Asher Sng Rong Yi
17	21 Jan 2020 11:37	Cim Dtl Modified	JPJ Reg. Date: -> 2010/05/07.	[A] Asher Sng Rong Yi
18	21 Jan 2020 11:37	Cim Details Notified		[A] Asher Sng Rong Yi
19	21 Jan 2020 12:15	Adj Mandate Request	Cur.Req:6166.00:LIABILITY: 100% B:28 4VEH CC OT 3RD	[A] Asher Sng Rong Yi

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Adj Type	Adj Agency	Co Name (Branch)	Ref 1	Ref 2	Amount
2364151	02 Dec 2019 14:54:02	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	AIG Asia Pacific Insurance Pte. Ltd. (Express)	SLS3143J	SGU1717U	11.77
2414232	21 Jan 2020 11:37:43	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLS3143J	SGY1717U	11.77

Print Received Message

This mail is associated with :

***SLS3143J (6526184053SG)**
[SGY1717U]
TP
GAN WEI YI EDWIN
Nov 29 2019 8:00PM
[PEH YING YU KRISTIN]
Fastech Auto Pte Ltd

From **AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS)**, sent on **21/01/2020 14:19 PM**.
To **LKK_HQ**
Subject **Alert - Adj Mandate Approved (S\$6166.00) - SLS3143J - Claim Handler: Loh, Chee-Heng**

Approved:6166.00.



redefining / insurance

AXA Insurance Pte Ltd

1800 880 4888 (Within Singapore)

(65) 6880 4888 (International)

(65) 6880 4740

customer.care@axa.com.sg

www.axa.com.sg

Certificate of Insurance

account number

04041

Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1980 - Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name	GAN WEI YI EDWIN	Certificate number	GA410986 / 1
Cover	Comprehensive	Chassis number	KNAFW611MA5224565
Plan name	Essential	Engine number	G4FCAH381762
NCD applicable	10%		
Vehicle registration number	SL53143J		
Period of insurance	from 14/11/2018 to 06/05/2020 (both dates inclusive)		
Finance loan company	Nil		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
(b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, is in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS	Basic Own Damage Excess	SGD 500.00
	Windscreen Excess	SGD 100.00

An Additional Excess is applicable as follows:

1. S\$500 for unnamed Authorised Driver
2. S\$500 for declared Young and Inexperienced Driver
3. S\$5,000 for undeclared Young and Inexperienced Drivers. This additional excess is reduced to S\$2,500 if you have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189). The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 431G

Vehicle Details

Vehicle No.: SLS3143J
Vehicle to be Exported: No
Intended Deregistration Date: 29 Nov 2019
Vehicle Make: KIA
Vehicle Model: CERATO FORTE KOUP 1.6 AT SX ABS D/AB SR
Primary Colour: Red
Manufacturing Year: 2010
Engine No.: G4FCAH381762
Chassis No.: KNAFW611MA5224565
Maximum Power Output: 92.7 kW (124 bhp)
Open Market Value: \$15,610.00
Original Registration Date: 07 May 2010
First Registration Date: 07 May 2010
Transfer Count: 2
Actual ARF Paid: \$15,610.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 06 May 2020
PARF Rebate Amount: \$7,805.00

Intended COE Rebate Details

COE Expiry Date: 06 May 2020
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$34,001.00
COE Rebate Amount: \$1,480.00
Total Rebate Amount: \$9,285.00

The information contained herein is correct as at 29 Nov 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Dec 2019 Edit Reg		02 Dec 2019 00:00 Edit Adj Rpt	S\$5,200.00 Edit Estimates	S\$5,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	PEH YING YU KRISTIN, ID: S88398761, Tel: +6581232103		
Main Claimant:	GAN WEI YI EDWIN, ID: S9049431G		
Vehicle Reg. No.:	SLS3143J	Date of Loss:	29/11/2019 20:00 - :59 [114 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 6526184053SG	Policy/Cover Note No.:	1900078079 (Comprehensive)
Vehicle Reg. No. (Insured):	SGY1717U	Policy No. (Claimant):	GA410986/1
		Excess:	
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 11/12/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG_EXPRESS (21/01/2020): Alert - Adj Mandate Approved (S\$6166.00) - SLS3143J - Claim Handler: Loh, Chee-H...
- AIG_SG (04/12/2019): Request to upload TP GIA Report
- AIG_SG (03/12/2019): Request To Upload TP GIA Report
- AIG_SG (03/12/2019): No Policy Found

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLS3143J (6526184053SG)
[SGY1717U]

TP
GAN WEI YI EDWIN
Nov 29 2019 8:00PM
[PEH YING YU KRISTIN]
Fastech Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page			☒		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail			Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown																Edit		
Photos/Images															3 per page			☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail			Print		
1	02/12/19 15:06	Odometer Reading																Load JPG ☒		
2	02/12/19 15:06	Chassis Number																Load JPG ☒		
3	02/12/19 15:08	General View																Load JPG ☒		
4	02/12/19 15:08	General View																Load JPG ☒		
5	02/12/19 15:08	General View																Load JPG ☒		
6	02/12/19 15:08	General View																Load JPG ☒		
7	02/12/19 15:08	General View																Load JPG ☒		
8	02/12/19 15:08	General View																Load JPG ☒		
9	02/12/19 15:08	General View																Load JPG ☒		
10	02/12/19 15:08	General View																Load JPG ☒		
11	02/12/19 15:08	General View																Load JPG ☒		
12	02/12/19 15:08	General View																Load JPG ☒		
13	02/12/19 15:08	General View																Load JPG ☒		
14	02/12/19 15:08	General View																Load JPG ☒		
15	02/12/19 15:08	General View																Load JPG ☒		
16	02/12/19 15:08	General View																Load JPG ☒		
17	02/12/19 15:08	General View																Load JPG ☒		
18	02/12/19 15:08	General View																Load JPG ☒		
19	02/12/19 15:08	General View																Load JPG ☒		
20	02/12/19 15:08	General View																Load JPG ☒		
21	02/12/19 15:08	General View																Load JPG ☒		
22	02/12/19 15:08	General View																Load JPG ☒		
23	02/12/19 15:08	General View																Load JPG ☒		
24	02/12/19 15:08	General View																Load JPG ☒		
25	02/12/19 15:08	General View																Load JPG ☒		
26	02/12/19 15:08	General View																Load JPG ☒		
27	02/12/19 15:08	General View																Load JPG ☒		
28	02/12/19 15:08	General View																Load JPG ☒		
29	02/12/19 15:08	General View																Load JPG ☒		
30	02/12/19 15:08	General View																Load JPG ☒		
31	02/12/19 15:08	General View																Load JPG ☒		
32	02/12/19 15:08	General View																Load JPG ☒		
33	02/12/19 15:08	General View																Load JPG ☒		
34	02/12/19 15:08	General View																Load JPG ☒		
35	02/12/19 15:08	General View																Load JPG ☒		
36	02/12/19 15:08	General View																Load JPG ☒		
37	02/12/19 15:08	General View																Load JPG ☒		
38	02/12/19 15:08	General View																Load JPG ☒		
39	02/12/19 15:08	General View																Load JPG ☒		
40	02/12/19 15:08	General View																Load JPG ☒		

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
41	02/12/19 15:08	General View	 Load JPG	☒
42	02/12/19 15:08	General View	 Load JPG	☒
43	02/12/19 15:08	General View	 Load JPG	☒
44	02/12/19 15:08	General View	 Load JPG	☒
45	02/12/19 15:08	General View	 Load JPG	☒
46	02/12/19 15:08	General View	 Load JPG	☒
47	02/12/19 15:08	General View	 Load JPG	☒
48	02/12/19 15:08	General View	 Load JPG	☒
49	02/12/19 15:08	General View	 Load JPG	☒
50	02/12/19 15:08	General View	 Load JPG	☒
51	02/12/19 15:08	General View	 Load JPG	☒
52	02/12/19 15:08	General View	 Load JPG	☒
53	02/12/19 15:08	General View	 Load JPG	☒
54	02/12/19 15:08	General View	 Load JPG	☒
55	02/12/19 15:08	General View	 Load JPG	☒
56	02/12/19 15:08	General View	 Load JPG	☒
57	02/12/19 15:08	General View	 Load JPG	☒
58	02/12/19 15:08	General View	 Load JPG	☒
59	02/12/19 15:08	General View	 Load JPG	☒
60	02/12/19 15:08	General View	 Load JPG	☒
61	02/12/19 15:08	General View	 Load JPG	☒
62	02/12/19 15:08	General View	 Load JPG	☒
63	02/12/19 15:08	General View	 Load JPG	☒
64	02/12/19 15:08	General View	 Load JPG	☒
65	02/12/19 15:08	General View	 Load JPG	☒
66	02/12/19 15:08	General View	 Load JPG	☒
67	02/12/19 15:08	General View	 Load JPG	☒
68	02/12/19 15:08	General View	 Load JPG	☒
69	02/12/19 15:08	General View	 Load JPG	☒
70	02/12/19 15:11	Reinspection Photo	 Load JPG	☒
71	02/12/19 15:11	Reinspection Photo	 Load JPG	☒
72	02/12/19 15:11	Reinspection Photo	 Load JPG	☒
73	02/12/19 15:11	Reinspection Photo	 Load JPG	☒
74	02/12/19 15:11	Reinspection Photo	 Load JPG	☒
75	02/12/19 15:11	Reinspection Photo	 Load JPG	☒
76	02/12/19 15:11	Reinspection Photo	 Load JPG	☒
77	02/12/19 15:11	Reinspection Photo	 Load JPG	☒
78	02/12/19 15:11	Reinspection Photo	 Load JPG	☒
79	02/12/19 15:11	Reinspection Photo	 Load JPG	☒
80	02/12/19 15:11	Reinspection Photo	 Load JPG	☒
81	02/12/19 15:11	Reinspection Photo	 Load JPG	☒
82	02/12/19 15:11	Reinspection Photo	 Load JPG	☒
83	02/12/19 15:11	Reinspection Photo	 Load JPG	☒
84	02/12/19 15:11	Reinspection Photo	 Load JPG	☒
85	02/12/19 15:11	Reinspection Photo	 Load JPG	☒
86	02/12/19 15:11	Reinspection Photo	 Load JPG	☒
87	02/12/19 15:11	Reinspection Photo	 Load JPG	☒
88	02/12/19 15:11	Reinspection Photo	 Load JPG	☒
89	02/12/19 15:11	Reinspection Photo	 Load JPG	☒
90	02/12/19 15:11	Reinspection Photo	 Load JPG	☒
91	02/12/19 15:11	Reinspection Photo	 Load JPG	☒
92	02/12/19 15:11	Reinspection Photo	 Load JPG	☒
93	02/12/19 15:11	Reinspection Photo	 Load JPG	☒
94	02/12/19 15:11	Reinspection Photo	 Load JPG	☒
95	02/12/19 15:11	Reinspection Photo	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
96	02/12/19 15:11	Reinspection Photo	 Load JPG	☒
97	02/12/19 15:11	Reinspection Photo	 Load JPG	☒
98	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
99	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
100	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
101	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
102	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
103	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
104	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
105	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
106	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
107	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
108	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
109	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
110	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
111	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
112	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
113	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
114	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
115	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
116	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
117	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
118	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
119	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
120	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
121	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
122	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
123	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
124	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
125	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
126	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
127	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
128	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
129	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
130	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
131	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
132	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
133	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
134	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
135	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
136	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
137	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
138	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
139	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
140	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
141	02/12/19 15:12	Reinspection Photo	 Load JPG	☒
142	02/12/19 15:12	Reinspection Photo	Load JPG	☒
143	02/12/19 15:12	Reinspection Photo	Load JPG	☒
144	02/12/19 15:12	Reinspection Photo	Load JPG	☒
145	02/12/19 15:12	Reinspection Photo	Load JPG	☒
146	02/12/19 15:12	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/12/19 16:54	TP GIA REPORT	 Load PDF	
2	05/12/19 17:07	LETTER TO OI	 Load PDF	
3	21/01/20 10:53	TP ESTIMATE-MARKED	 Load PDF	

Letters/Correspondences				1 per page	☒
No	Finalized On			Thumbnail	Print
4	13/02/20 10:22	LKK Auto Consultants Pte Ltd (HQ)			
		WORKSHOP INVOICE		Load PDF	
5	13/02/20 10:22				
		AUTHORISATION TO ACT FORM		Load PDF	
6	13/02/20 10:22				
		Release Voucher		Load PDF	
7	13/02/20 10:22				
		RENTAL RECEIPT		Load PDF	
8	13/02/20 10:22				
		LOD		Load PDF	
9	13/02/20 10:22				
		GIA SEARCH		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	04/12/19 14:09	OI GIA REPORT			Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SGY1717U (Insd veh)	Model:	KIA CERATO FORTE KOUP
	SLS3143J (TP veh)		1.6 SX ABS D/AB SR (A)
Date of Accident:	29/11/2019		

Global Sum Settlement	:	☐ Yes	☒ No	
Repair Estimate	:	\$	20,690.16	
Final Repair Cost	:	\$	5,564.00	
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$	600.00	6 days
LTA / GIA Search Fee	:	\$	2.00	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	6,166.00	

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ 0 ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Fastech Auto Pte Ltd	:	\$ 6,166.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

13 Feb
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC8/AIG19021212/UES3Q2

Date: 13/02/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900078079
 Claimant SLS3143J Insured Vehicle No : SGY1717U
 Vehicle No : SLS3143J
 Date of Loss: 29/11/2019 Nature of Claim: TP Claim No: 6526184053SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLS3143J
 Make & Model: KIA CERATO FORTE KOUP, 1.6 SX ABS D/AB SR (A) Engine No: G4FCAH381762
 Reg. Date: 07/05/2010 (Man. Year: 2010) Chassis No: KNAFW611MA5224565
 Colour: Red Odometer: 141592 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,636.60	5,351.56	9,285.04	63.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,700.00	2,820.00	1,880.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,336.60	8,171.56	11,165.04	57.74
Approved Total (Overridden) (S\$)		5,200.00		
(S\$)	19,336.60	5,200.00	14,136.60	73.11
+ GST 7.00/7.00% (S\$)	1,353.56	364.00	989.56	73.11
Nett Amount (S\$)	20,690.16	5,564.00	15,126.16	73.11
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,166.00		

INSPECTION

Date of Assignment: 02/12/2019
 Date Inspected: 02/12/2019 Inspected At: Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50
 Autobay
 Singapore 417883
 Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE

MARKET VALUE: \$14,500

LTA REBATE: \$9,258

NETT VALUE: \$5,242

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent / Buckled	1,120.30 F	*929.30 FL
2	1		*BOOTLID REAR LOGO	Necessary	66.80 F	*66.80 FL
3	2		*BOOTLID REFLECTORS	Not Necessary	840.20 F	*- FL
4	1		*BOOTLID INNER LOCK	Twisted	166.30 F	*166.30 FL
5	1		*BOOTLID WEATHERSTRIP	Twisted	266.50 F	*225.00 FL
6	1		*REAR BUMPER	Distorted	845.20 F	*601.00 FL
7	1		*REAR BUMPER SPONGE	Torn	209.30 F	*209.30 FL
8	1		*REAR BUMPER REINFORCEMENT	Cracked	488.20 F	*394.00 FL
9	2		*REAR BUMPER REINFORCEMENT STAYS	Bent	210.00 F	*210.00 FL
10	5		*REAR BUMPER REINFORCEMENT TOP & LOWER BRACKETS	Not Necessary	110.00 F	*- FL
11	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	97.00 F	*- FL
12	1		*REAR BUMPER LOWER CENTRE GARNISH	Not Necessary	310.00 F	*- FL
13	1		*REAR BUMPER LOWER SKIRTING	Deformed	1,500.00 F	*850.00 FL
14	1		*REAR END PANEL	Badly Dented	688.20 F	*688.20 FL
15	1		*REAR END PANEL TOP GARNISH	Twisted	165.00 F	*165.00 FL
16	1		*REAR FLOOR PANEL	Repair	1,100.00 F	*- FL
17	1		*REAR FLOOR PANEL TOP BOARD	Torn	365.30 F	*365.30 FL
18	2		*TAILLAMPS	Serviceable	930.00 F	*- FL
19	2		*TAILLAMPS HOUSING PANELS	Repair	430.00 F	*- FL
20	2		*REAR FENDERS	Repair	2,210.00 F	*- FL
21	2		*REAR FENDERS INNER TRIMS	Deformed / Torn	798.20 F	*798.20 FL
22	1		*REAR EXHAUST	Repair	820.10 F	*- FL
23	2		*REAR EXHAUST MOUNTINGS	Not Necessary	90.00 F	*- FL
24	1		*REAR REVERSE CAMERA	Not Necessary	380.00 FS	*- FS
25	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
26	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
27	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 F	*- FL
28	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 14,636.60 5,918.40

- List Item Discount on L Items 0.00/10.00% (\$\$) 0.00 566.84

Total Parts (\$\$) 14,636.60 5,351.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
4	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY	New	120.00	80.00
5	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
6	TO DISMANTLE & REFIX BOOTLID MECHANISM	New	100.00	0.00
7	TO CONDUCT CHASSIS ALIGNMENT	New	380.00	0.00
8	TO SPRAY RUSF PROOFING	New	120.00	60.00
9	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTENED & REPLACING PARTS	New	1,800.00	1,000.00
10	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,600.00
Gross Labour Cost (\$\$)			4,700.00	2,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >