



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

CLEANING TECHNOLOGY MANAGEMENT PTE LTD
14 TAMPINES INDUSTRIAL DRIVE
SINGAPORE 528530

Attention : THE OWNER
Contact : 64819588 85527540

Estimate : ES006857

Date : 02/12/2019
Vehicle Num. : XD8401T
Make/Model : MAN TGM 18.280 4X2 BB-2013
Chassis/Eng# : WMAN08ZZ7DY296490/21834545853
Accident Date : 30/11/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	SPECIAL NETT ITEMS :		
2.	1	TAIL LAMP L/H <i>bro</i>		395.00
3.	1	TAIL LAMP BRACKET L/H <i>bt</i>		228.60
4.	1	TAIL LAMP BRACKET REFLECTOR <i>ca</i>		36.80
4.	1	VERDEGRO SYSTEM US-100K (TMA'S) TRUCK MOUNT ATTENUATORS (PASS NCHRP350 STS LEVEL 3) C/W <i>prc</i>		
		HYDRAULIC LIFT <i>prc?</i>		
		Special Nett Total S\$:		59,800.00 <i>? prc</i>
		LABOUR :		60,460.40
		CHANGE TAILLAMP AND CHECK WIRING		
		TO DISMANTLE CARRIAGE, KNOCK AND STRAIGHTEN REAR		
		CHASSIS FRAME, RE-ALIGN BODY AND RUST PROOFING		
		LABOUR CHARGE TO INSTALL, REMOVE/DISPOSE DAMAGE TMA		
		Labour Total S\$:		120.00 <i>60</i>
				3 days
				1,200.00 <i>X</i>
				1,000.00 <i>800</i>
				2,320.00

Resurvey before repair

ema

SingDollars : Sixty-Two Thousand Seven Hundred Eighty & Cents Forty Only

Total S\$: 62,780.40

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: