



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 19700288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

EQ INSURANCE COMPANY LIMITED
22 GEMMILL LANE
SINGAPORE 069257

EQ INSURANCE COMPANY LIMITED

VEHICLE NO. : FBP4961S
MAKE/MODEL : DUCATI / MONSTER 821

NO. : 35239

DATE : 20/11/2019
CLAIM NO. : 11466
POLICY NO. :
FROM : HASRIANAH

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	AIR SHROUD CYLINDER	REPLACE	1.00	\$35.00	35.00
2	BALANCER SET, HANDLE BAR	REPLACE	1.00	\$3.00	3.00
3	COVER	REPLACE	1.00	\$58.00	58.00
4	EMBLEM DUCATI	REPLACE	2.00	\$47.00	94.00
5	FOOTREST RH	REPLACE	2.00	\$97.00	194.00
6	Frame Sliders Ducati Monster 821/ Monster	REPLACE	1.00	\$308.00	308.00
7	GASKET	REPLACE	1.00	\$9.00	9.00
8	GASKET FUEL PUMP	REPLACE	1.00	\$98.00	98.00
9	GASKET, EXHAUST PIPE	REPLACE	1.00	\$9.00	9.00
10	GRIP HANDLE LH	REPLACE	1.00	\$58.00	58.00
11	GUARD DUCATI <i>Exhaust</i>	REPLACE	1.00	\$40.00	40.00 ?
12	GUARD HEAT	REPLACE	1.00	\$115.00	115.00
13	HANDLEBAR	REPLACE	1.00	\$261.00	261.00 ?

*35239

*fuel tank DO -
At signal lamp o/s one -*

bizSAFE₃



CERT NO: 2002-1-0363
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
14	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED INCLUDING BLEEDING FRONT BREAK	4	7.00	\$49.00	300 343.00
15	LEVER BRAKE	REPLACE	1.00	\$331.00	sun 331.00
16	LEVER BRAKE REAR <i>sky</i>	REPLACE	1.00	\$210.00	Bro 210.00
17	LOGO STICKER'DUCATI'	REPLACE	1.00	\$42.00	nu 42.00
18	MIRROR RH	REPLACE	1.00	\$157.00	cu 157.00
19	OIL BRAKE (MOTUL) RBF 600 P/N: 44153	REPLACE	1.00	\$37.00	nu 37.00
20	PAD FUEL TANK	REPLACE	2.00	\$20.00	nu 40.00
21	PIPE, EXHAUST CENTER	REPLACE	1.00	\$1,011.00	sd/cu 1,011.00
22	PIPE, EXHAUST HEAD	REPLACE	1.00	\$726.00	sd/cu 726.00
23	PLATE HOLDER FOOT PEG RH <i>Rec</i>	REPLACE	1.00	\$440.00	one 440.00
24	RUBBER COVER FOOT PEG RH	REPLACE	2.00	\$20.00	cu 40.00
25	RUBBER SECTION	REPLACE	1.00	\$58.00	nu 58.00
26	Slider axle front (motivation)	REPLACE	1.00	\$112.00	cu 112.00
27	Slider axle rear(motivation)	REPLACE	1.00	\$133.00	cu 133.00
28	SWITCH HANDLE RH	REPLACE	1.00	\$177.00	su 177.00 X
29	THROTTLE CONTROL	REPLACE	1.00	\$573.00	573.00 ?

SUB TOTAL

\$5,712.00

GST @ 7 %

\$399.84

GRAND TOTAL

\$6,111.84

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

*35239 *

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Acknowledge & Accepted By

bizSAFE₃CERT NO.: 2002-1-0383
ISO 9001:2015

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
------------	--------------------	---------------	------------	-------------------	---------------



This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*35239 *

bizSAFE₃

