



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2004847
INV Date 09/07/2020
Reference CC6/LPC19021222/Gka3n2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. SKR 5235G
Insured Veh. SKB 679B
Claim No. 19/19/19/VP05/0222209
Policy No. Z19VP05023133
Accident Date 11/08/2019
Inspection Date 22/11/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC6/LPC19021222/Gka3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 09-07-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKB 679B	Veh. Inspected	SKR 5235G
Policy No.	Z19VP05023133	Coverage (\$)	0.00
Claim No.	19/19/19/VP05/0222209	Excess (\$)	0.00
Assign From		Assign Date	22/11/2019

2. Vehicle Particulars & Condition

Make & Model	NISSAN SYLPHY 1.6	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	MNTBBAB17Z0022135	Colour	WHITE
Odometer	92187	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	CONTINENTAL	5 mm
L/H Front Tyre	205/55 R16	CONTINENTAL	5 mm
R/H Rear Tyre	205/55 R16	CONTINENTAL	5 mm
L/H Rear Tyre	205/55 R16	CONTINENTAL	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/08/2019	Inspection Date	22/11/2019
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 5235G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED	755.30	382.70
2	FRONT BUMPER SIDE RETAINER @\$52.30	DEFORMED	104.60	38.20
1	FRONT BUMPER FOGLAMP COVER RH	NOT NECESSARY	125.60	-
1	FRONT BUMPER SPONGE	NOT NECESSARY	296.50	-
1	HEAD LAMP RH	CRACKED	788.90	482.40
1	HEAD LAMP LOWER BRACKET RH	CUT	70.00	42.00
1	FRONT FENDER	BUCKLED	633.50	386.50
1	FRONT FENDER INNER COWLING	DEFORMED	443.80	87.60
	LESS 10% DISCOUNT		-321.82	-141.94
			2,896.38	1,277.46
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	20.00	20.00
1	FRONT FENDER INNER COWLING CLIPS (SN)	NECESSARY	22.00	22.00
1	WHEEL RIM (LOCAL REPAIR)(SN)	CUT	1,200.00	150.00
			1,242.00	192.00
<u>LABOUR</u>				
	PANEL BEATING, REMOVING AND REPLACING PARTS.		1,200.00	450.00
	SPRAY PAINTING TO AFFECTED AREA.		1,200.00	500.00
	TUFF COAT.		150.00	60.00
	WIRING CHECK.		50.00	30.00
			2,600.00	1,040.00
GRAND TOTAL			6,738.38	2,509.46
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,000.00

Report Ref No. CC6/LPC19021222/Gka3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKR 5235G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

