

INS. CASE OWNER

CC³ /AIG19021227, E d³LKK:
IDAC:

Surveyor:

Steve

DOI:

ASSIGNMENT

16/12/19

Date / Time:

11/1/20

Registered in Merimen:

1/1/20

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLR 8544H

Claim No.:

Name of Insured:

KOH CHAN YANG EDWIN

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :S\$

D.O.A.:

29/11/19

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES NO)

OI GIA REPORT: YES NO ; TP GIA REPORT: YES NO

Insured Liability:

% Final ? Yes / No

SMH 9807J



INSRS:

WSP:

Tel:

Liability:

RMKS:

performance



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐
	After call ltr to OI:	☒
	Authorisation To Act:	☒
	Release Voucher:	☒
	Final Repair Bill:	☒
	Car Rental Invoice:	☐
	Towing Invoice:	☐
	LTA / GIA:	☒
	Medical Bill:	☐
	PIR:	☐
	Mandate/Reject Instruction:	☐
	LOD:	☒
	Payment Breakdown Form:	☐
	Post-Repair Photos:	☐
	Others:	☐

PRELIMINARY ADVICE	Date/Time:	Sent By:

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	S\$	(days) Reduction:	% Email ☐ Call ☐

FINAL SETTLEMENT	Date/Time:	Confirm with:	Email ☒ Call ☐
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No. : 27	If NO or B 28, Ass. Lia :
Repair Cost: (w/ln)	S\$ 8504.15		
Loss of Rental (LOR):	S\$ -	(days)	
Loss of Use (LOU):	S\$ 500.00	(\$ 100 x 5 days)	
Loss of Income (LOI):	S\$ -	(\$ x days)	
LOR only ☐ LOU only ☒	LOR + LOU ☐ LOR + LO ☐	[Tick only one]	
GIA/LTA Search	S\$ 2.00		
Medical:	S\$ -		
Disbursement:	S\$ -	(e.g. Tow/ Independent)	
Legal Cost	S\$ -		
Total:	S\$ 9006.15	Global Sum S\$:	

FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	S\$ 9006.15	Name 1: Performance Motors Limited	
Payee 2: (Strike if N.A.)	S\$	Name 2:	
Payee 3: (Strike if N.A.)	S\$	Name 3:	

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2282289)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 119941
Fax: 64747773

240, Kampong Arang Road
East Coast Centre
Singapore 434185
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796621 (AfterSales)
64796624 (Motorrad)



02 DEC 2019

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 53629
Date Estimated : 30/11/2019
Prepared By : Joseph Yaguel

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Herinckx Miriam
25 Oxley Walk
#03-23

Singapore 238595

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMH9807J	WBATR12070LC94548	19/02/2019	X3 sDrive20i	0

DESCRIPTION

Replacing rear bumper panel and attachments, rework
bootlid - R

VALUE

1275 2,125.00

Spray rear bumper and bootlid

1868 2,076.00

To replace rear exhaust silencer including alignment
system and conduct checks for leak. 451

451 / ? 531.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 177.00

Sundries

80 / ? 150.00

Total Labour 1: 5,059.00

DESCRIPTION

CLAMPING BUSH ? / AKC
TAILPIPE TRIM CHROME D=90MM ? / CUT
REAR SILENCER ? / 00
REAR BUMPER CARRIER ? X NA1
LH SIDE GUIDE FOR BUMPER ? X AM1
LH BUMPER GUIDE ? X NN
REAR BUMPER BOTTOM REINFORCEMENT ? / DR
REAR UNDERRIDE GUARD (X LINE) / CUT
REAR BUMPER PANEL PRIMED (X LINE PM) / 00
REAR BUMPER CLADDING (PDC) / CUT
LETTERING X3 / AK
LETTERING S DRIVE 20i / AK
DECOUPING RING PDC TORQUE CONVERTER / X AM1

QTY	PRIC	VALUE
1	80.80	80.80
1	122.20	122.20
1	1,257.55	1,257.55
1	743.50	743.50
1	58.25	58.25
1	70.30	70.30
1	78.85	78.85
1	227.90	227.90
1	1,555.40	1,555.40
1	608.05	608.05
1	64.45	64.45
1	96.65	96.65
4	5.10	20.40

Total Parts : 4,964.10

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

102, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kembangan Road
East Coast Centre
Singapore 438160
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796628 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No.	: b1 53629	Page No. : 2 of 5
Date Estimated	: 30/11/2019	
Prepared By	: Joseph Yaguel	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMH9807J	WBATR12070LC94548	19/02/2019	X3 sDrive20i	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date:

Steve (LKK) w/c Arrvl 16/12/19, 11.00am
5 days
P/P
By Del 5/1



Labour 1	:	5,059.00
Parts	:	4,964.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	701.62
Grand Total	:	10,724.72

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

PERFORMANCE MOTORS LIMITED

** PICKING LIST **

Order No : 003867060
Repair Order No : 1423603

Reference No : 4005
Page : 1

Enter by : p97loml
Doc. Date : 17/12/2019

Customer Code : 121
ATG Asia Pacific Insura

PART NUMBER	BO	SQ	DESCRIPTION	1st LOC	2nd LOC	% NET PRICE
			SMH9807J			
			WEATR12070LC94548			
18308693919	1	0	REAR SILENCER			
18308658210	1	0	TAILPIPE TRIM CHROME			
18308582060	1	0	REAR SILENCER LH BRA	BR	\$38.15	
18307536426	1		CLAMPING BUSH	F02L0502		60.60

Steve 19/12/19



4005
Total : 60.60
ADD GST 7 % : 4.24
TOTAL AMOUNT : 64.84



SUED BY 

PICKED BY 

PARTS RECEIVED BY (MECHANIC)

Performance Motors Limited

A member of the Sime Darby Group
Cik Reg No. 197401559W, GST Reg No. M2-0020081-X



Final Report

Estimate No. : b1 53629
Date Estimated : 30/11/2019
Prepared By : Joseph Yaguel

- ESTIMATE REPAIR FOR -

Herinckx Miriam
25 Oxley Walk
#03-23

Singapore 238595

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMH9807J	WBATR12070LC945	19/02/2019	X3 sDrive20i	0
DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments including to make good rear boot lid and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job.	1,275.00	0	1,275.00	
To respray rear bumper and rear boot lid	1,868.00	0	1,868.00	
To replace rear exhaust silencer, chrome pipe and clamping bush etc including to align system and conduct checks for leak.	451.00	0	451.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0	150.00	
Sundries	80.00	0	80.00	

3824

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# CLAMPING BUSH	60.60	1	0	60.60
# REAR SILENCER LH BRACKET / BR	38.15	1	0	38.15
TAILPIPE TRIM CHROME D=90MM	122.20	1	0	122.20
REAR SILENCER	1,257.55	1	0	1,257.55
REAR BUMPER BOTTOM REINFORCEMENT	78.85	1	0	78.85
REAR UNDERRIDE GUARD (X LINE)	227.90	1	0	227.90
REAR BUMPER PANEL PRIMED (X LINE PM)	1,555.40	1	0	1,555.40
REAR BUMPER CLADDING (PDC)	608.05	1	0	608.05
LETTERING X3	64.45	1	0	64.45
LETTERING S DRIVE 20i	96.65	1	0	96.65
# EXPANDING RIVET BLACK / MC	1.40	10	0	14.00

SUPPLEMENTARY ITEMS

Total - ~~7947.80~~
7947.80

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg No. 197401559W, GST Reg No. M2-0020081-X



Supplementary

Estimate No. : b1 53629
Date Estimated : 30/11/2019
Prepared By : Joseph Yaguel

- ESTIMATE REPAIR FOR -

Herinckx Miriam
25 Oxley Walk
#03-23

Singapore 238595

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMH9807J	WBATR12070LC94E	19/02/2019	X3 sDrive20i	0

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT
-------------	----------------------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# REAR SILENCER LH BRACKET / OR	38.15	1	0	38.15
# EXPANDING RIVET BLACK / MC	1.40	10	0	14.00

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	52.15
Total Labour & Parts :	52.15



Final Report

Total Labour :	3,824.00
Total Parts :	4,123.80
Total Labour & Parts :	7,947.80
GST @7%:	556.35
Grand Total :	8,504.15

DATE	TIME
Stove	
Lt-f	17/1/20 5

LOSS OF USE = \$100 X 5 DAYS.
GIA SEARCH FEE - \$2.00

Note : Please seek MANDATE from your
principle ASAP.

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2253269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Tampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



02 DEC 2019

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 53629
Date Estimated : 30/11/2019
Prepared By : Joseph Yaguel

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Herinckx Miriam
25 Oxley Walk
#03-23

Singapore 238595

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMH9807J	WBATR12070LC94548	19/02/2019	X3 sDrive20i	0

DESCRIPTION

Replacing rear bumper panel and attachments, rework
bootlid - R

VALUE

1275 2,125.00

Spray rear bumper and bootlid

1868 2,076.00

To replace rear exhaust silencer including alignment
system and conduct checks for leak. 457

? 531.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 177.00

Sundries

? 150.00

Total Labour 1: 5,059.00

DESCRIPTION

CLAMPING BUSH

QTY

PRIC

VALUE

TAILPIPE TRIM CHROME D=90MM

1

60.60

60.60

REAR SILENCER

1

122.20

122.20

REAR BUMPER CARRIER

1

1,257.55

1,257.55

LH SIDE GUIDE FOR BUMPER

1

743.50

743.50

LH BUMPER GUIDE

1

58.25

58.25

REAR BUMPER BOTTOM REINFORCEMENT

1

70.30

70.30

REAR UNDERRIDE GUARD (X LINE)

1

78.85

78.85

REAR BUMPER PANEL PRIMED (X LINE PM)

1

227.90

227.90

REAR BUMPER CLADDING (PDC)

1

1,555.40

1,555.40

LETTERING X3

1

608.05

608.05

LETTERING S DRIVE 20i

1

64.45

64.45

DECOUPING RING PDC TORQUE CONVERTER

1

96.65

96.65

4

5.10

20.40

Total Parts : 4,964.10

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255268)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

260, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449777

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64786601 (AfterSales)
64786624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 53629
Date Estimated : 30/11/2019
Prepared By : Joseph Yaguel

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMH9807J	WBATR12070LC94548	19/02/2019	X3 sDrive20i	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Store (LKK) with April 18/2/19, 11.00am
5 days
P/P
By Dec 5/19



Labour 1	:	5,059.00
Parts	:	4,964.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	701.62
Grand Total	:	10,724.72

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	250J
Vehicle Details	
Vehicle No.:	SMH9807J
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Dec 2019
Vehicle Make:	B.M.W.
Vehicle Model:	X3 SDRIVE20I
Primary Colour:	Brown
Manufacturing Year:	2018
Engine No.:	F0383142B48B20A
Chassis No.:	WBATR12070LC94548
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$41,424.00
Original Registration Date:	19 Feb 2019
First Registration Date:	19 Feb 2019
Transfer Count:	0
Actual ARF Paid:	\$49,994.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Feb 2029
PARF Rebate Amount:	\$37,495.00
Intended COE Rebate Details	
COE Expiry Date:	18 Feb 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$34,509.00
COE Rebate Amount:	\$31,653.00
Total Rebate Amount:	\$69,148.00

The information contained herein is correct as at 16 Dec 2019

OK

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255169)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



02 DEC 2019

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 53629
Date Estimated : 30/11/2019
Prepared By : Joseph Yaguel

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Herinckx Miriam
25 Oxley Walk
#03-23

Singapore 238595

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMH9807J	WBATR12070LC94548	19/02/2019	X3 sDrive20i	0

DESCRIPTION

Replacing rear bumper panel and attachments, rework
bootlid

VALUE

2,125.00

Spray rear bumper and bootlid

2,076.00

To replace rear exhaust silencer including alignment
system and conduct checks for leak.

531.00

To check electrical wiring systems and lightings at the
rear section for proper function.

177.00

Sundries

150.00

Total Labour 1: 5,059.00

DESCRIPTION

CLAMPING BUSH
TAILPIPE TRIM CHROME D=90MM
REAR SILENCER
REAR BUMPER CARRIER
LH SIDE GUIDE FOR BUMPER
LH BUMPER GUIDE
REAR BUMPER BOTTOM REINFORCEMENT
REAR UNDERRIDE GUARD (X LINE)
REAR BUMPER PANEL PRIMED (X LINE PM)
REAR BUMPER CLADDING (PDC)
LETTERING X3
LETTERING S DRIVE 20i
DECOUPING RING PDC TORQUE CONVERTER

QTY

PRIC

VALUE

1	60.60	60.60
1	122.20	122.20
1	1,257.55	1,257.55
1	743.50	743.50
1	58.25	58.25
1	70.30	70.30
1	78.85	78.85
1	227.90	227.90
1	1,555.40	1,555.40
1	608.05	608.05
1	64.45	64.45
1	96.65	96.65
4	5.10	20.40

Total Parts : 4,964.10

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255268)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kembangan Road
East Coast Centre
Singapore 438180
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 53629
Date Estimated : 30/11/2019
Prepared By : Joseph Yaguel

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMH9807J	WBATR12070LC94548	19/02/2019	X3 sDrive20i	0



Labour 1	:	5,059.00
Parts	:	4,964.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	701.62
Grand Total	:	10,724.72

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Third Party Insurer Enquiry

Our Ref No: GR-19-197750

Date of Request: 30/11/2019

Your Ref No:

Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 30/11/2019
Enquiry By Melanie Setiawati
TP Vehicle No. SLR8544H
Accident Date 29/11/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLR8544H	AIG Asia Pacific Insurance Pte. Ltd.	30/08/2019-29/08/2020	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

TAX INVOICE

Our Ref No: GR-19-197750

Date of Request: 30/11/2019

Your Ref No:

Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 30/11/2019
Enquiry By Melanie Setiawati
TP Vehicle No. SLR8544H
Accident Date 29/11/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



redefining / insurance

AXA Insurance Pte Ltd
1800 880 4888 (Within Singapore)
(65) 6880 4888 (International)
(65) 6880 4740
customer.care@axa.com.sg
www.axa.com.sg

Certificate of Insurance

account number
14235

-Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 - Road Transport Act, 1987 (Malaysia)
-Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name	HERINCKX MIRIAM	Certificate number	GA445370 / 1
Cover	Comprehensive	Chassis number	WBATR12070LC94548
Plan name	PML	Engine number	F0363142B48820A
NCD applicable	0%		
Vehicle registration number	SMH9807J		
Period of Insurance	from 19/02/2019 to 18/02/2021 (both dates inclusive)		
Finance loan company	DBS BANK LTD		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
(b) Any Named Driver as stated in the Policy:
1. HERINCKX EMMANUEL ARNAUD OLIVIER
(c) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS	Basic Own Damage Excess	SGD 700.00
	Windscreen Excess	Not Applicable

An Additional Excess is applicable as follows:

\$2500 for undeclared Young and Inexperience Driver(s)

\$2000 for Named Driver(s) with driving experience of less than 1 year on the relevant class of driving licence.

\$1500 for Named Driver(s) who are age 21 years old and below with driving experience of 1 year or more on the relevant class of driving licence.

\$1000 for Named Driver(s) who are age 22 years old to 26 years old with driving experience of 1 year or more on the relevant class of driving licence.

Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.

AXA Insurance Pte Ltd (199903512M)
B Shenton Way, #24-01, AXA Tower,
Singapore 068811
Customer Centre, #B1-01

1 of 3

View Received Message

This mail is associated with :

*SMH9807J (8865614143SG)
[SLR8544H]
TP
MIRIAM HERINCKX
Nov 29 2019 4:25PM
[KOH CHAN YANG EDWIN]
Performance Motors Limited

Reply Reply All Mark as Unread Print Message Delete Message Forward

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 16/03/2020 17:06 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$9006.15) - SMH9807J - Claim Handler: Tan, Bennie-WZ

Approved:9006.15:Subject to Final Repair Bill, GTA Search Bill in order.

DOCUMENTS SUMMARY
There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)
Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Dec 2019 Edit Reg		16 Dec 2019 00:00 Edit Adj Rpt	\$57,947.80 Edit Estimates	\$57,947.80 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS		[Created by adjuster]
Insured:	KOH CHAN YANG EDWIN, ID: S7913804E	
Main Claimant:	MIRIAM HERINCKX, ID: S7486250J	
Vehicle Reg. No.:	SMH9807J	Date of Loss: 29/11/2019 16:00 - :59 [9 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8865614143SG	Policy/Cover Note No.: 1700044437 (Comprehensive)
Vehicle Reg. No. (Insured):	SLR8544H	Policy No. (Claimant): GA445370
		Excess:
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174	
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com	
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 11/12/2019]	

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG_SG_EXPRESS (16/03/2020): Alert - Adj Mandate Approved (\$59006.15) - SMH9807J - Claim Handler: Tan, Bennie...

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMH9807J (8865614143SG)
[SLR8544H]
TP
MIRIAM HERINCKX
Nov 29 2019 4:25PM
[KOH CHAN YANG EDWIN]
Performance Motors Limited

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Letters/Correspondences										1 per page v	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown						1		Edit	
Photos/Images										3 per page v	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	16/12/19 18:46	Odometer Reading						1		Load JPG	
2	16/12/19 18:46	Chassis Number						1		Load JPG	
3	16/12/19 18:46	General View						1		Load JPG	
4	16/12/19 18:46	General View						1		Load JPG	
5	16/12/19 18:46	General View						1		Load JPG	
6	16/12/19 18:46	General View						1		Load JPG	
7	16/12/19 18:46	General View						1		Load JPG	
8	16/12/19 18:46	General View						1		Load JPG	
9	16/12/19 18:46	General View						1		Load JPG	
10	16/12/19 18:46	General View						1		Load JPG	
11	16/12/19 18:46	General View						1		Load JPG	
12	16/12/19 18:46	General View						1		Load JPG	
13	16/12/19 18:46	General View						1		Load JPG	
14	16/12/19 18:46	General View						1		Load JPG	
15	16/12/19 18:46	General View						1		Load JPG	
16	16/12/19 18:46	General View						1		Load JPG	
17	16/12/19 18:46	General View						1		Load JPG	
18	16/12/19 18:46	General View						1		Load JPG	
19	16/12/19 18:46	General View						1		Load JPG	
20	16/12/19 18:46	General View						1		Load JPG	
21	16/12/19 18:46	General View						1		Load JPG	
22	16/12/19 18:46	General View						1		Load JPG	
23	16/12/19 18:46	General View						1		Load JPG	
24	16/12/19 18:46	General View						1		Load JPG	
25	16/12/19 18:46	General View						1		Load JPG	
26	16/12/19 18:46	General View						1		Load JPG	
27	16/12/19 18:46	General View						1		Load JPG	
28	16/12/19 18:46	General View						1		Load JPG	
29	20/01/20 09:43	Photographs of Damaged Parts						1		Load JPG	
30	20/01/20 09:43	Photographs of Damaged Parts						1		Load JPG	
31	20/01/20 09:43	Photographs of Damaged Parts						1		Load JPG	
32	20/01/20 09:43	Photographs of Damaged Parts						1		Load JPG	
33	20/01/20 09:43	Photographs of Damaged Parts						1		Load JPG	
34	20/01/20 09:43	Photographs of Damaged Parts						1		Load JPG	
35	20/01/20 09:43	Photographs of Damaged Parts						1		Load JPG	
36	20/01/20 09:43	Photographs of Damaged Parts						1		Load JPG	
37	20/01/20 09:43	Photographs of Damaged Parts						1		Load JPG	
38	20/01/20 09:43	Photographs of Damaged Parts						1		Load JPG	
39	20/01/20 09:43	Photographs of Damaged Parts						1		Load JPG	
40	20/01/20 09:43	Photographs of Damaged Parts						1		Load JPG	

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
41	20/01/20 09:43	Photographs of Damaged Parts	 Load JPG	☒
42	20/01/20 09:43	Photographs of Damaged Parts	 Load JPG	☒
43	20/01/20 09:43	Photographs of Damaged Parts	 Load JPG	☒
44	20/01/20 09:43	Photographs of Damaged Parts	 Load JPG	☒
45	20/01/20 09:43	Photographs of Damaged Parts	 Load JPG	☒
46	20/01/20 09:43	Photographs of Damaged Parts	 Load JPG	☒
47	20/01/20 09:43	Photographs of Damaged Parts	 Load JPG	☒
48	20/01/20 09:43	Photographs of Damaged Parts	 Load JPG	☒
49	20/01/20 09:43	Photographs of Damaged Parts	 Load JPG	☒
50	20/01/20 09:43	Photographs of Damaged Parts	 Load JPG	☒
51	20/01/20 09:43	Photographs of Damaged Parts	 Load JPG	☒
52	20/01/20 09:43	Photographs of Damaged Parts	 Load JPG	☒
53	20/01/20 09:43	Photographs of Damaged Parts	 Load JPG	☒
54	20/01/20 09:44	Photographs of Damaged Parts	 Load JPG	☒
55	20/01/20 09:44	Photographs of Damaged Parts	 Load JPG	☒
56	20/01/20 09:44	Photographs of Damaged Parts	 Load JPG	☒
57	20/01/20 09:44	Photographs of Damaged Parts	 Load JPG	☒
58	20/01/20 09:44	Photographs of Damaged Parts	 Load JPG	☒
59	20/01/20 09:44	Photographs of Damaged Parts	 Load JPG	☒
60	20/01/20 09:44	Photographs of Damaged Parts	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/12/19 16:00	TP ESTIMATE	 Load PDF	
2	02/12/19 16:00	TP GIA REPORT	 Load PDF	
3	03/02/20 17:25	LETTER TO OI	 Load PDF	
4	03/02/20 17:30	LOD	 Load PDF	
5	03/02/20 17:30	GIA SEARCH FEE	 Load PDF	
6	19/03/20 08:52	WORKSHOP INVOICE	 Load PDF	
7	19/03/20 08:52	AUTHORISATION TO ACT FORM	 Load PDF	
8	19/03/20 08:52	Release Voucher	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	03/12/19 15:36	OI GIA REPORT	 Load PDF	
2	16/03/20 16:54	Letter of Demand from Third Party	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLR8544H (Insd veh)	Model:	BMW X3 2.0 I SDRIVE (A)
	SMH9807J (TP veh)		
Date of Accident:	29/11/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	10,780.52
Final Repair Cost	:	\$	8,504.15
Loss of Use	:	\$	500.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	9,006.15
Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ 100 (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 9,006.15
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

19 Mar
2020

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19021227/EDS3Q2

Date: 19/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700044437
 Claimant: SMH9807J Insured Vehicle No: SLR8544H
 Date of Loss: 29/11/2019 Nature of Claim: TP Claim No: 8865614143SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMH9807J
 Make & Model: BMW X3, 2.0 I SDRIVE (A) Engine No: F0383142B48B20A
 Reg. Date: 19/02/2019 (Man. Year: 2018) Chassis No: WBATR12070LC94548
 Colour: Brown Odometer: 14948 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/50 R19 Rear Tyre Size: 245/50 R19
 Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
 Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,166.25	4,203.80	962.45	18.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,909.00	3,744.00	1,165.00	23.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,075.25	7,947.80	2,127.45	21.12
+ GST 7.00/7.00% (S\$)	705.27	556.35	148.92	21.12
Nett Amount (S\$)	10,780.52	8,504.15	2,276.37	21.12
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		9,006.15		

INSPECTION

Date of Assignment: 16/12/2019
 Date Inspected: 16/12/2019 Inspected At: Performance Motors Limited
 (Alexandra)
 303 Alexandra Road, Sime Darby
 Performance Centre
 Singapore 159941

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*CLAMPING BUSH	Necessary	60.60 FS	*60.60 FS
3	1		*TAILPIPE TRIM CHROME D=90MM	Cut	122.20 FS	*122.20 FS
4	1		*REAR SILENCER	Dented	1,257.55 FS	*1,257.55 FS
5	1		*REAR BUMPER CARRIER	Not Necessary	743.50 FS	*- FS
6	1		*LH SIDE GUIDE FOR BUMPER	Not Necessary	58.25 FS	*- FS
7	1		*LH BUMPER GUIDE	Not Necessary	70.30 FS	*- FS
8	1		*REAR BUMPER BOTTOM REINFORCEMENT	Broken	78.85 FS	*78.85 FS
9	1		*REAR UNDERRIDE GUARD (X LINE)	Cut	227.90 FS	*227.90 FS
10	1		*REAR BUMPER PANEL PRIMED (X LINE PM)	Dented	1,555.40 FS	*1,555.40 FS
11	1		*REAR BUMPER CLADDING (PDC)	Cut	608.05 FS	*608.05 FS
12	1		*LETTERING X3	Necessary	64.45 FS	*64.45 FS
13	1		*LETTERING S DRIVE 20I	Necessary	96.65 FS	*96.65 FS
14	4		*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	20.40 FS	*- FS
15	1		*REAR SILENCER LH BRACKET	Broken	38.15 F	*38.15 F
16	10		*EXPANDING RIVET BLACK	Necessary	14.00 F	*14.00 F
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					5,166.25	4,203.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACING REAR BUMPER PANEL AND ATTACHMENTS ,REWORK BOOTLID	New	2,125.00	1,275.00
2	SPRAY REAR BUMPER AND BOOTLID	New	2,076.00	1,868.00
3	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK	New	531.00	451.00
4	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (S\$)			4,909.00	3,744.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >