

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141311

CO. REG: 200707743D GST REG: 200707743D

29-Nov-19

leong

hence notify
The Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- All prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: \$ 696.00

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1871 E

1 pc	Rear bumper ✓ CRA		\$	696.00
1 pc	Rear bumper lower cover ?		\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 X		\$	58.00
1 pc	Rear bumper inner sponge ?		\$	114.00
1 pc	Rear bumper reinforcement ?		\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 X		\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 ?		\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 ?		\$	36.00
2 pcs	Rear bumper reflector n/s @ \$ o/s @ \$46.00 ?		\$	92.00
			\$	1,953.00
			Less 10%	\$ 195.30
			\$	1,757.70

S/NETT

1 set	Reverse sensor ?		\$	280.00
1 set	Rear bumper clips / n/c.		\$	48.00
1 pc	Rear bumper top protector / n/c.		\$	80.00

Sundry ? \$ 50.00

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs. \$ 180.00 X

To dismantle / replace reverse sensor to new bumper and reset to the same \$ 120.00 40

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc \$ 650.00 200

To putty and spray painting on rear bumper, end panel \$ 400.00 200

To apply rustproofing on the repaired and replaced panels. \$ 120.00 X
\$ 3,685.70

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Guo Qiang @ lkk auto. com

2 Days -
lump sum repair.
After repair photos.
Gmo Qiang - 82880282
02/12/19.