

ASS. REC. BY:

REF: CS/MSG M021239 /

MTN 51 S
AST3

Special Instruction:

SUPERVISOR

Adrian

ASSIGNMENT (Office)

From (Person):

Chia Nyuk Rui

of

MS16

Date/Time:

2.12.19 12.44p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLS 6905H

Insured:

SLU 441H

at Workshop m/s

SRY Automotive

Tel:

67479241

of Block C-1 Kari Bukit Ave 6 A01-43

Policy No:

29114756 hkf

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A. 30.11.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

mp

Date/Time:

2.12.19 5.03 p.m

Person Contacted:

Subyri

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLS 6905H - X
	SLU 441H - X
05/12/19	@ 11:50 am sent proxy estimate to Nyuk Rui via messenger.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Dec 2019 15:03		02 Dec 2019 16:44 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Main Claimant:	ZURAINI BIN SUHAIMI, ID: S7410679Z								
Vehicle Reg. No.:	SLS6905H	Date of Loss:	30/11/2019 00:00 - :59 [26 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:	29114756MKF (Comprehensive) Coverage: 01/02/2019 - 31/01/2020						
Vehicle Reg. No. (Insured):	SLU441H	Policy No. (Claimant):							
		Excess:							
Repairer:	Sm Automotive - Kaki Bukit (HQ) BLOCK C - 1, KAKI BUKIT AVE 6, #01-43, 417863 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 03/12/2019]								
Adj Asg. Remarks:	on WP. OI:Grab. Liab: clear. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Sukyi Chong @ 6747 9241.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***SLS6905H (613304)**
[SLU441H]

TP
ZURAINI BIN SUHAIMI
Nov 30 2019 11:00AM
[GRAB RENTALS PTE LTD]
Sm Automotive - Kaki Bukit

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **05/12/2019 11:50 AM**.
To nyukpui_chhia@sg.mslg-asia.com
CC sur@lkkauto.com
Subject **SLS6905H (613304) [SLU441H] TP**

Dear Nyuk Pui,

Please be informed that we have inspected the vehicle SLS 6905H on 02/12/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/11/2019 12:56
Date Of Accident	30/11/2019 11:20
Exact Location Of Accident	PIE TOWARDS CHANGI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS6905H
Insured/Policyholder	
Name Of Registered Owner	ZURAINI BIN SUHAIMI
NRIC No	S7410679Z
Email Address	ZACKZURAINI@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96635344
Alternative Phone No	OTHERS-97377557

Vehicle Particulars

Manufacturer	SUBARU
Model	FORESTER-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2019-00014536
Cover Note Number	

Driver

Name of Driver	FEVRIENA BINTE MARWAN
NRIC No	S7404770Z
Date Of Birth	07/02/1974
Occupation	INDOOR
Date Of Driving Pass	07/03/2009
Driving Experience	10 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97377557
Fax Number	
Contact Number	
Email Address	NINAFEVRIENA07@GMAIL.COM

Address	BLK 126 POTONG PASIR AVE 1 #01-227 SINGAPORE
Postcode	350126
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : PAX 1 GENDER: : MALE
Passenger 2	NAME: : PAX 2 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLV441H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SFV9510Z
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRC/FIN No.:

30/11/19

12:43pm

Sketch Plan #2

SKETCH PLAN

	Vehicle A-SLS 6905 H B-SLV 441 H C-SFV 9510
	Legend

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving @ a speed of 80 km/h
 the car in front of me brake & i gradually
 brake and the car behind me hit me.

@ 11:20am
 P.E.T. towards changi
 P.I.E.

DECLARATION

I/We declare the foregoing particulars are true in every respect.
 Please be advised that your insurer may have a fourteen (14) days clause whereby the claim against own policy must be made within the stipulated timeframe
 from the day of occurrence. Kindly check your policy for more details.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

12:43pm
 30/11/19

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

prakes

SM AUTOMOTIVÉ

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

02/12/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

T.P. MS/G.

Shirley.

Accident date: 30/11/2019

Estimated repair cost for vehicle no: SLS6905H SUBARU FORESTER 2.0 A '17

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Regr</i>		\$1,292.30 +
2	2	Rear Boot Lid Hinge <i>2 new</i>	\$55.00	\$110.00 +
3	2	Rear Boot Lid Shock Absorber	\$154.00	\$308.00 +
4	1	Rear Boot Lid Emblem Logo <i>2</i>		\$65.00 ✓
5	1	Rear Boot Lid Subaru Logo <i>new</i>		\$68.00 ✓
6	1	Rear Boot Lid Forester Logo		\$68.00 ✓
7	1	Rear Boot Lid AWD Logo		\$65.00 ✓
8	1	Rear Boot Lid Number Plate <i>new</i>		\$50.00 +
9	1	Rear Boot Lid Inner Lock		\$560.30 +
10	1	Rear Boot Lid Inner Rubber		\$160.30 +
11	1	Rear Boot Lid Inner Trim Board <i>not new</i>		\$220.30 +
12	1	Rear Boot Lid Windscreen Seal		\$85.00 +
13	2	Rear Boot Lid Windscreen Side Seal	\$75.00	\$150.00 +
14	1	Rear Boot Lid Camera (Special Nett)		\$680.00 +
15	2	Rear Tail Lamp <i>LH cracked</i>	\$437.00	\$874.00 437.
16	2	Rear Tail Lamp Lower Bracket <i>LH cracked</i>	\$28.00	\$56.00 28
17	1	Rear Bumper <i>Regr</i>		\$980.30 -
18	10	Rear Bumper Clip <i>new</i>	\$6.50	\$65.00 30
19	2	Rear Bumper Side Retainer <i>new LH cracked</i>	\$28.00	\$56.00 28
20	2	Rear Bumper Side Reflector <i>LH cracked</i>	\$32.00	\$64.00 32
21	1	Rear Bumper Centre Top SUBARU Moulding <i>Best</i>		\$360.00 ✓
22	1	Rear Bumper Towing Cover <i>Regr</i>		\$17.00 -
23	1	Rear Bumper Reinforcement <i>Best</i>		\$320.80 ✓
24	2	Rear Bumper Reinforcement Bracket <i>new</i>	\$28.60	\$57.20 x
25	1	Rear Bumper Reverse Sensor (Special Nett) <i>Damaged</i>		\$380.00 200/50
26	1	Rear Bumper L/H Exhaust Cover <i>new</i>		\$86.00 x
27	2	Rear Fender Trim Board <i>LH cracked</i>	\$286.30	\$572.60 286.3
28	16	Rear Fender Trim Board Clip <i>new</i>	\$6.50	\$104.00 30

29	1	Rear End Panel <i>Dented</i>		\$332.00 ✓
30	1	Rear End Panel Top Garnish <i>Dented</i>		\$90.00 ✓
31	1	Rear Spare Tyre Panel <i>Regrind</i>		\$832.40 ✓
32	1	Rear Spare Tyre Panel Top Cover <i>crackd</i>		\$336.00 ✓
33	1	Rear Spare Tyre Panel & End Panel Sealant <i>new</i>		\$450.00 ✓
34	1	Rear Exhaust		\$668.00 ✓
35	1	Rear Centre Exhaust		\$1,248.00 ✓
36	1	Rear Exhaust Chrome Pipe		\$125.90 ✓
37	1	Rear Exhaust Aluminium Cover		\$68.00 ✓
38	2	Rear Exhaust Mounting	\$23.10	\$46.20 ✓
39	1	Tools Sponge Tray. <i>crackd</i>	261 ✓	
40	1	Tools Sponge Tray (Side) <i>crackd</i>	138 ✓	
			Subtotal :-	\$12,071.60

Labour charges

3972.40
3177.92 SW 200

To remove & refit cushion & trim board	\$280.00 80
To remove & refit reverse camera	\$180.00 +
To remove & refit reverse sensor	\$100.00 50
To remove & refit rear & centre exhaust	\$380.00 +
To remove & refit rear windscreen	\$120.00 +
Gum	1870 \$50.00 +
To check wiring	\$100.00 30
Tuff kote	\$150.00 60
Panel beating	\$1,400.00 850
Spray painting	\$1,400.00 800
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:	
Subtotal :-	\$4,160.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total 5247.92 **Total:-** **\$16,231.60**

A/S: A-2/C. Admin L
4/5 02/12/19.
06 Days.

421C

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Dec 2019 15:03		02 Dec 2019 16:44 Edit Adj Rpt	S\$4,200.00 Edit Estimates	S\$4,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Main Claimant:	ZURAINI BIN SUHAIMI, ID: S7410679Z								
Vehicle Reg. No.:	SLS6905H	Date of Loss:	30/11/2019 11:00 - :59 [26 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 613304	Policy/Cover Note No.:	29114756 (Comprehensive) Coverage: 01/02/2019 - 31/01/2020						
Vehicle Reg. No. (Insured):	SLU441H	Policy No. (Claimant):							
		Excess:							
Repairer:	Sm Automotive - Kaki Bukit (HQ) BLOCK C - 1, KAKI BUKIT AVE 6, #01-43, 417883 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pul - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 03/12/2019]								
Adj Asg. Remarks:	on WP. 01:Grab. Liab: clear. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Sukyl Chong @ 6747 9241.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLS6905H (613304)
[SLU441H]
TP
ZURAINI BIN SUHAIMI
Nov 30 2019 11:00AM
[GRAB RENTALS PTE LTD]
Sm Automotive - Kaki Bukit

[Upload Documents](#) | [Upload Photos](#) | [Compose New Letter](#)
View [View in Browser](#)

Video				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	23/12/19 11:01	Video - Accident (OI)		Load MP4	
Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	14/01/20 10:19	General View		Load JPG	☒
2	14/01/20 10:19	General View		Load JPG	☒
3	14/01/20 10:19	General View		Load JPG	☒
4	14/01/20 10:19	General View		Load JPG	☒
5	14/01/20 10:19	General View		Load JPG	☒
6	14/01/20 10:19	General View		Load JPG	☒
7	14/01/20 10:19	General View		Load JPG	☒
8	14/01/20 10:19	General View		Load JPG	☒
9	14/01/20 10:19	General View		Load JPG	☒
10	14/01/20 10:19	General View		Load JPG	☒
11	14/01/20 10:19	General View		Load JPG	☒
12	14/01/20 10:19	General View		Load JPG	☒
13	14/01/20 10:19	General View		Load JPG	☒
14	14/01/20 10:19	General View		Load JPG	☒
15	14/01/20 10:19	General View		Load JPG	☒
16	14/01/20 10:19	General View		Load JPG	☒
17	14/01/20 10:19	General View		Load JPG	☒
18	14/01/20 10:19	General View		Load JPG	☒
19	14/01/20 10:19	General View		Load JPG	☒
20	14/01/20 10:19	General View		Load JPG	☒
21	14/01/20 10:19	Reinspection Photo		Load JPG	☒
22	14/01/20 10:19	Reinspection Photo		Load JPG	☒
23	14/01/20 10:19	Reinspection Photo		Load JPG	☒
24	14/01/20 10:19	Reinspection Photo		Load JPG	☒
25	14/01/20 10:19	Reinspection Photo		Load JPG	☒
26	14/01/20 10:19	Reinspection Photo		Load JPG	☒
27	14/01/20 10:19	Reinspection Photo		Load JPG	☒
28	14/01/20 10:19	Reinspection Photo		Load JPG	☒
29	14/01/20 10:19	Reinspection Photo		Load JPG	☒
30	14/01/20 10:19	Reinspection Photo		Load JPG	☒
31	14/01/20 10:19	Reinspection Photo		Load JPG	☒
32	14/01/20 10:19	Reinspection Photo		Load JPG	☒
33	14/01/20 10:19	Reinspection Photo		Load JPG	☒
34	14/01/20 10:19	Reinspection Photo		Load JPG	☒
35	14/01/20 10:19	Reinspection Photo		Load JPG	☒
36	14/01/20 10:19	Reinspection Photo		Load JPG	☒
37	14/01/20 10:19	Reinspection Photo		Load JPG	☒
38	14/01/20 10:19	Reinspection Photo		Load JPG	☒
39	14/01/20 10:19	Reinspection Photo		Load JPG	☒
40	14/01/20 10:19	Reinspection Photo		Load JPG	☒

Video			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				☒
41	14/01/20 10:19	Reinspection Photo	 Load JPG	☒
42	14/01/20 10:19	Reinspection Photo	 Load JPG	☒
43	14/01/20 10:19	Reinspection Photo	 Load JPG	☒
44	14/01/20 10:19	Reinspection Photo	 Load JPG	☒
45	14/01/20 10:19	Reinspection Photo	 Load JPG	☒
46	14/01/20 10:19	Reinspection Photo	 Load JPG	☒
47	14/01/20 10:19	Reinspection Photo	 Load JPG	☒
48	14/01/20 10:19	Reinspection Photo	 Load JPG	☒
49	14/01/20 10:19	Reinspection Photo	 Load JPG	☒
50	14/01/20 10:19	Reinspection Photo	 Load JPG	☒
51	14/01/20 10:19	Reinspection Photo	 Load JPG	☒
52	14/01/20 10:19	Reinspection Photo	 Load JPG	☒
53	14/01/20 10:19	Reinspection Photo	 Load JPG	☒
54	14/01/20 10:19	Reinspection Photo	 Load JPG	☒
55	14/01/20 10:19	Reinspection Photo	 Load JPG	☒
56	14/01/20 10:19	Reinspection Photo	 Load JPG	☒
57	14/01/20 10:19	Reinspection Photo	 Load JPG	☒
58	14/01/20 10:19	Reinspection Photo	 Load JPG	☒
59	14/01/20 10:19	Reinspection Photo	 Load JPG	☒
60	14/01/20 10:19	Reinspection Photo	 Load JPG	☒
61	14/01/20 10:19	Reinspection Photo	 Load JPG	☒
62	14/01/20 10:19	Reinspection Photo	 Load JPG	☒
63	14/01/20 10:19	Reinspection Photo	 Load JPG	☒
64	14/01/20 10:19	Reinspection Photo	 Load JPG	☒
65	14/01/20 10:19	Reinspection Photo	 Load JPG	☒
66	14/01/20 10:19	Reinspection Photo	 Load JPG	☒
67	14/01/20 10:19	Reinspection Photo	 Load JPG	☒
68	14/01/20 10:19	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/12/19 15:04	PRI	 Load PDF	
2	02/12/19 15:04	TP GIA	 Load PDF	
3	02/12/19 15:20	Agree on SJE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19021239/AGSF3Q2

Date: 16/01/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29114756

Claimant Vehicle No : SLS6905H

Insured Vehicle No : SLU441H

Date of Loss: 30/11/2019

Nature of Claim: TP Claim No: 613304

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLS6905H

Make & Model: SUBARU FORESTER, 2.0 I-L CVT AWD SR (A)

Engine No: FB20YB10463

Reg. Date: 29/09/2017 (Man. Year: 2017)

Chassis No: JF1SJ5KC5JG098560

Colour: White

Odometer: 54599 km

Engine Capacity: 1995 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/60 R17

Rear Tyre Size: 225/60 R17

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,470.60	3,377.92	9,092.68	72.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,160.00	1,870.00	2,290.00	55.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,630.60	5,247.92	11,382.68	68.44
Approved Total (Overridden) (S\$)		4,200.00		
Nett Amount (S\$)	16,630.60	4,200.00	12,430.60	74.75

INSPECTION

Date of Assignment: 02/12/2019

Date Inspected: 02/12/2019 Inspected At:

Sm Automotive - Kaki Bukit (HQ)
BLOCK C - 1, KAKI BUKIT AVE 6,
#01-43
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jan 2020)
Parts:	M1-SUV	SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS6905H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BOOT LID	Repair	1,292.30 F	*- FL
2	2	*REAR BOOT LID HINGE	Not Necessary	110.00 F	*- FL
3	2	*REAR BOOT LID SHOCK ABSORBER	Not Necessary	308.00 F	*- FL
4	1	*REAR BOOT LID EMBLEM LOGO	Necessary	65.00 F	*65.00 FL
5	1	*REAR BOOT LID SUBARU LOGO	Necessary	68.00 F	*68.00 FL
6	1	*REAR BOOT LID FORESTER LOGO	Necessary	68.00 F	*68.00 FL
7	1	*REAR BOOT LID AWD LOGO	Necessary	65.00 F	*65.00 FL
8	1	*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
9	1	*REAR BOOT LID INNER LOCK	Not Necessary	560.30 F	*- FL
10	1	*REAR BOOT LID INNER RUBBER	Not Necessary	160.30 F	*- FL
11	1	*REAR BOOT LID INNER TRIM BOARD	Not Necessary	220.30 F	*- FL
12	1	*REAR BOOT LID WINDSCREEN SEAL	Not Necessary	85.00 F	*- FL
13	2	*REAR BOOT LID WINDSCREEN SIDE SEAL	Not Necessary	150.00 F	*- FL
14	1	*REAR BOOT LID CAMERA	Not Necessary	680.00 FS	*- FS
15	1	*REAR TAIL LAMP	N/S Cracked	874.00 F	*437.00 FL
16	1	*REAR TAIL LAMP LOWER BRACKET	N/S Cracked	56.00 F	*28.00 FL
17	1	*REAR BUMPER	Deformed	980.30 F	*980.30 FL
18	10	*REAR BUMPER CLIP	Necessary	65.00 F	*30.00 FL
19	1	*REAR BUMPER SIDE RETAINER	N/S Cracked	56.00 F	*28.00 FL
20	1	*REAR BUMPER SIDE REFLECTOR	N/S Cracked	64.00 F	*32.00 FL
21	1	*REAR BUMPER CENTRE TOP SUBARU MOULDING	Bent	360.00 F	*360.00 FL
22	1	*REAR BUMPER TOWING COVER	Deformed	17.00 F	*17.00 FL
23	1	*REAR BUMPER REINFORCEMENT	Bent	320.80 F	*320.80 FL
24	2	*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	57.20 F	*- FL
25	1	*REAR BUMPER REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS
26	1	*REAR BUMPER L/H EXHAUST COVER	Not Necessary	86.00 F	*- FL
27	1	*REAR FENDER TRIM BOARD	N/S Cracked	572.60 F	*286.30 FL
28	1	*REAR FENDER TRIM BOARD CLIP (16 PCS)	Necessary	104.00 F	*30.00 FL
29	1	*REAR END PANEL	Dented	332.00 F	*332.00 FL
30	1	*REAR END PANEL TOP GARNISH	Deformed	90.00 F	*90.00 FL
31	1	*REAR SPARE TYRE PANEL	Repair	832.40 F	*- FL
32	1	*REAR SPARE TYRE PANEL TOP COVER	Cracked	336.00 F	*336.00 FL
33	1	*REAR SPARE TYRE PANEL & END PANEL SEALANT	Not Necessary	450.00 F	*- FL
34	1	*REAR EXHAUST	Not Necessary	668.00 F	*- FL
35	1	*REAR CENTRE EXHAUST	Not Necessary	1,248.00 F	*- FL
36	1	*REAR EXHAUST CHROME PIPE	Not Necessary	125.90 F	*- FL
37	1	*REAR EXHAUST ALUMINIUM COVER	Not Necessary	68.00 F	*- FL
38	2	*REAR EXHAUST MOUNTING	Not Necessary	46.20 F	*- FL
39	1	*TOOLS SPONGE TRAY	Cracked	261.00 F	*261.00 FL
40	1	*TOOLS SPONGE TRAY (SIDE)	Cracked	138.00 F	*138.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **12,470.60** **4,172.40**
 - List Item Discount on L Items 0.00/20.00% (\$\$) **0.00** **794.48**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	12,470.60 3,377.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT CUSHION & TRIM BOARD	New	280.00	80.00
2	TO REMOVE & REFIT REVERSE CAMERA	New	180.00	0.00
3	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
4	TO REMOVE & REFIT REAR & CENTRE EXHAUST	New	380.00	0.00
5	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	0.00
6	GUM	New	50.00	0.00
7	TO CHECK WIRING	New	100.00	30.00
8	TUFF KOTE	New	150.00	60.00
9	PANEL BEATING	New	1,400.00	850.00
10	SPRAY PAINTING	New	1,400.00	800.00
Gross Labour Cost (\$\$)			4,160.00	1,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >