

ESTIMATE TO REPAIR

VEHICLE NO. : SGN 5708 C
MAKE : TOYOTA
MODEL : VIOS 1.5E A
YEAR : 2006
CHASSIS NO : MR053HY4204210577

SURVEYOR NAME :
DATE OF SURVEY : 04/12/19
TIME OF SURVEY :

DATE : 30-Nov-19
DATE OF ACCIDENT : 29-Nov-19
THIRD PARTY REF : SKV 4091 P
THIRD PARTY REF : AIG ASIA PACIFIC INSURANCE PTE LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	rear bumper			\$	262.90
2 pcs	rear bumper retainer		\$ 35.60	\$	71.20
1 pc	rear bumper end panel			\$	751.02
1 pc	rear end panel garnish			\$	98.60
1 pc	rear boot VIOS emblem			\$	54.40
1 pc	rear boot emblem			\$	58.40
				\$	1,296.52
	Less 25%			\$	324.13
				\$	972.39
1 pc	rear bumper sensor	S.NETT		\$	200.00
1 pc	rear bumper company logo	S.NETT		\$	280.00
	To putty & spray paint.			\$	600.00
	To check rear wiring & water leakage			\$	30.00
	To anti- rust.			\$	30.00
	Labour charges.			\$	550.00
TG/VL	TOTAL			\$	2,662.39
Not Notified 11/12/19 Repair After Paint 4-5 days					
TG/VL	TOTAL			\$	-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Lim Tan Motor Pte Ltd
Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel: 65-64520893 Fax: 65-64589127 Email: admin@ltd.sg
Co. Reg No. 199307277D GST Reg No. M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without prior written consent of Lim Tan Motor Pte Ltd