

Kd

**ESTIMATE TO REPAIR**

VEHICLE NO. : SGN 5708 C
 MAKE : TOYOTA
 MODEL : VIOS 1.5E A
 YEAR : 2006
 CHASSIS NO : MR053HY4204210577

SURVEYOR NAME
 DATE OF SURVEY : 07/12/19
 TIME OF SURVEY

DATE : 30-Nov-19
 DATE OF ACCIDENT : 29-Nov-19
 THIRD PARTY REF : SKV 4091 P
 THIRD PARTY REF : AIG ASIA PACIFIC INSURANCE PTE LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	rear bumper			\$ CM	262.90
2 pcs	rear bumper retainer		\$ 35.60	\$	71.20
1 pc	rear bumper end panel			\$	751.02
1 pc	rear end panel garnish			\$	98.60
1 pc	rear boot VIOS emblem			\$	54.40
1 pc	rear boot emblem			\$	58.40
	Less 25%			\$	1,296.52
				\$	324.13
				\$	972.39
1 pc	rear bumper sensor	S.NETT		\$	200.00
1 pc	rear bumper company logo	S.NETT		\$	250.00
	To putty & spray paint			\$	600.00
	To check rear wiring & water leakage			\$	30.00
	To anti-rust			\$	30.00
	Labour charges			\$	550.00
TG/VL	TOTAL			\$	2,662.39
	<i>Not Authorized</i> <i>61 By 81700</i> <i>Recovery After Paint</i> <i>5 days</i> Parts 898.44 Supp 360.63 SN 120.00 Lab 1130.00 LS 2000.00 APPROVED 24/12/19				
TG/VL	TOTAL			\$	-

Lim Tan Motor Pte Ltd
 175 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 57521
 Tel: 65-64520603 Fax: 65-64556127 Email: sales@ltd.sg
 Co. Reg No. 196302770 GST Reg No. M2-0016086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without prior written consent of Lim Tan Motor Pte Ltd

