

Kd



**ESTIMATE TO REPAIR**

VEHICLE NO. : SGN 5708 C  
 MAKE : TOYOTA  
 MODEL : VIOS 1.5E A  
 YEAR : 2006  
 CHASSIS NO : MR053HY4204210577

|                |          |
|----------------|----------|
| SURVEYOR NAME  |          |
| DATE OF SURVEY | 09/11/19 |
| TIME OF SURVEY |          |

DATE : 30-Nov-19  
 DATE OF ACCIDENT : 29-Nov-19  
 THIRD PARTY REF : SKV 4091 P  
 THIRD PARTY REF : AIG ASIA PACIFIC INSURANCE PTE LTD

| Qty   | Parts Description/ Labour   | Type   | Unit Price | Nett Item Amt | Amount            |
|-------|---|--------|------------|---------------|-------------------|
| 1 pc  | rear bumper   |        |            |               | \$ CM 262.90 ✓    |
| 2 pcs | rear bumper retainer  |        | \$ 35.60   | 01/11/19      | \$ M 71.20 ✓      |
| 1 pc  | rear bumper end panel   |        |            |               | \$ M 751.02 ✓     |
| 1 pc  | rear end panel garnish  |        |            |               | \$ M 98.60 ✓      |
| 1 pc  | rear boot VIOS emblem   |        |            |               | \$ M 54.40 ✓      |
| 1 pc  | rear boot emblem  |        |            |               | \$ M 58.40 ✓      |
|       |   |        |            |               | \$ 1,296.52       |
|       | Less 25%  |        |            |               | \$ 324.13         |
|       |   |        |            |               | \$ 972.39         |
| 1 pc  | rear bumper sensor  | S.NETT |            |               | \$ M 200.00 X     |
| 1 pc  | rear bumper company logo  | S.NETT |            |               | \$ M 280.00 1205m |
|       | To putty & spray paint.   |        |            |               | \$ 600.00 560h    |
|       | To check rear wiring & water leakage                              |        |            |               | \$ 30.00 20       |
|       | To anti- rust.  |        |            |               | \$ 30.00 ✓        |
|       | Labour charges.   |        |            |               | \$ 550.00 520h    |
| TG/VL | TOTAL   |        |            |               | \$ 2,662.39       |
|       | Not Authorized<br>1 Day & 700h<br>Recovery After Paint<br>.5 days |        |            |               |                   |
| TG/VL | TOTAL   |        |            |               | \$ -              |

Lim Tan Motor Pte Ltd  
 Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721  
 Tel 65 64520893 Fax 65 64580127 Email [adm@ltd.ltm.sg](mailto:adm@ltd.ltm.sg)  
 Co. Reg No 109307277D GST Reg No M2-0019088-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without prior written consent of Lim Tan Motor Pte Ltd