

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508989
Fax: 8548 8156

Date : 05/12/19

Fax :

Vehicle Reg No. : SHC1802K

Date of Accident : 30-Nov-19

1. The repair job shall bill to: **AIG ASIA** --- **SMF5916P**

2. The finalized amount shall be:

(a)	Spare Parts after List discount	\$821.64
-----	---------------------------------	----------

(b)	Labour Charges	\$560.00
-----	----------------	----------

Total for Part-By-Part Repair Cost	\$1,381.64
---	-------------------

(c.) **Lumpsum Repair (if applicable)**

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost

3. Estimated normal period for repairs: **2** working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : _____

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature 

Name GUO QIANG

Date : 12/1/20

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	-----			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Ag Asia CP/P
LKK

Date: 02.12.2019

Time: 12:04:40

Page: 1

12 JS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305358329
 REGN NO : SHC1802K
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 03.07.2018
 DATE/TIME IN : 02.12.2019 09:45
 ACCIDENT DATE : 30.11.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	REAR BUMPER	459.40	20.00	367.52	✓
0002	04-01-0104-2533-G	REAR BUMPER CTR MOULDING	451.25	20.00	361.00	✓
0003	04-01-0104-0852-G	REAR BUMPER REFLECTOR RH	31.90	20.00	25.52	✓
0004	04-01-0104-2532-G	REAR BUMPER SIDE BRKT RH	138.10	20.00	110.48	✓
0005	04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60
0006	04-01-0104-1150-A	REAR BUMPER MAT	1	50.00	50.00	✓

SUB-TOTAL : 932.12

JOB NATURE

0000	PB	PANEL BEATING	350.00	320
0001	SP	SPRAYPAINT CHARGE	250.00	200
0002	L	R/I REVERSE SENSOR	120.00	40

SUB-TOTAL : 720.00

P/P
 Refue part photos.
 Gms Ap.
 03/12.
 2 days.

964.55
 2% : 771.64
 1381.64

560

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Anglia (P/P)

Date: 02.12.2019

Time: 12:04:40

Page: 2/2

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305358329
REGN NO : SHC1802K
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 03.07.2018
DATE/TIME IN : 02.12.2019 09:45
ACCIDENT DATE : 30.11.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,652.12

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

P/P
before part photos.
Emo Giall
2 Days. 03/12/19.

LKK Auto Consultants hence notify
the Repairer :
• To resurvey the repair work
• To inform the repairer during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: