

ASS. REC. BY:

REF: CS/FCI/9021263/Avf3 n2

Special Instruction:

SUNWAY: Adrian

## ASSIGNMENT (Office)

From (Person): Mirina chia Sam San

of FCI

Date/Time: 5.12.19 9.01 a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLB 50788

Insured: SHA 0484 L

at Workshop m/s NEW HOCK TEE

Tel: 67479241

of 1 Kaki Bukit Ave 6 Blk C #01-43

Policy No:

Claim No: D19007604 MPFH

Sum Insured:

Excess:

Make of Vch:

D.O.A. 29.11.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 3.12.2019 9.00 a.m

Person Contacted:

Sukys

H.O.D. Endorsement:

Vehicle: IN / OUT

| Date/Time | Action/Instruction ( ✓ ) Estimate               |
|-----------|-------------------------------------------------|
|           | SLB 50788 - X                                   |
|           | SHA 0484L - X                                   |
| 4/12/19   | Informed FCI pending est from repairer by email |
| 3/2/2020  | Adrian confirmed LS \$6000 (Red 17,046, 741)    |
| 3/2/2020  | Email preli revised to FCI                      |



**MOTOR SURVEY ASSIGNMENT**

|                           |                                                    |                                      |
|---------------------------|----------------------------------------------------|--------------------------------------|
| <b>Date</b>               | 02-12-2019                                         | <b>Our Ref No.</b> D19007604MFSH     |
| <b>Accident Date</b>      | 29-11-2019                                         | <b>Claim Type.</b> Third Party       |
| <b>Insured Vehicle</b>    | SHA0484L                                           | <b>Third Party Vehicle.</b> SLB5078B |
| <b>Survey Location</b>    | 1 KAKI BUKIT AVE 6 BLK C #01-43 AUTOBAY@KAKI BUKIT |                                      |
| <b>Contact Person.</b>    | SUKYI CHONG                                        |                                      |
| <b>Contact No.</b>        | 67479241/ 0                                        | <b>Fax No.</b> 67417276              |
| <b>Survey Type</b>        | WITHOUT PREJUDICE:                                 |                                      |
| <b>Appointed Surveyor</b> | LKK AUTO CONSULTANTS PTE LTD                       |                                      |
| <b>Contact Person</b>     | NA                                                 | <b>Fax No.</b> 68416315              |
| <b>Contact Number.</b>    | NA                                                 |                                      |

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

|                          |                                |                                |
|--------------------------|--------------------------------|--------------------------------|
| <b>Cc : Workshop</b>     | NEW HOCK TECK<br>MOTOR PTE LTD | <b>Attention.</b> NIL          |
| <b>Cc : TP Solicitor</b> | NA                             | <b>TP Solicitor Fax No.</b> NA |
| <b>Officer Incharge</b>  | MERINA CHIA SAN SAN            |                                |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Veron Chen (LKKAUTO)

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Monday, 3 February 2020 5:07 PM  
**To:** 'CWS Motor Claims'; SUR  
**Cc:** 'Merina Chia'  
**Subject:** RE: SURVEY ASSESSMENT - D19007604MFSH/1-SLB 5078B  
**Attachments:** SLB 5078B PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLB 5078B  
Date of survey: 3/12/2019  
Number of days (estimated) : 6 days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Wednesday, 4 December 2019 10:09 AM  
**To:** 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>  
**Cc:** 'Merina Chia' <MerinaChia@msfirstcapital.com.sg>  
**Subject:** RE: SURVEY ASSESSMENT - D19007604MFSH/1-SLB 5078B

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SLB 5078B on 3/12/2019.

We are pending estimate from repairer.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO) <admin-d@lkkauto.com>  
**Sent:** Tuesday, 3 December 2019 9:09 AM  
**To:** 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>  
**Cc:** 'Merina Chia' <MerinaChia@msfirstcapital.com.sg>  
**Subject:** RE: SURVEY ASSESSMENT - D19007604MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

**Summer Lee** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>

**Sent:** Tuesday, 3 December, 2019 9:01 AM

**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)

**Cc:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; Merina Chia <[MerinaChia@msfirstcapital.com.sg](mailto:MerinaChia@msfirstcapital.com.sg)>

**Subject:** PRI: SURVEY ASSESSMENT - D19007604MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

**Note: All the accident reports are uploaded into CWS for your perusal.**

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**

## Shirley Hiew (LKK Auto)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Tuesday, 28 January 2020 7:57 am  
**To:** 'CWS Motor Claims'; SUR  
**Cc:** 'Merina Chia'; assignments  
**Subject:** RE: REQUEST OF SURVEY REPORT-OUR REF:D19007604MFSH;ACCIDENT INVOLVING SHA0484L AND SLB5078B ON 29-11-2019

Dear Sir/Mdm,

Thank you for the email.

Dear Veron,

Kindly assist

**FYNA Our Ref : CS/FCI19021263/Avf3**

*- Wishing you a Happy and Prosperous Lunar New Year -*



Best Regards

**G.NIVITHA**

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

**Sent:** Friday, 24 January 2020 2:47 PM

**To:** ASSIGNMENTS@LKKAUTO.COM

**Cc:** CWS Motor Claims; Merina Chia

**Subject:** REQUEST OF SURVEY REPORT-OUR REF:D19007604MFSH;ACCIDENT INVOLVING SHA0484L AND SLB5078B ON 29-11-2019

Dear Sir,

We received LOD from workshop/solicitor.

Please let us have the **Survey Report including Vehicle Inspection Photos & Survey Fees Invoice** asap.

Kindly upload the survey report through CWS from document management screen by selecting option Survey report.

Thanks & Regards,  
Motor Claims Department  
MS First Capital Insurance Ltd  
[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)



**AVG**

This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Wednesday, 4 December 2019 10:09 AM  
**To:** 'CWS Motor Claims'; SUR  
**Cc:** 'Merina Chia'  
**Subject:** RE: SURVEY ASSESSMENT - D19007604MFSH/1-SLB 5078B

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SLB 5078B on 3/12/2019.

We are pending estimate from repairer.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :[sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Sent:** Tuesday, 3 December 2019 9:09 AM  
**To:** 'CWS Motor Claims' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Cc:** 'Merina Chia' <[MerinaChia@msfirstcapital.com.sg](mailto:MerinaChia@msfirstcapital.com.sg)>  
**Subject:** RE: SURVEY ASSESSMENT - D19007604MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

**Summer Lee** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>  
**Sent:** Tuesday, 3 December, 2019 9:01 AM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; Merina Chia <[MerinaChia@msfirstcapital.com.sg](mailto:MerinaChia@msfirstcapital.com.sg)>  
**Subject:** PRI: SURVEY ASSESSMENT - D19007604MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

**Note: All the accident reports are uploaded into CWS for your perusal.**

Best Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department  
MS First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**

> [Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Foreign Identification Number  
Owner ID: 906X

### Vehicle Details

Vehicle No.: SLB5078R  
Vehicle to be Exported: No  
Intended Deregistration Date: 30 Nov 2019  
Vehicle Make: TOYOTA  
Vehicle Model: ESQUIRE HYBRID 1.8 GI A  
Primary Colour: White  
Manufacturing Year: 2015  
Engine No.: 2ZR6531021  
Chassis No.: ZWR800141365  
Maximum Power Output: 100.0 kW (134 bhp)  
Open Market Value: \$29,454.00  
Original Registration Date: 12 Apr 2016  
First Registration Date: 12 Apr 2016  
Transfer Count: 0  
Actual ARF Paid: \$18,236.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 11 Apr 2026  
PARF Rebate Amount: \$13,677.00

### Intended COE Rebate Details

COE Expiry Date: 11 Apr 2026  
COE Category: E - Open Category  
COE Period(Years): 10  
QP Paid: \$45,009.00  
COE Rebate Amount: \$28,643.00  
**Total Rebate Amount: \$42,320.00**

The information contained herein is correct as at 30 Nov 2019

OK

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along UTE (City) before Braddell Rd exit. vehicle in front of me slowed down and stopped. I followed suit and stopped. suddenly, I felt an impact. vehicle B hit in the rear portion of my vehicle and caused damages. after the accident, one of my passenger felt discomfort.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com

Website: www.nhtmotor.com

Tel: 6747 9241

Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

30/11/2019

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

TP 1st Cap.

Veron

Accident date: 29/11/2019

Estimated repair cost for vehicle no: SLB5078R TOYOTA ESQUIRE HYBRID 1.8 A '16

CHASSIS: ZWR800141365

| S/n | Qty | Items                                              | U/price  | Amount                     |
|-----|-----|----------------------------------------------------|----------|----------------------------|
| 1   | 1   | Rear Boot Lid <i>Dented</i>                        |          | <del>\$2,012.00</del> 1712 |
| 2   | 2   | Rear Boot Lid Hinge <i>2 NHT</i>                   | \$138.00 | \$276.00 x                 |
| 3   | 2   | Rear Boot Lid Shock Absorber <i>2 NHT</i>          | \$333.00 | \$666.00 x                 |
| 4   | 1   | Rear Boot Lid Emblem Logo <i>NHT NHT</i>           |          | \$80.00 x                  |
| 5   | 1   | Rear Boot Lid Esquire Logo <i>NHT</i>              |          | \$75.00 ✓                  |
| 6   | 1   | Rear Boot Lid Hybrid Synergy Drive Logo <i>NHT</i> |          | \$78.00 ✓                  |
| 7   | 1   | Rear Boot Lid Center Moulding Assy <i>NHT NHT</i>  |          | \$839.00 +                 |
| 8   | 1   | Rear Boot Lid Number Plate <i>2 NHT</i>            |          | \$50.00 +                  |
| 9   | 1   | Rear Boot Lid Reverse Camera <i>1 NHT</i>          |          | \$850.00 +                 |
| 10  | 1   | Rear Boot Lid Inner Lock <i>Dented</i>             |          | \$452.00 ✓                 |
| 11  | 1   | Rear Boot Lid Inner Rubber <i>1 NHT</i>            |          | \$375.00 ✓                 |
| 12  | 1   | Rear Boot Lid Inner Trim Board <i>Cracked</i>      |          | \$570.00 ✓                 |
| 13  | 8   | Rear Boot Lid Inner Trim Board Clip <i>NHT</i>     | \$6.50   | \$52.00 30                 |
| 14  | 1   | Rear Boot Lid Windscreen Moulding <i>NHT</i>       |          | \$105.00 ✓                 |
| 15  | 2   | Rear Tail Lamp <i>2 NHT</i>                        | \$625.00 | \$1,250.00 +               |
| 16  | 4   | Rear Tail Lamp Clip <i>1 NHT</i>                   | \$8.00   | \$32.00 x                  |
| 17  | 2   | Rear Tail Lamp Lower Cover <i>Dented</i>           | \$206.00 | \$412.00 ✓                 |
| 18  | 1   | Rear Bumper <i>Dented</i>                          |          | \$645.00 ✓                 |
| 19  | 10  | Rear Bumper Clip <i>NHT</i>                        | \$6.50   | \$65.00 30                 |
| 20  | 2   | Rear Bumper Side Retainer <i>NHT</i>               | \$75.00  | \$150.00 ✓                 |
| 21  | 2   | Rear Bumper Side Reflector <i>NHT NHT</i>          | \$70.00  | \$140.00 x                 |
| 22  | 1   | Rear Bumper Towing Cover <i>Dented</i>             |          | \$25.00 ✓                  |
| 23  | 1   | Rear Bumper Reverse Sensor <i>Damaged</i>          |          | \$380.00 200(SW)           |
| 24  | 1   | Rear End Panel <i>Dented</i>                       |          | \$735.00 ✓                 |
| 25  | 1   | Rear End Panel Top Garnish <i>Dented</i>           |          | \$182.00 ✓                 |
| 26  | 2   | Rear Fender Inner Trim Board <i>Dented</i>         | \$582.00 | \$1,164.00 ✓               |
| 27  | 16  | Rear Fender Inner Trim Board Clip <i>NHT</i>       | \$6.50   | \$104.00 60                |
| 28  | 1   | Rear Floor Panel <i>Repair</i>                     |          | \$835.00 x                 |

|    |   |                             |     |            |   |
|----|---|-----------------------------|-----|------------|---|
| 29 | 1 | Rear Floor Panel Top Cover  | old | \$202.00   | ✓ |
| 30 | 1 | Rear Floor Panel Inner Trim | new | \$934.00   | x |
| 31 | 1 | Rear Floor Panel Sealant    |     | \$450.00   | x |
| 32 | 1 | Rear Exhaust                | NP  | \$1,010.00 | x |
| 33 | 2 | Rear Exhaust Mounting       | new | \$68.00    | + |
| 34 | 1 | Rear Center Exhaust         |     | \$3,555.00 | + |

7002  
\$251.5

SN: 200

Subtotal :- \$18,886.00

### Labour charges

|                                         |                          |
|-----------------------------------------|--------------------------|
| To remove & refit cushion & trim board  | <del>\$280.00</del> 80   |
| To remove & refit reverse camera        | <del>\$180.00</del> 50   |
| To remove & refit reverse sensor        | <del>\$100.00</del> 50   |
| To remove & refit rear windscreen       | \$120.00 ✓               |
| Gum new                                 | \$50.00 ✓                |
| To remove & refit rear & center exhaust | \$380.00 x               |
| To check wiring                         | <del>\$100.00</del> 30   |
| Tuff kote                               | <del>\$150.00</del> 60   |
| Panel beating                           | <del>\$1,400.00</del> 20 |
| Spray painting                          | <del>\$1,400.00</del> 20 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

2040  
Subtotal :- \$4,160.00

Total:- \$23,046.00

total 7491.50

L/S: 6k

06 Days.

6k.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                      |                                                                                                      |                 |                             |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------|-----------------|-----------------------------|-------------------------------------------------------------------------------------|
| MS FIRST CAPITAL INSURANCE LTD                                                                                                                                                         |                                                                                                      |                 | Ref : CS/FCI19021263/Avf3n2 |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                                                                  |                                                                                                      |                 | Date : 04-02-2020           |  |
|                                                                                                                                                                                        |                                                                                                      |                 | Code : FCI2                 |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                                                                      |                                                                                                      |                 |                             |                                                                                     |
| Insured Veh.                                                                                                                                                                           | SHA 484L                                                                                             | Veh. Inspected  | SLB 5078B                   |                                                                                     |
| Policy No.                                                                                                                                                                             |                                                                                                      | Coverage (\$)   | 0.00                        |                                                                                     |
| Claim No.                                                                                                                                                                              | D19007604MFSH                                                                                        | Excess (\$)     | 0.00                        |                                                                                     |
| Assign From                                                                                                                                                                            | MERINA CHIA SAN SAN                                                                                  | Assign Date     | 03/12/2019                  |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                          |                                                                                                      |                 |                             |                                                                                     |
| Make & Model                                                                                                                                                                           | TOYOTA ESQUIRE HYBRID                                                                                | c.c             | 1797                        |                                                                                     |
| Engine No.                                                                                                                                                                             | HIDDEN                                                                                               | Year of Reg.    | 2016                        |                                                                                     |
| Chassis No.                                                                                                                                                                            | ZWR800141365                                                                                         | Colour          | WHITE                       |                                                                                     |
| Odometer                                                                                                                                                                               | 62569                                                                                                | Steering        | IN ORDER                    |                                                                                     |
| Brakes                                                                                                                                                                                 | IN ORDER                                                                                             | Modification    | SPORTS RIM                  |                                                                                     |
| General                                                                                                                                                                                | GOOD                                                                                                 |                 |                             |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                                                                          |                                                                                                      |                 |                             |                                                                                     |
|                                                                                                                                                                                        | Size                                                                                                 | Make            | Balance                     |                                                                                     |
| R/H Front Tyre                                                                                                                                                                         | 195/65 R15                                                                                           | FALKEN          | 6 mm                        |                                                                                     |
| L/H Front Tyre                                                                                                                                                                         | 195/65 R15                                                                                           | FALKEN          | 6 mm                        |                                                                                     |
| R/H Rear Tyre                                                                                                                                                                          | 195/65 R15                                                                                           | FALKEN          | 6 mm                        |                                                                                     |
| L/H Rear Tyre                                                                                                                                                                          | 195/65 R15                                                                                           | FALKEN          | 6 mm                        |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                                                                       |                                                                                                      |                 |                             |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.                                                                                                                                     |                                                                                                      |                 |                             |                                                                                     |
| DAMAGES SEE DETAILS.                                                                                                                                                                   |                                                                                                      |                 |                             |                                                                                     |
| <b>5. General Information</b>                                                                                                                                                          |                                                                                                      |                 |                             |                                                                                     |
| Accident Date                                                                                                                                                                          | 29/11/2019                                                                                           | Inspection Date | 03/12/2019                  |                                                                                     |
| Survey held at                                                                                                                                                                         | NEW HOCK TECK MOTOR PTE LTD<br>1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT<br>SINGAPORE 417883 |                 |                             |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                                                                     |                                                                                                      |                 |                             |                                                                                     |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                      |                 |                             |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                                                                     |                                                                                                      |                 |                             |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                    |                                                                                                      | 6 Working Days  |                             |                                                                                     |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 5078B

| Qty                         | Description of Parts                        | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|---------------------------------------------|----------------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                                             |                      |                           |                   |
| 1                           | REAR BOOT LID                               | DENTED               | 2,012.00                  | 1,712.00          |
| 2                           | REAR BOOT LID HINGE @\$138.00               | NOT NECESSARY        | 276.00                    | -                 |
| 2                           | REAR BOOT LID SHOCK ABSORBER @\$333.00      | NOT NECESSARY        | 666.00                    | -                 |
| 1                           | REAR BOOT LID EMBLEM LOGO                   | NOT NECESSARY        | 80.00                     | -                 |
| 1                           | REAR BOOT LID ESQUIRE LOGO                  | NECESSARY            | 75.00                     | 75.00             |
| 1                           | REAR BOOT LID HYBRID SYNERGY DRIVE LOGO     | NECESSARY            | 78.00                     | 78.00             |
| 1                           | REAR BOOT LID CENTER MOULDING ASSY          | NOT NECESSARY        | 839.00                    | -                 |
| 1                           | REAR BOOT LID NUMBER PLATE                  | NOT NECESSARY        | 50.00                     | -                 |
| 1                           | REAR BOOT LID REVERSE CAMERA                | NOT NECESSARY        | 850.00                    | -                 |
| 1                           | REAR BOOT LID INNER LOCK                    | DAMAGED              | 452.00                    | 452.00            |
| 1                           | REAR BOOT LID INNER RUBBER                  | CUT                  | 375.00                    | 375.00            |
| 1                           | REAR BOOT LID INNER TRIM BOARD              | CRACKED              | 570.00                    | 570.00            |
| 8                           | REAR BOOT LID INNER TRIM BOARD CLIP @\$6.50 | NECESSARY            | 52.00                     | 30.00             |
| 1                           | REAR BOOT LID WINDSCREEN MOULDING           | NECESSARY            | 105.00                    | 105.00            |
| 2                           | REAR TAIL LAMP @\$625.00                    | NOT NECESSARY        | 1,250.00                  | -                 |
| 4                           | REAR TAIL LAMP CLIP @\$8.00                 | NOT NECESSARY        | 32.00                     | -                 |
| 2                           | REAR TAIL LAMP LOWER COVER @\$206.00        | DEFORMED             | 412.00                    | 412.00            |
| 1                           | REAR BUMPER                                 | DEFORMED             | 645.00                    | 645.00            |
| 10                          | REAR BUMPER CLIP @\$6.50                    | NECESSARY            | 65.00                     | 30.00             |
| 2                           | REAR BUMPER SIDE RETAINER @\$75.00          | NECESSARY            | 150.00                    | 150.00            |
| 2                           | REAR BUMPER SIDE REFLECTOR @\$70.00         | NOT NECESSARY        | 140.00                    | -                 |
| 1                           | REAR BUMPER TOWING COVER                    | DEFORMED             | 25.00                     | 25.00             |
| 1                           | REAR END PANEL                              | DENTED               | 735.00                    | 735.00            |
| 1                           | REAR END PANEL TOP GARNISH                  | DEFORMED             | 182.00                    | 182.00            |
| 2                           | REAR FENDER INNER TRIM BOARD @\$582.00      | DEFORMED             | 1,164.00                  | 1,164.00          |
| 16                          | REAR FENDER INNER TRIM BOARD CLIP @\$6.50   | NECESSARY            | 104.00                    | 60.00             |
| 1                           | REAR FLOOR PANEL                            | TO REPAIR SEE LABOUR | 835.00                    | -                 |
| 1                           | REAR FLOOR PANEL TOP COVER                  | DEFORMED             | 202.00                    | 202.00            |
| 1                           | REAR FLOOR PANEL INNER TRIM                 | NOT NECESSARY        | 934.00                    | -                 |
| 1                           | REAR FLOOR PANEL SEALANT                    | NOT NECESSARY        | 450.00                    | -                 |

Report Ref No. CS/FCI19021263/Avf3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts                                                        | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-----------------------------------------------------------------------------|---------------|---------------------------|-------------------|
| 1   | REAR EXHAUST                                                                | NOT NECESSARY | 1,010.00                  | -                 |
| 2   | REAR EXHAUST MOUNTING @\$68.00                                              | NOT NECESSARY | 136.00                    | -                 |
| 1   | REAR CENTER EXHAUST                                                         | NOT NECESSARY | 3,555.00                  | -                 |
|     | LESS 25% DISCOUNT                                                           |               | -                         | -1,750.50         |
|     |                                                                             |               | 18,506.00                 | 5,251.50          |
|     | <b>SPECIAL NETT ITEMS</b>                                                   |               |                           |                   |
| 1   | REAR BUMPER REVERSE SENSOR (SN)                                             | DAMAGED       | 380.00                    | 200.00            |
| 1   | GUM (SN)                                                                    | NECESSARY     | 50.00                     | 50.00             |
|     |                                                                             |               | 430.00                    | 250.00            |
|     | <b>LABOUR</b>                                                               |               |                           |                   |
|     | TO REMOVE & REFIT CUSHION & TRIM BOARD.                                     |               | 280.00                    | 80.00             |
|     | TO REMOVE & REFIT REVERSE CAMERA.                                           |               | 180.00                    | 50.00             |
|     | TO REMOVE & REFIT REVERSE SENSOR.                                           |               | 100.00                    | 50.00             |
|     | TO REMOVE & REFIT REAR WINDSCREEN.                                          |               | 120.00                    | 120.00            |
|     | TO REMOVE & REFIT REAR & CENTER EXHAUST.                                    | NOT NECESSARY | 380.00                    | -                 |
|     | TO CHECK WIRING.                                                            |               | 100.00                    | 30.00             |
|     | TUFF KOTE.                                                                  |               | 150.00                    | 60.00             |
|     | PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL.                  |               | 1,400.00                  | 800.00            |
|     | SPRAY PAINTING.                                                             |               | 1,400.00                  | 800.00            |
|     |                                                                             |               | 4,110.00                  | 1,990.00          |
|     | <b>GRAND TOTAL</b>                                                          |               | <b>23,046.00</b>          | <b>7,491.50</b>   |
|     | <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |               |                           | <b>6,000.00</b>   |

Report Ref No. CS/FCI19021263/Avf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.