

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No. 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SLU3064T

Not Authorised
Lump & ?
Resurvey After Paint
8-8 days

No.	Qty	List Items			
1	1	Front bumper	\$	635.60	✓
2	1	Front bumper LH fog lamp cover	\$	19.40	X
3	1	Front bumper LH fog lamp	\$	354.50	✓
4	1	Front bumper LH side retainer	\$	24.80	✓
5	1 set	Front bumpere clips	\$	30.00	✓
6	1	Front bumper inner reinforcement	\$	218.80	?
7	1	Front grille	\$	208.10	?
8	1	LH Headlamp	\$	603.00	✓
9	1	Front bonnet	\$	638.90	X
10	1	Front LH fender	\$	480.00	✓
11	1	Front LH fender under shield	\$	82.70	✓
12	1 set	Front fender under shield clips	\$	30.00	✓
13	1	Front LH wheel huouse panel	\$	662.40	?
14	1	Front LH shock absorber	\$	388.20	?
15	1	Front LH lower arm	\$	367.40	?
16	1	Front LH knuckle arm	\$	347.40	?
17	1	Front LH wheel hub & bearing	\$	392.30	?
18	1	Front LH drive shaft	\$	996.90	X
			\$	6,480.40	
			Less 20%	\$	1,296.08
			Total :	\$	5,184.32

		Special Nett Items			
19	1	Front LH tyre	\$	220.00	?
20	1	Front LH sports rims	\$	500.00	350.00
			Total :	\$	720.00

		Labour			
1		Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$	1,000.00	?
2		To putty and spray Spray Paintings charges.	\$	800.00	700.00
3		To remove, refit engine assy, to facilitate repair.	\$	350.00	?
4		To remove, refit front LH under carriage damage parts.	\$	250.00	180.00
5		To conduct computerise wheel alignment test.	\$	80.00	80.00
6		To check wirings and lightings.	\$	40.00	20.00
7		To supply and apply anti rust treatment	\$	60.00	?
			Total :	\$	2,580.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Total Parts and Labour : \$ 8,484.32