

INS. CASE OWNER:

CC 4/1AIG19021302, KKK 90

LKK:
IDAC:

Surveyor:

Kamath

DOI:

ASSIGNMENT

7/11/19

Date / Time:

21/12/19

Registered in Merimen:

7/11/19

Pre-assign / CCU / FTE:



Insured Vehicle No.:

SGL 3103X

Claim No.:

Name of Insured:

FANNY XU FENG

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :\$S

D.O.A.:

26/11/19

Place of Accident:

Is driver the owner?

☒ YES / ☐ NO

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT:

YES / NO

TP GIA REPORT:

YES / NO

Insured Liability:

%

Final? Yes / No

SLS 4109C

INSRS:
WSP:
Tel:
Liability:
RMKS:Kam
HlerINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	AMEE 09.12.19
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐
	After call ltr to OI:	☒
	Authorisation To Act:	☒
	Release Voucher:	☒
	Final Repair Bill:	☒
	Car Rental Invoice:	☒
	Towing Invoice:	☐
	LTA / GIA:	☐
	Medical Bill:	☐
	PIR:	☐
	Mandate/Reject Instruction:	☒
	LOD:	☒
	Payment Breakdown Form:	☐
	Post-Repair Photos:	☐
	Others:	☐
PRELIMINARY ADVICE Date/Time: Sent By:		
FINALIZATION Date/Time: Confirm with: Confirm by: KKK		
Repair Cost:	SS 6,650.00 (4 days) Reduction: 31 %	Email ☒ Call ☐
FINAL SETTLEMENT Date/Time: 09-03-20 Confirm with: FANNY		
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No.: 34	Email ☒ Call ☐
Repair Cost:	SS 6,650.00	DI REVERSED PAYING LOT H1 T.
Loss of Rental (LOR):	SS 500.00 (5 days) x 100	
Loss of Use (LOU):	SS - (\$ x days)	
Loss of Income (LOI):	SS - (\$ x days)	
LOR only ☒ LOU only ☐	LOR + LOU ☐ LOR + LO ☐ [Tick only one]	
GIA/LTA Search	SS -	
Medical:	SS -	
Disbursement:	SS - (e.g. Tow/ Independent)	
Legal Cost	SS -	
Total:	SS 180.00	Global Sum SS:
FINAL PAYMENT Date/Time: 09-03-20 Confirm with: FANNY		
Payee 1:	SS 180.00	Name 1: VAN HIE MOTORS
Payee 2: (Strike if N.A.)	SS	Name 2:
Payee 3: (Strike if N.A.)	SS	Name 3:

COPY SENT
12/3/2020

ke

Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial PK 2 Singapore 569541
Tel : 64817221

Fax : 64816131

AIG Asia Pacific Insurance Singapore Pte Ltd
78 Shenton Way #07-16
AIG Building
Singapore 079120

Vehicle No : SLS 4109 C
Make/Model : Toyota C-HR
Year : 2017

Not Authored

Running B4 park

4 days

11 Sep 8 6650h

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate cost of repair

1 pc	Rear o/s door assy	
1 pc	Rear o/s door protector	
1 pc	Rear o/s door frame black sticker	
1 pc	Rear o/s door inner trim board	?
1 pc	Rear o/s door glass regulator	photo
1 pc	Rear o/s door glass regulator motor	photo
1 pc	Rear o/s door inner lock	X
1 pc	Rear o/s door rubber	photo
1 pc	Front o/s door protector	
1 pc	Front o/s door frame black sticker	X
1 pc	Rear o/s fender arch garnish	
1 pc	Rear lower bumper	
1 pc	O/S locker panel garnish	
1 pc	Rear o/s shock absorber	
1 pc	Rear o/s lower arm	
1 pc	Rear o/s kunckle arm	
1 pc	Rear o/s kunckle bearing	
1 pc	Rear o/s trailing arm	
1 pc	Rear o/s hub assy	

Ry	\$1,218.50	✓
Mr1	\$376.10	✓
Re	\$134.50	✓
mg	\$455.70	✓
Di1	\$185.10	✓
Tr	\$485.70	✓
R	\$305.10	X
Gr	\$185.90	✓
CM	\$397.10	✓
nn	\$134.50	X
Del1	\$255.10	✓
Ca	\$685.70	✓
Du	\$655.70	✓
R1	\$497.80	7 ✓
D11	\$497.80	7 ✓
R1	\$847.60	7 ✓
Re	\$205.10	7 ✓
D11	\$255.60	7 ✓
R1	\$455.60	7 ✓
	\$8,234.20	7,794.5
Less 25 %	\$2,058.55	1,948.65
	\$6,175.65	5,845.9

S Nett

1 pc	Rear n/s tyre rim
20 pcs	Clip

nd	\$450.00	✓
\$2.50	\$50.00	✓
	\$500.00	370.00

balance c/f \$6,675.65

SLS 4109 C

balance b/f \$6,675.65

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$800.00

58d
~~600~~

To putty and spray paint

\$800.00

60d

Check & reconnect wiring.

\$45.00

201

To respray anti-rust proofing treatment

\$120.00

301

Remove/refit rear tail-gate mechanism to new door.

\$150.00

601

Remove/renew rear o/s undercarriages.

\$450.00

200d

Check and realign wheel alignment.

\$60.00

✓

Total

\$9,100.65

1620.00

H: Kenneth

Paint - 5,845.95

S.Welt - 500.00

Labour - 1,620.00

7,965.95

6/5000 15% ~~6,720.00~~

Measurement printout

Car standard measurement

Beissbarth © * SL

M * R+ * * OK * / 1.00 / / C

Date: 12.12.2019 17:24:12



Version (program)
v5.0b3224/v5.0b3224

Version (FWA)
v5.0b1801

Version (target data)
—

Serial number
QZ0000178

Last service
18.03.2019

Customer

Vehicle

Order

Vehicle: *SLS 4109 C*

Rear Axle		Initial Measurement	Target Data	Final Measurement
Camber	left	-2°01'		-1°46'
	right	-0°50'		-1°14'
Individual Toe	left	+0°15'		+0°16'
	right	-0°50'		+0°16'
Total Toe		-0°35'		+0°31'
Setback		+0°08'		-0°13'
Geometrical driving axis		-0°32'		
Front Axle		Initial Measurement	Target Data	Final Measurement
Castor 20°	left	+5°53'		+6°34'
	right	+6°21'		+6°20'
K.P.I. 20°	left	+9°15'		
	right	+10°29'		
Toe out on turns	left	-1°20'		
	right	-1°09'		
Camber	left	+0°01'		+0°10'
	right	+0°07'		-0°01'
Individual Toe	left	-0°01'		+0°05'
	right	+0°04'		+0°05'
Total Toe		+0°03'		+0°10'
Setback		+0°27'		+0°04'
Included Angle 20°	left	+9°11'		
	right	+10°38'		

Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial PK 2 Singapore 569541
Tel : 64817221

Fax : 64816131

AIG Asia Pacific Insurance Singapore Pte Ltd
78 Shenton Way #07-16
AIG Building
Singapore 079120

Vehicle No : SLS 4109 C
Make/Model : Toyota C-HR
Year : 2017

Not Authorised
Runway BP party
4 days

Qty	Description	Unit Price	Amount
<u>Estimate cost of repair</u>			
1 pc	Rear o/s door assy	<i>Ry</i> \$1,218.50	✓
1 pc	Rear o/s door protector	<i>M/I</i> \$376.10	✓
1 pc	Rear o/s door frame black sticker	<i>Re</i> \$134.50	✓
1 pc	Rear o/s door inner trim board	<i>Ln</i> \$455.70	X
1 pc	Rear o/s door glass regulator		\$185.10 ?
1 pc	Rear o/s door glass regulator motor		\$485.70 ?
1 pc	Rear o/s door inner lock	<i>R</i> \$305.10	X
1 pc	Rear o/s door rubber		\$185.90 ?
1 pc	Front o/s door protector	<i>CM</i> \$397.10	✓
1 pc	Front o/s door frame black sticker	<i>Nn</i> \$134.50	X
1 pc	Rear o/s fender arch garnish	<i>Not W</i> \$255.10	✓
1 pc	Rear lower bumper	<i>Cu</i> \$685.70	✓
1 pc	O/S locker panel garnish	<i>Du</i> \$655.70	✓
1 pc	Rear o/s shock absorber		\$497.80 ?
1 pc	Rear o/s lower arm		\$497.80 ?
1 pc	Rear o/s kunckle arm		\$847.60 ?
1 pc	Rear o/s kunckle bearing		\$205.10 ?
1 pc	Rear o/s trailing arm		\$255.60 ?
1 pc	Rear o/s hub assy		\$455.60 ?
			\$8,234.20
Less 25 %			\$2,058.55
			\$6,175.65

S Nett

1 pc Rear n/s tyre rim
20 pcs Clip

nd \$450.00 ✓
\$2.50 *Re* \$50.00 ✓
\$500.00

balance c/f \$6,675.65

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during repairs
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- An Inval (notification) is allowed
- Supplying items (s) which are not listed in the list of parts approved by the Insurer

Authorised by Repairer

SLS 4109 C

balance b/f \$6,675.65

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$800.00 4001

To putty and spray paint

\$800.00 4001

Check & reconnect wiring.

\$45.00 201

To respray anti-rust proofing treatment

\$120.00 301

Remove/refit rear tail-gate mechanism to new door.

\$150.00 601

Remove/renew rear o/s undercarriages.

\$450.00 ?

Check and realign wheel alignment.

\$60.00 ✓

Total

\$9,100.65

Your password will expire in 10 days. [Click here to change it.](#)

PRE-REPAIR INSPECTION REQUEST – SLS4109C vs SGL3103X (OI) on D.O.A.: 28/11/2019

From: Hor, Yinnul

To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)

Cc: Fong, Andy-SY, Chan, Jennifer-WM, Abu Kassim, Noor Marissa, Azlan, Syazairina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeelaur, Parthiban, Theerthan, Subramaniam, Divya

Sent: 12/2/2019 4:27:31 PM

Attachments:  CCF 000030.pdf

Hi,

Please refer to the enclosed request from **Lian Her Motors**.

Claim no : 7758793724SG003

Case Owner : Bernard Ler Ji Qian

If you have any queries/concerns, please let us know.

Kindly assist to assign **Kenneth Kong** as *Single Joint Expert* as requested.

Thanks & Regards,

Hor Yin Rul (Viviane)

AIG

FNOL Adjuster I

Singapore FNOL | Claims Operations – Auto

Tel: 8001206556 | Ext: 1002208

Yinnul.Hor@aig.com | www.aig.sg

5:03pm 2/12/19
P: Anthony
v: Nt In
Arrange on 3/12/19

From: cheonganthony@yahoo.com.sg [mailto:cheonganthony@yahoo.com.sg]

Sent: Monday, December 02, 2019 4:06 PM

To: Hor, Yinnul

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGL3103X AND SLS4109C ON 28/11/2019

Without Prejudice

Your Reference : SLS4109C

Our Reference : 7758793724SG003

Dear Sir/Mdm,

We refer to your email dated 2 Dec 2019.

We are agreeable to the usage of Kenneth Kong from LKK Auto Consultants Pte Ltd as the Single Joint Expert to conduct the Pre-Repair Survey.

Kindly proceed to engage LKK Auto Consultants Pte Ltd to perform the said Pre-Repair Survey in accordance to the NIMA Protocol.

Thank you.

Regards

Anthony Cheong

Claims

From: Hor, Yinrul
Sent: Mon, 2 Dec 2019 07:39:08 +0000
To: cheonganthony@yahoo.com.sg
Cc: Fong, Andy-SY, Chan, Jennifer-WM, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divyashni
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGL3103X AND SLS4109C ON 28/11/2019

Without Prejudice

Your Reference : SLS4109C
Our Reference : 7758793724SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gury)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Tel: 8001206556 | Ext: 1002208
Yinrul.Hor@aig.com | www.aig.as

From: Anthony Cheong [mailto:cheonganthony@yahoo.com.sg]
Sent: Monday, 2 December, 2019 10:44 AM
To: AIG SGP, Claims-Survey
Subject: [EXTERNAL] Accident involving SLS4109C & SGL3103X on 28.11.2019

This message is from an external sender; be cautious with links and attachments.

WITHOUT PREJUDICE

Your ref : SGL3103X
Our ref : 4109/2019

Dear Sir/Mdm

We refer to the above matter.

Our client's vehicle **SLS4109C** was involved in the above accident with your insured's vehicle no **SGL3103X** on **28 Nov 2019**.

Kindly let us have your surveyor list for our attention.

Also, please let us know within 2 working days whether you would like to conduct the pre repair survey of our client's vehicle.

The survey can be conducted at the following address

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541

If we do not hear from you within the next 2 working days excluding Saturday, Sunday or holiday, We will commence repairs thereafter without further reference to you.

Enclosed herewith the GLA report of **SLS4109C** for your kind perusal.

In the meantime, if you have any queries, please do not hesitate to contact me at **91082728** and I'll be most happy to assist you.

Your kind attention to the above is much appreciated.

Best Regards
Anthony Cheong
Claims
Lian Her Motors

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To : AIG Asia Pacific Insurance Pte. Ltd.
Attn : Ler, Bernard-JQYour Ref : 7758793724SG
Our Ref : CC4/AIG19021302/KEB3
Date : 19 Dec 2019**"WITHOUT PREJUDICE"****ACCIDENT INVOLVING SGL3103X & SLS4109C ON 28/11/2019**

Refer to the above accident.

The accident occurred when insured reversed into the parking lot hit third party vehicle. We have clarified with the OI on the nature of the accident and he/she is aware that his/her NCD would be affected.

On behalf of AIG Asia Pacific Insurance Pte. Ltd., we have **successfully / not successfully** carried out **TP Express Settlement** between your insured (vehicle no. SGL3103X) and third party claimant (vehicle no. SLS4109C).

Summary of offer made to workshop Lian Her Motors is as follows :

	Claimed	Revised
Cost of Repairs	\$ 9,100.65	\$ 6,650.00
Loss of Rental (5days x \$110)	\$ 550.00	\$ 550.00 (5days x \$110)

Amount of claim at **Liability 100%** \$ 7,200.00

Our surveyor recommended 4days repair.

Enclose herewith the relevant supporting documents for your perusal.

For your approval please.

Regards,
Asher Sng Rong Yi
LKK Auto Consultants Pte Ltd

Print Received Message

This mail is associated with :

***SLS4109C (7758793724SG)
[SGL3103X]**

TP
L H CAR RENTAL PTE LTD
Nov 28 2019 4:00PM
[FANNY XU FENG]
Lian Her Motors

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 06/03/2020 11:44 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$7150.00) - SLS4109C - Claim Handler: Ler, Bernard-JQ

Approved:7150.00:Cost of Repair : \$6,650.00 As per surveyor finalization Loss of Rental : \$500.00 5 days @ S\$ 100/day LTA/ GIA Search Fee : \$- Total : \$7,150.00

...CLAIM SUBFOLDER...(Pending for Survey Report)
Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Nov 2019 Edit Reg		02 Dec 2019 00:00 Edit Adj Rpt	\$56,650.00 Edit Estimates	\$56,650.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	FANNY XU FENG, ID: S6973091D, Tel: +6598177243		
Main Claimant:	L H CAR RENTAL PTE LTD, Co. Reg. No.: 200009761N		
Vehicle Reg. No.:	SLS4109C	Date of Loss:	28/11/2019 16:00 - :59 [26 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 77587937245G	Policy/Cover Note No.:	1700083766 (Comprehensive)
Vehicle Reg. No. (Insured):	SGL3103X	Policy No. (Claimant):	5109111878-000029
		Excess:	
Repairer:	Lian Her Motors (HQ) Block 5038 Ang Mo Kio Avenue 3, #01-405 Ang Mo Kio Industrial Park 2, 569541 Ang Mo Kio - Tel: 82990599		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 12/12/2019]		
Driver/Custodian (Insured):	FANNY XU FENG (), NRIC: S6973091D, Tel: +6598177243 Email:		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG_SG_EXPRESS (06/03/2020): Alert - Adj Mandate Approved (\$57150.00) - SLS4109C - Claim Handler: Ler, Bernar...
- AIG_SG_EXPRESS (13/02/2020): Alert - Adj Mandate Maintained - SLS4109C - Claim Handler: Ler, Bernard-JQ
- AIG_SG_EXPRESS (16/01/2020): Alert - Adj Mandate Maintained - SLS4109C - Claim Handler: Ler, Bernard-JQ

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLS4109C (7758793724SG)
[SGL3103X]
TP
L H CAR RENTAL PTE LTD
Nov 28 2019 4:00PM
[FANNY XU FENG]
Lian Her Motors

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Letters/Correspondences

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1 Edit	

Assessment Reports

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/12/19 14:52	Adjuster Immediate Advice	1 Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/12/19 14:06	General View	1 Load JPG	
2	19/12/19 14:06	General View	1 Load JPG	
3	19/12/19 14:06	General View	1 Load JPG	
4	19/12/19 14:06	General View	1 Load JPG	
5	19/12/19 14:06	General View	1 Load JPG	
6	19/12/19 14:06	General View	1 Load JPG	
7	19/12/19 14:06	General View	1 Load JPG	
8	19/12/19 14:06	General View	1 Load JPG	
9	19/12/19 14:06	General View	1 Load JPG	
10	19/12/19 14:06	General View	1 Load JPG	
11	19/12/19 14:06	General View	1 Load JPG	
12	19/12/19 14:06	General View	1 Load JPG	
13	19/12/19 14:06	General View	1 Load JPG	
14	19/12/19 14:06	General View	1 Load JPG	
15	19/12/19 14:06	General View	1 Load JPG	
16	19/12/19 14:06	General View	1 Load JPG	
17	19/12/19 14:06	Odometer Reading	1 Load JPG	
18	19/12/19 14:06	General View	1 Load JPG	
19	19/12/19 14:06	General View	1 Load JPG	
20	19/12/19 14:06	Chassis Number	1 Load JPG	
21	19/12/19 14:07	Reinspection Photo	1 Load JPG	
22	19/12/19 14:07	Reinspection Photo	1 Load JPG	
23	19/12/19 14:07	Reinspection Photo	1 Load JPG	
24	19/12/19 14:07	Reinspection Photo	1 Load JPG	
25	19/12/19 14:07	Reinspection Photo	1 Load JPG	
26	19/12/19 14:07	Reinspection Photo	1 Load JPG	
27	19/12/19 14:07	Reinspection Photo	1 Load JPG	
28	19/12/19 14:07	Reinspection Photo	1 Load JPG	
29	19/12/19 14:07	Reinspection Photo	1 Load JPG	
30	19/12/19 14:07	Reinspection Photo	1 Load JPG	
31	19/12/19 14:07	Reinspection Photo	1 Load JPG	
32	19/12/19 14:07	Reinspection Photo	1 Load JPG	

Documentation

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/12/19 14:35	EMAIL FROM AIG DD 12022019	1 Load PDF	
2	03/12/19 14:35	TP GIA REPORT	1 Load PDF	

Letters/Correspondences				1 per page	☒
No	Finalized On			Thumbnail	Print
3	07/12/19 14:48	LKK Auto Consultants Pte Ltd (HQ)	LETTER TO OI	 Load PDF	
4	19/12/19 14:40	TP ESITMATE - MARKED		 Load PDF	
5	20/01/20 10:37	ALIGNMENT REPORT		 Load PDF	
6	16/03/20 08:33	WORKSHOP INVOICE		 Load PDF	
7	16/03/20 08:33	AUTHORISATION TO ACT FORM		 Load PDF	
8	16/03/20 08:33	Release Voucher		 Load PDF	
9	16/03/20 08:33	RENTAL RECEIPT		 Load PDF	
10	16/03/20 08:33	LOD		 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	05/12/19 10:47	OI GIA REPORT		 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^v

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)

Vehicle No:	SGL3103X (Insd veh)	Model:	TOYOTA C-HR 1.2 (A)
	SLS4109C (TP veh)		
Date of Accident:	28/11/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	9,100.65
Final Repair Cost	:	\$	6,650.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	500.00 5 days
LTA / GIA Search Fee	:	\$	0.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	7,150.00
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____100_____(%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____(%)		Assessed Liability (*): _____(%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Lian Her Motors	:	\$ 7,150.00
2)		:	\$

JOANNE LEE KHANG MIN

16 Mar 2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19021302/KES3Q2

Date: 16/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700083766
 Claimant: SLS4109C Insured Vehicle No: SGL3103X
 Vehicle No: SLS4109C
 Date of Loss: 28/11/2019 Nature of Claim: TP Claim No: 7758793724SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLS4109C
 Make & Model: TOYOTA C-HR, 1.2 (A) Engine No: 2ZR8162029
 Reg. Date: 22/09/2017 (Man. Year: 2017) Chassis No: ZYX102061816
 Colour: Metallic Red Odometer: 255102 km
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17
 Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm
 Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,675.65	6,345.95	329.70	4.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,425.00	1,510.00	915.00	37.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,100.65	7,855.95	1,244.70	13.68
Approved Total (Overridden) (S\$)		6,650.00		
Nett Amount (S\$)	9,100.65	6,650.00	2,450.65	26.93
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
Nett Liability (S\$)		7,150.00		

INSPECTION

Date of Assignment: 02/12/2019
 Date Inspected: 03/12/2019 Inspected At: Lian Her Motors (HQ)
 Block 5038 Ang Mo Kio Avenue 3,
 #01-405 Ang Mo Kio Industrial Park 2
 Singapore 569541
 Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR O/S DOOR ASSY	Bent	1,218.50 FL	*1,218.50 FL
2	1		*REAR O/S DOOR PROTECTOR	Missing	376.10 FL	*376.10 FL
3	1		*REAR O/S DOOR FRAME CLACK STICKER	Necessary	134.50 FL	*134.50 FL
4	1		*REAR O/S DOOR INNER TRIM BOARD	Mtg Cracked	455.70 FL	*455.70 FL
5	1		*REAR O/S DOOR GLASS REGULATOR	Distorted	185.10 FL	*185.10 FL
6	1		*REAR O/S DOOR GLASS REGULATOR MOTOR	Jammed	485.70 FL	*485.70 FL
7	1		*REAR O/S DOOR INNER LOCK	Repair	305.10 FL	*- FL
8	1		*REAR O/S DOOR RUBBER	Cut	185.90 FL	*185.90 FL
9	1		*FRONT S/O DOOR PROTECTOR	Cracked	397.10 FL	*397.10 FL
10	1		*FRONT S/O DOOR FRAME BLACK STICKER	Not Necessary	134.50 FL	*- FL
11	1		*REAR S/O FENDER ARCH GARNISH	Dented / Cut	255.10 FL	*255.10 FL
12	1		*REAR LOWER BUMPER	Cut	685.70 FL	*685.70 FL
13	1		*O/S LOCKER PANEL GARNISH	Dented	655.70 FL	*655.70 FL
14	1		*REAR S/O SHOCK ABSORBER	Bent	497.80 FL	*497.80 FL
15	1		*REAR S/O LOWER ARM	Distorted	497.80 FL	*497.80 FL
16	1		*REAR S/O KNUCKLE ARM	Bent	847.60 FL	*847.60 FL
17	1		*REAR S/O KNUCKLE BEARING	Necessary	205.10 FL	*205.10 FL
18	1		*REAR S/O TRAILING ARM	Distorted	255.60 FL	*255.60 FL
19	1		*REAR S/O HUB ASSY	Bent	455.60 FL	*455.60 FL
20	1		*REAR N/S TYRE RIM	Dented	450.00 FS	*450.00 FS
21	20		*CLIP	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,734.20	8,294.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,058.55	1,948.65
Total Parts (\$\$)	6,675.65	6,345.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE / RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING & CUTTING	New	800.00	540.00
2	TO PUFFY AND SPRAY PAINT	New	800.00	600.00
3	CHECK & RECONNECT WIRING	New	45.00	20.00
4	TO RESPRAY ANTI-RUST PROOFING TREATMENT	New	120.00	30.00
5	REMOVE / REFIT REAR TAIL-GATE MECHANISM TO NEW DOOR	New	150.00	60.00
6	REMOVE / RENEW REAR O/S UNDERCARRIAGES	New	450.00	200.00
7	CHECK AND REALIGN WHEEL ALIGNMENT	New	60.00	60.00
Gross Labour Cost (S\$)			2,425.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >