

ke

Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial PK 2 Singapore 569541
Tel : 64817221

Fax : 64816131

AIG Asia Pacific Insurance Singapore Pte Ltd
78 Shenton Way #07-16
AIG Building
Singapore 079120

Vehicle No : SLS 4109 C
Make/Model : Toyota C-HR
Year : 2017

NOT AUTHORIZED

Running BY party

4 days

11 Sep @ 6650h

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate cost of repair

1 pc	Rear o/s door assy
1 pc	Rear o/s door protector
1 pc	Rear o/s door frame black sticker
1 pc	Rear o/s door inner trim board
1 pc	Rear o/s door glass regulator
1 pc	Rear o/s door glass regulator motor
1 pc	Rear o/s door inner lock
1 pc	Rear o/s door rubber
1 pc	Front o/s door protector
1 pc	Front o/s door frame black sticker
1 pc	Rear o/s fender arch garnish
1 pc	Rear lower bumper
1 pc	O/S locker panel garnish
1 pc	Rear o/s shock absorber
1 pc	Rear o/s lower arm
1 pc	Rear o/s kunckle arm
1 pc	Rear o/s kunckle bearing
1 pc	Rear o/s trailing arm
1 pc	Rear o/s hub assy

photo
photo
photo

photo

photo

Ry	\$1,218.50	—
Mr	\$376.10	—
Mr	\$134.50	—
Mr	\$455.70	✓
Dis	\$185.10	✓
Tr	\$485.70	✓
R	\$305.10	X
Mr	\$185.90	✓
CR	\$397.10	✓
NA	\$134.50	X
Net	\$255.10	✓
Cr	\$685.70	✓
Dr	\$655.70	✓
Ry	\$497.80	✓
Dr	\$497.80	✓
Ry	\$847.60	✓
Mr	\$205.10	✓
Dis	\$255.60	✓
Ry	\$455.60	✓

	\$8,234.20	7,794.65
Less 25 %	\$2,058.55	1,948.65
	\$6,175.65	5,845.90

S Nett

1 pc	Rear n/s tyre rim
20 pcs	Clip

Dr	\$450.00	✓
\$2.50	\$50.00	✓
	\$500.00	300.00

balance c/f \$6,675.65

SLS 4109 C

balance b/f \$6,675.65

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$800.00

58d

To putty and spray paint

\$800.00

60d

Check & reconnect wiring.

\$45.00

201

To respray anti-rust proofing treatment

\$120.00

301

Remove/refit rear tail-gate mechanism to new door.

\$150.00

601

Remove/renew rear o/s undercarriages.

\$450.00

200d

Check and realign wheel alignment.

\$60.00

✓

Total

\$9,100.65

1620.00

Hi Kenneth

Paint - 5,845.95
S.Watt - 500.00
Labour - 1,620.00
7,965.95

1/50m 15% 6,740.00


Measurement printout

Car standard measurement

Beissbarth © * SL

M * R+ ** OK * / 1.00 // C

Date: 12.12.2019 17:24:12



Version (program)
v5.0b3224/v5.0b3224

Version (FWA)
v5.0b1801

Version (target data)

Serial number
QZ0000178

Last service
16.03.2019

Customer

Vehicle

Order

Vehicle: SLS 4109 C

Rear Axle		Initial Measurement	Target Data	Final Measurement
Camber	left	-2°01'		-1°46'
	right	-0°50'		-1°14'
Individual Toe	left	+0°15'		+0°16'
	right	-0°50'		+0°16'
Total Toe		-0°35'		+0°31'
Setback		+0°08'		-0°13'
Geometrical driving axis		-0°32'		
Front Axle		Initial Measurement	Target Data	Final Measurement
Castor 20°	left	+5°53'		+6°34'
	right	+6°21'		+6°20'
K.P.I. 20°	left	+9°15'		
	right	+10°29'		
Toe out on turns	left	-1°20'		
	right	-1°09'		
Camber	left	+0°01'		+0°10'
	right	+0°07'		-0°01'
Individual Toe	left	-0°01'		+0°05'
	right	+0°04'		+0°05'
Total Toe		+0°03'		+0°10'
Setback		+0°27'		+0°04'
Included Angle 20°	left	+9°11'		
	right	+10°38'		